

Map ID
Direction
Distance (ft)
Elevation
Site

MAP FINDINGS

Database(s)
EOR ID Number
EPA ID Number

Z & S AUTO SALES (Continued)

Pollution Char: Not reported
Remed Action: Not reported
Release Date: 4/7/1999
Close Date: 10/18/1998
Cleanup Fund ID: Not reported
Discovery Date: 1/1/1995
Enforcement DI: Not reported
Enf Type: Not reported
Enter Date: 12/18/1998
Funding: 0
Staff Initials: UST
How Discovered: Tank Closure
Interim: Not reported
Leak Cause: Corrosion
Leak Source: Tank
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE, includes Unknown and Not Analyzed.
Priority: 3A3
Local Case #: Not reported
Beneficial: WNL
Staff: Not reported
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hyd Basin #: 8.50
Operator: Not reported
Oversight Pgm: R8 Lead Underground Storage Tank
Review Date: 6/30/1997
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: UNKNOWN
RP Address: 450 CAMINO EL ESTERO
Global ID: T0805300168
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mils Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Luit: 0
Waste Discharge Global ID: Not reported
Waste Ditch Assigned Name: Not reported

LIST Region 3:
Case Number: 2778
Case Street: PARK
Release Date: 10/18/1998
Local Agency: UNKNOWN
Discovery: 01/01/1995
How Found: Tank Closure
Source: Tank
Cause: Corrosion
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported

Remed Plan: Not reported
Monitoring: Not reported

Database(s)
EOR ID Number
EPA ID Number

Map ID
Direction
Distance (ft)
Elevation
Site

MAP FINDINGS

Database(s)
EOR ID Number
EPA ID Number

Z & S AUTO SALES (Continued)

Facility Status: Case Closed
Facility County: Monterey
Review Date: 6/30/97
Confirm Leak: //
Prism Assets: //
Remedial Plan: //
Monitoring: Not reported
Enf Type: Not reported
Enter Date: //
Interim Action: 0
Mils Concentration: 0
Mils Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Data: //
MTBE Tested: NT
Law/Long: 36.600077 / -121.880724
Groundwater Qualifier: Not reported
Summary: CONTAMINATION DISCOVERED DURING TANK PULL SITE CHARACTERIZATION
PENDING

CORTESE:
Reg ID: 2778
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Funding: 0
Workplan: //
Pollution Char: 06030/1997
Remedial Action: //
Close Date: 04/07/1998
Pilot Program: UST
Region: 3

71
NNW
112-1
3703 ft.
Higher

REESE PUMP STATION NEAR WAVE
STREET
MONTEREY, CA 92184

Notify 65 U090051814
N/A

NOTIFY 65:
Data Reported: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Incident Description: 82194

Staff Initials: Not reported

72
SE
112-1
3788 ft.
Higher

MONTEREY PENINSULA COLLEGE
880 FREEMONT ST
MONTEREY, CA 93940

HAZNET 515934878
Cortese N/A

Map ID
Direction
Distance (ft)
Elevation

MAP FINDINGS

Database(s)
EPA ID Number
S105034876

MONTEREY PENINSULA COLLEGE (Continued)

HAZNET:
Geopaid: CAL000012794
Tepaid: CAD982042475
Gen County: Monterey
Tad County: Solano
Tons: 03900
Category: Asbestos-containing waste
Disposal Method: Disposal, Land Fill
Contact: MONTEREY PENINSULA COLLEGE
Telephone: (408) 646-4040
Mailing Address: 880 FREMONT ST
MONTEREY, CA 93940 - 4704
County: Monterey
Geopaid: CAL000012794
Tepaid: WMD982300250
Gen County: Monterey
Tad County: 99
Tons: 07000
Category: Laboratory waste chemical
Disposal Method: Not reported
Contact: MONTEREY PENINSULA COLLEGE
Telephone: (408) 646-4040
Mailing Address: 880 FREMONT ST
MONTEREY, CA 93940 - 4704
County: Monterey
Geopaid: CAL000012794
Tepaid: CAD980794133
Gen County: Monterey
Tad County: San Joaquin
Tons: 00000
Category: Asbestos-containing waste
Disposal Method: Not reported
Contact: MONTEREY PENINSULA COLLEGE
Telephone: (408) 646-4040
Mailing Address: 880 FREMONT ST
MONTEREY, CA 93940 - 4704
County: Monterey
Geopaid: CAL000012794
Tepaid: CAT000046117
Gen County: Monterey
Tad County: Kings
Tons: 4000
Category: Contaminated soil from site clean-ups
Disposal Method: Disposal, Land Fill
Contact: MONTEREY PENINSULA COLLEGE
Telephone: (408) 646-4040
Mailing Address: 880 FREMONT ST
MONTEREY, CA 93940 - 4704
County: Monterey

Map ID
Direction
Distance (ft)
Elevation

MAP FINDINGS

Database(s)
EPA ID Number
S105034876

MONTEREY PENINSULA COLLEGE (Continued)

Geopaid: CAL000012794
Tepaid: CAT000022148
Gen County: Monterey
Tad County: San Bernardino
Tons: 00026
Category: Off-specification, aged, or surplus organics
Disposal Method: Disposal, Other
Contact: MONTEREY PENINSULA COLLEGE
Telephone: (408) 646-4040
Mailing Address: 880 FREMONT ST
MONTEREY, CA 93940 - 4704
County: Monterey
The CA HAZNET database contains 38 additional records for this site.
Please contact your EDR Account Executive for more information.
CORTESE:
Reg id: 508
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

73
ESE
1/2-1
4233 ft.
Higher

SLOAT / 4TH STREETS
MONTEREY, CA 93940

CHMIRS S100278423
N/A

CHMIRS:
OES Control Number: 9120208 DOT ID: 1693
DOT Hazard Class: Poisonous and atoxic (medicinal) material
Chemical Name: METHYLENE CHLORIDE
CAS Number: 75082
Environmental Contamination: Ground 01-NOV-91
Time Spent: 1945
Physical State Stored: Liquid
Physical State Released: Liquid
Release Unit: Gallons
Container Description: 19
Container Type: 19
Container Material: Undetermined
Level Of Containment: Ground level
Container Capacity: Not reported
Estimate Of Release (code): Not reported
Agency ID Number: 9
OES Incident Number: 27704
Time Notified: 91-08
Estimated Temperature: 7120209
Surrounding Area: 1730
Property Management: 60
More Than Two Substances Involved?: C
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported

(Continued)

Special Studies 4 :		Not reported
Special Studies 5 :		Not reported
Special Studies 6 :		Not reported
Responding Agency Personnel # Of Injuries :	0	Not reported
Responding Agency Personnel # Of Fatalities :	0	Not reported
Resp Agency Personnel # Of Decontaminated :	5	Not Reported
Others Number Of Decontaminated :	1	
Others Number Of Injuries :	0	
Others Number Of Fatalities :	0	
Vehicle Make/Year :		Not reported
Vehicle License Number :		Not reported
Vehicle State :		Not reported
Vehicle Id Number :		Not reported
CADOT/PU/CIC Number :		Not reported
Company Name :		Not reported
Reporting Officer Name/ID :	BRUCE WEIDON	Not reported
Report Date :	12-AUG-92	
Comments :	Yes	
Facility Telephone Number :	408 765-4511	
Waterway Involved :	Not reported	
Waterway :		Not reported
Spill Site :		Not reported
Cleanup By :		Not reported
Contaminant :		Not reported
What Happened :	Not reported	
Date/Time :		Not reported
Evacuators :		Not reported
Type :	Not reported	
Other :	Not reported	
Chemical 1 :		Not Reported
Chemical 2 :		Not Reported
Chemical 3 :		Not Reported

74 CORNER STORE
NINW 398 LIGHTHOUSE AVE
1/2-1 MONTEREY, CA 93931
4389 ft.
Higher

LUST S10328594
Cortese N/A

State LUST:	Not reported	
Cross Street:	Qly Leased:	
Case Number:	2820	
Reg Board:	Central Coast Region	
Chemical:	Gasoline	
Lead Agency:	Regional Board	
Local Agency:	27000	
Case Type:	Other ground water affected	
Status:	Remedial action (cleanup) Underway	
County:	Monterey	
Abate Method:	Unknown - action taken at site is unknown	
Review Date:	1/1/1975	Confirm Leak:
Workplan:	Not reported	Prelim Assess:
Pollution Chart:	Not reported	Remed Plan:
Remed Action:	Not reported	Monitoring:
Closes Date:	Not reported	
Release Date:	7/3/1987	

CORNER STORE (Continued)

Cleaning Fund ID:	Not reported	Release Date:	Not reported
Discover Date:	1/1/1985	Enter Date:	1/1/1985
Enforcement ID:	Not reported	Enter Date:	1/29/1988
Ent Type:	LET	Funding:	0
Staff Initials:	Not reported	How Discovered:	Subsurface Monitoring
How Stopped:	Not reported	Interim:	No
Leak Cause:	UNK	Leak Source:	UNK
MTBE Date:	5/14/2001	MTBE Date:	5/14/2001
Max MTBE GW:	410 Parts per Billion	MTBE Tield:	MTBE Detected. Site tested for MTBE & MTBE detected
Priority:	Not reported	Local Case #:	Not reported
Beneficial:	MUN	Staff:	WML
GVV Qualifier:	=	GVV Qualifier:	=
Max MTBE Soil:	Not reported	Soil Qualifier:	Not reported
Hydr Basin Rf:	9.50	Operator:	Not reported
Overnight Pgm:	RB Lead Underground Storage Tank	Overnight Pgm:	UST
Review Date:	9/8/2002	Stop Date:	Not reported
Work Suspended:	Not reported	Responsible Party:	WILLIAM EVERETT
RP Address:	450 CAMINO EL ESTERO	Global ID:	70805300219
Org Name:	Not reported	Contact Person:	Not reported
MTBE Conc:	Not reported	Miba Fuel:	1
Water System Name:	Not reported	Well Name:	Not reported
Distance To Leak:	0	Waste Discharge Global ID:	Not reported
Waste Ditch Assigned Name:	Not reported	UST Region 3:	2820
Case Number:	2820	Cross Street:	Not reported
Responsible Party:	WILLIAM EVERETT	Local Agency:	03
Discovered:	01/01/1985	How Found:	Subsurface Monitoring
Source:	Other	Cause:	UNK
Lead Agency:	Regional Board	Case Type:	Other ground water affected
Contact:	Not reported	Family Status:	Remedial action (Cleanup) Underway
Review Date:	9/8/02	Family County:	Monterey
Confirm Leak:	01/01/1975	Funding:	Workplan:

LUST Region 3:

Case Number:	2820	Release Date	07/03/1997
Cross Street:	Not reported	Enter Date:	1/29/98
Responsible Agency:	PANYWILLIAM EVERETT		
Local Agency:	03	Regional Board:	Central Coast Region
Discovered:	01/01/1986	Stop Date:	Not reported
How Found:	Surface/ra Monitoring	How Stopped:	Not reported
Source:	Other		
Cause:	UNK		
Lead Agency:	Regional Board		
Case Type:	Other ground water affected		
Contact:	Not reported	Staff Initials:	WNL
Facility Status:	Remedial action (cleanup)		
Facility County:	Morley		
Reviser:	9802	Funding:	0
Review Date:	01/01/1975	Workplan:	/ /
Confirm Leak:			

Map ID
Direction
Distance (ft)
Elevation

Site

MAP FINDINGS

Database(s)
EPA ID Number

CORNER STORE (Continued)

5103285944

Prelim Assess: //
Remedial Plan: //
Monitoring: Not reported
Enforce Type: LET
Enforce Date: //
Interim Action: 0
Mile Concentration:
Mile Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: 410
Max MTBE Soil: Not reported
MTBE Date: 12/04/2002
MTBE Tested: YES
Leakage: 36.614428 / -121.8898413
Soil Qualifier: Not reported
Groundwater Qualifier: =
Summary: OWNER HAS HAD WATER IN ONE TANK SINCE 1987. OWNER HAS REFUSED TO PROVIDE TANK TESTS UPON INSPECTOR'S REQUEST AS A REQUIREMENT TO UPGRADE HIS TANKS. SOIL BORINGS WERE TAKEN IN APRIL AND SHOWED BENZENE (160 PPB), MTBE (8200 PPB) & XYLENE (28 PPB) IN WATER
CORTESE:
Reg ID: 2920
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

75
NNW
11/21
4436 ft
Higher

MONTEREY PLAZA HOTEL
400 CANNERY ROW
MONTEREY, CA 93940

HAZNET 8103975295
CHMIRS N/A

HAZNET:
Gapaid: CAC001503144
Tepaid: WAD981281767
Gen County: Monterey
Tad County: 99
Tons: 5838
Category: Off-specification, aged, or surplus organics
Disposal Method: Treatment, Incineration
Contact: MONTEREY PLAZA HOTEL
Telephone: (408) 464-1700
Mailing Address: 400 CANNERY ROW
MONTEREY, CA 93940
County: Monterey
Gapaid: CAC001503144
Tepaid: WAD981281767
Gen County: Monterey
Tad County: 99
Tons: 0041
Category: Off-specification, aged, or surplus organics
Disposal Method: Disposal, Land Fill
Contact: MONTEREY PLAZA HOTEL
Telephone: (408) 464-1700
Mailing Address: 400 CANNERY ROW
MONTEREY, CA 93940
County: Monterey

Map ID
Direction
Distance (ft)
Elevation

Site

MAP FINDINGS

Database(s)
EPA ID Number

MONTEREY PLAZA HOTEL (Continued)

5103975295

Gapaid: CAC001431784
Tepaid: WAD981281767
Gen County: Monterey
Tad County: 99
Tons: 125
Category: Off-specification, aged, or surplus organics
Disposal Method: Treatment, Incineration
Contact: MONTEREY PLAZA HOTEL
Telephone: (831) 546-1700
Mailing Address: 400 CANNERY ROW
MONTEREY, CA 93940
County: Monterey
CHMIRS:
DES Control Number: 01-5410
DOT Hazard Class: Not Reported
Chemical Name: Oil
Extent of Release: Not reported
CAS Number: Not reported
Environmental Contamination: None Reported
Incident Date: Not reported
Time Completed: Not reported
Physical State Stored: Not reported
Physical State Released: Not reported
Release Unit: Not reported
Container Description: Not reported
Container Type: Not reported
Container Material: Not reported
Level Of Container: Not reported
Container Capacity: Not reported
Extent Of Release (code): Not reported
Agency ID Number: Not reported
Agency Incident Number: Not reported
Time Notified: 01-5410
Surrounding Area: Not reported
Estimated Temperature: Not reported
Property Management: Not reported
More Than Two Substances Involved?: Not reported
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
Responding Agency Personnel # Of Injuries: 0
Responding Agency Personnel # Of Fatalities: 0
Resp Agency Personnel # Of Decontaminated: Not reported
Others Number Of Decontaminated: Not reported
Others Number Of Injuries: Not reported
Others Number Of Fatalities: Not reported
Vehicle Make/Year: Not reported
Vehicle License Number: Not reported
Vehicle State: Not reported
CA/DOT/PLU/CIC Number: Not reported

Map ID	Direction	Distance	Distance (ft.)	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
								

Mag ID	Direction	Distance	Distance (ft.)	Elevation	Site	EOR ID Number	Database(s)	EPA ID Number
MAP FINDINGS								

MINIEMER PLAZA HOTEL (continued)		
Company Name :		Not reported
Reporting Officer (Name/Id) :		Not reported
Report Date :		Not reported
Comments :		Not reported
Facility Telephone Number :		Not reported
Waterway involved :		No
Waterway :	Not reported	
Spill Site :	Road	
Cleanup By :		
Containment :	Unknown	
What Disappeared :	No	
Date/Time :	On a vacant lot there are three 55 gal drums. One is leaking and has a small puddle in front of it on the ground.	
Evaporations :	9/23/01 1730	
Type :	PETROLEUM	
Other :	Not reported	
Chemical 1 :	Not Reported	
Chemical 2 :	Not Reported	
Chemical 3 :	Not Reported	

(continued)	
Level Of Containment :	10
Container Capacity :	1
Container Capacity Units (code) :	Calsons
Event Of Release (code) :	7
Agency Of Release :	27704
Agency Incident Number :	88-0056
OES Incident Number :	8903704
Time Notified :	1300
Surrounding Area :	946
Estimated Temperature :	42
Property Management :	5
More Than Two Substances Involved? :	Not reported
Special Studies 1 :	Not reported
Special Studies 2 :	Not reported
Special Studies 3 :	Not reported
Special Studies 4 :	Not reported
Special Studies 5 :	Not reported
Special Studies 6 :	Not reported
Responding Agency Personnel # Of Injuries :	1

NOTE: 85:	
Date Reported:	Not reported
Report File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Incident Description:	82184

Offairs Number of Fatalities :	0
Vehicle Make/year :	98 TOYOTA
Vehicle License Number :	3W65072
Vehicle State :	CA
Vehicle RI Number :	Not reported
CANDOT/PCINOC Number :	Not reported
Company Name :	ANGELO DEMARCO III
Reporting Office Name/ID :	JON JENNINGS
Report Date :	08-NOV-89
Comments :	Not reported
Facility Telephone Number :	408-755-6511

CHMIRS:		CHMIRS	
DOT Hazard Class:	8805794	DOT ID:	1789
Chemical Name:	ACID, HYDROCHLORIC		
Exant of Release:	Not reported		
CAS Number:	7647010	Quantity Released:	Not reported
Environmental Contamination:	Ground	Property Use:	Freeway
Incident Date:	07-NOV-99	Date Completed:	07-NOV-99
Time Completed:	2100		
Physical State Stored:	Liquid		
Physical State Released:	Liquid		
Release Unit:	Gallons		
Container Description:	2		
Container Type:	Plastic, Flexible		
Container Material:			

Confinement :	Not reported
What Happened :	Not reported
Date/Time :	Not reported
Exposures :	Not reported
Type :	Not reported
Other :	Not reported
Chemical 1 :	Not Reported
Chemical 2 :	Not Reported
Chemical 3 :	Not Reported

DANA PROPERTY 301 LIGHTHOUSE AVE MONTEREY, CA	LUST S102428625 Cortese N/A
---	--------------------------------------

Map ID
Direction
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)

EPA ID Number
5102428525

DANA PROPERTY (continued)

Case Number: 512
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency: 27000
Case Type: Soil only
Status: Case Closed
County: Monterey
Abuse Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: 3/23/1992
Close Date: 5/13/1992
Release Date: 2/1/1988
Cleanup Fund ID: Not reported
Discover Date: 1/1/1985
Enforcement DI: Not reported
Enf Type: Not reported
Enter Date: 2/8/1988
Funding: Not reported
Staff Initials: UST
How Discovered: Tank Closure
How Stopped: Not reported
Interim: UNK
Leak Cause: Tank
Leak Source: Not reported
MTBE Data: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE, includes Unknown and Not Analyzed.
Priority: Medium priority
Local Case #: Not reported
Beneficial: Not reported
Staff: JWG
GW Qualifier: Not reported
Max MTBE Sol: Not reported
Sol Qualifier: Not reported
Hydr Basin #: 9.50
Operator: Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Oversight Prgm: UST
Review Date: 5/13/1992
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
Ref Address: Not reported
Global ID: T0805300317
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Media Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance to LUST: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Map ID
Direction
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)

EPA ID Number
5102428525

DANA PROPERTY (continued)

LUST Region 3:
Case Number: 512
Cross Street: Not reported
Responsible Party: Not reported
Local Agency: 03
Discover Date: 01/01/1985
How Found: Tank Closure
Source: Tank
Cause: UNK
Lead Agency: Local Agency
Case Type: Soil only
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey
Review Date: 5/13/92
Confirm Leak: Not reported
Prelim Assess: Not reported
Remedial Plan: Not reported
Monitoring: 3/23/92
Enforce Type: Not reported
Enforce Date: Not reported
Interim Action: Not reported
Mile Concentration: Not reported
Mile Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Sol: Not reported
MTBE Tested: NT
LUST/Long: 36.6123278 / -121.9009303
Sol Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: NO BENEFICIAL USES OF GROUNDWATER. CASE DELEGATED TO LOCAL AGENCIES
05/13/92
CORTESE:
Reg ID: 512
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

79
NW
1/2-1
4922 ft.
Higher

MIR TOM O'NEAL
456 PINE
MONTEREY, CA 93940

HAZNET 5104408523
LUST N/A
Cortese

State LUST:
Cross Street: MCQUELLAN
Qty Leaked: Not reported
Case Number: 3280
Reg Board: Central Coast Region
Chemical: Standard Solvent
Lead Agency: Local Agency
Local Agency: 27000
Case Type: Other ground water affected
Status: Leak being confirmed
County: Monterey
Abuse Method: Unknown - action taken at site is unknown

Map ID
Direction
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number
EPA ID Number

MAP FINDINGS

MR TOM O'NEAL (Continued)

Review Date: 2/22/2000
Workplan: Not reported
Pollution Chart: Not reported
Remedial Action: Not reported
Close Date: Not reported
Release Date: 2/22/2000
Cleanup Fund ID: Not reported
Discovery Date: 1/1/1985
Enforcement Date: Not reported
Entire Date: 3/26/2000
Funding: Not reported
Staff Initials: COR
How Discovered: Subsurface Monitoring
How Stopped: Not reported
Interim: Not reported
Leak Cause: UNK
Leak Source: UNK
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not Required to be Tested
Priority: Not reported
Local Case #: Not reported
Beneficial: Not reported
Staff: RBA
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Overnight Pym: R8 Land Underground Storage Tank
Overnight Pym: UST
Review Date: Not reported
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party/MOLLE O'NEAL
RP Address: PO BOX 1520
Global ID: T080530267
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mils Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Limit: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Confirm Leak: 2/22/2000
Prelim Assess: Not reported
Remed Plan: Not reported
Monitoring: Not reported

8104405623

Map ID
Direction
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number
EPA ID Number

MAP FINDINGS

MR TOM O'NEAL (Continued)

Case Type: Other ground water affected
Contact: Not reported
Facility Status: Leak being confirmed
Facility County: Monterey
Review Date: Not reported
Confirm Leak: 02/02/2000
Prelim Assess: //
Remedial Plan: //
Monitoring: Not reported
Enforce Date: Not reported
Enforce Action: Not reported
Interim Action: Not reported
Mils Concentration: Not reported
Mils Fuel: 0
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
MTBE Tested: //
Lat/Long: 36.6033348 / -121.90032014
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: SUBSURFACE MONITORING INDICATE A LEAK HAS OCCURRED. FOUR UST'S REMOVED ON 2/20/00 W/ OBVIOUS SOIL STAINING & ODOR. SAMPLES OF UST PIT PENDING.

HAZNET:
Gapaid: CAC002225153
Tepaid: CAD009466382
Gan County: Monterey
Ted County: 7
Tone: 8000
Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Contact: MR TOM O'NEAL
Telephone: (831) 358-5040
Mailing Address: PO BOX 1520
CARAMEL VALLEY, CA 93924
County: Monterey

CORTESE:
Reg ID: 3280
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

8104405623

80
BE
112-1
5278 ft.
Higher

FORMER CHERON #9-3487
1200 MARK THOMAS DR
MONTEREY, CA

LUST 5102430171
Cortese N/A

State LUST:
Cross Street: Not reported
Qty Leaked: Not reported
Case Number: 751
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

FORMER CHEVRON #8-3887 (Continued)

8102430171

Case Type: Other ground water affected
Status: Case Closed
County: Monterey
Abate Method: U
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Plan: Not reported
Release Date: 4/8/1983
Cleanup Fund ID: Not reported
Discover Date: 1/1/1985
Enforcement ID: Not reported
EPA Type: Not reported
Enter Date: 2/2/1980
Funding: Not reported
Staff Initials: UST
How Discovered: CM
How Stopped: Not reported
Interim: No
Leak Cause: UNK
Leak Source: UNK
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not reported
Priority: 0
Local Case #: Not reported
Beneficial: JWG
Staff: Not reported
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 8.50
Operator: Not reported
Oversight Pgm: RB Lead Underground Storage Tank
Review Date: 4/8/1983
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
PP Address: Not reported
Global ID: T080530374
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Miba Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
LUST Region 3:
Case Number: 751
Case Status: Not reported
Release Date: 06/12/1989
Regional Board: Central Coast Region
Local Agency: Not reported
Stop Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

FORMER CHEVRON #8-3887 (Continued)

8102430171

How Found: Not reported
Source: Other
Cause: UNK
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey
Review Date: 4/8/83
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Type: Not reported
Enforce Date: / /
Interim Action: 0
Miba Concentration: / /
Miba Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Data: / /
MTBE Tested: NT
Lat/Long: 36.5821853 / -121.873511
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: Not reported
COORTESE:
Reg ID: 751
Region: COORTESE
Reg By: Leaking Underground Storage Tanks

How Stopped: Not reported
Staff Initials: JWG
Funding: Not reported
Workplan: / /
Pollution Char: / /
Remedial Action: / /
Close Date: 04/09/1983
Pilot Program: UST
Region: 3

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
MONTEREY	S103674957	DENTAL X-RAY OF MONTEREY	880 CASS STREET SUITE 206	93940	HAZNET
MONTEREY	S105689250	MONTEREY COLLECTION SYSTEM	CITY HALL	93940	CA WDS
MONTEREY	S105025031	MONTEREY PENINSULA UNIF S	540 CNYN DEL REY	93940	Cortese
MONTEREY	S103654375	UNIVERSITY OF CALIFORNIA SANTA CRU	34500 COAST RTE 1	93940	HAZNET
MONTEREY	S103654376	UC SANTA CRUZ/MARINE POLLUTION LAB	34500 COAST RTE. 1	93940	HAZNET
MONTEREY	S104569625	US ARMY CORP ENGINEERS/GRANITE CNY	34500 COAST HWY 1	93940	HAZNET
MONTEREY	U001593636	ALLEN FUNT RANCH	COAST RT 1	93940	HIST UST
MONTEREY	U001593654	EL SUR RANCH	COAST ROUTE, HIGHWAY #1 (25 MI	93940	HIST UST
MONTEREY	U001593693	RANCHO CALERA	COAST RT	93940	HIST UST
MONTEREY	S102613813	RUSSO'S MARINE FUELING STATION	NW CORNER OF DEL MONTE AVE /	93940	HAZNET
MONTEREY	S103962909	ENVIRONMENTAL RESOURCES MANAGEMENT	N/E CORNER OF DEL MONTE / FI	93940	HAZNET
MONTEREY	S103678458	PG & E	CORNER ALVARADO / FRANKLIN		HAZNET
MONTEREY	S103619347	DPR CUSTOM HOUSE	#20 CUSTOM HOUSE PLAZA	93940	HAZNET
MONTEREY	S103966005	WILLIAM THAYER CONSTRUCTION	#20 CUSTOM HOUSE PLAZA	93940	HAZNET
MONTEREY	1003678893	PG&E GAS PLANT MONTEREY	DEL MONTE FRANKLIN ADAMS FIGER	93940	CERC-NFRAP
MONTEREY	S103678581	RITZ CAMERA CENTERS #346	DEL MONTE SHOPPING CTR	93940	HAZNET
MONTEREY	S103643405	DEL MONTE SHOPPING CENTER	1410 DEL MONTE SHOPPING CENTER	93940	CA SLIC
MONTEREY	S103643244	SUDDEN SERVICE DRY CLEANERS	951 DEL MONTE BLVD		CA SLIC
MONTEREY	S101539726	BORG-WARNER EQUITIES CORP.	DEL MONTE DUNE SITE		CA SLIC
MONTEREY	S103678583	MONTEREY MARINA	DELMONTE / WASHINGTON ST	93940	HAZNET
MONTEREY	S101822874	MONTEREY FAIRGROUNDS-7TH DIST.	FAIRGROUNDS RD	93940	CA FID UST
MONTEREY	1000251403	PACIFIC BELL	401 FRANKLIN STREET	93940	RCRIS-SQG, FINDS, HAZNET, CA FI
					UST, HIST UST
MONTEREY	U003781830	PACIFIC BELL - FRANKLIN ST.	401 FRANKLIN ST.	93940	UST
MONTEREY	S103960444	DEPT FISH & GAME	GRANITE CANYON RTE 1		HAZNET
MONTEREY	S104582591	COMMUNITY HOSPITAL @ MONTEREY PENI	2 HARRIS CT STE B 3 / 4	93940	HAZNET
MONTEREY	S105088412	CITY OF MONTEREY PUBLIC WORKS	JACK'S PARK WASHINGTON	93940	HAZNET
MONTEREY	S103340345	VETERAN'S MEMORIAL PARK LANDFILL	JEFFERSON STREET EXTENSION		SWF/LF
MONTEREY	U001593691	PRESIDIO OF MONTEREY EXCHANGE	KIT CARSON PLAZA	93940	HIST UST
MONTEREY	S101622889	PRESIDIO OF MONTEREY EXCHANGE	KIT CARSON PLZ	93940	CA FID UST
MONTEREY	S105025036	MONTEREY PENINSULA AIRPOR	MONTEREY COUNTY		Cortese
MONTEREY	S103678285	MONTEREY COUNTY STORM DAMAGE	MONTEREY COUNTY		HAZNET
MONTEREY	S105084861	MLM PARTNERS	2801 MONTEREY SALINAS HWY 68	93940	HAZNET
MONTEREY	S103962343	EDDIE HUANG	1500 MONTEREY PASS RD		HAZNET, Cortese
MONTEREY	S105087273	MLM PARTNERS	2801 MONTEREY-SALINAS HIGHWAY	93940	HAZNET
MONTEREY	S101622873	MONTEREY COUNTY S.P.C.A.	1002 MONTEREY/SALINAS HWY	93940	CA FID UST
MONTEREY	S104566430	MONTEREY COUNTY BANK	601 MUNARS	93940	HAZNET
MONTEREY	S105461915	GRANITE CANYON MARINE LAB	34500 HIGHWAY ONE	93940	Cal-Sites, AWP
MONTEREY	S103678697	MURLAND RICHARD L MD	757 PACIFIC ST STE D-1	93940	HAZNET
MONTEREY	S103680154	MONTEREY COUNTY/CLANDESTINE DRUG L	VARIOUS LOCATIONS WITHIN MONTE		HAZNET
MONTEREY	U001593673	MONTEREY MARINE SERVICE	WHARF #2	93940	HIST UST
MONTEREY	S105256236	MONTEREY MUNICIPAL MARINA	WHARF II	93940	CA WDS
MONTEREY	S101822875	MONTEREY MARINE SERVICE	WHARF 2	93940	CA FID UST

TC0960024.13s Page 104

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
MONTEREY	S102361364	MONTEREY PRESIDIO LF	YERBA BUENA ST. AT PRESIDIO		SWF/LF

TC0960024.13s Page 105

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provide confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM STANDARD RECORDS

NPL: National Priority List

Source: EPA

National Priorities List (Superfund) The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/28/03
Date Made Active at EDR: 03/04/03
Database Release Frequency: Semi-Annually

NPL Site Boundaries

Source: EPA

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1

Telephone 617-918-1143

EPA Region 3

Telephone 215-914-5418

EPA Region 4

Telephone 404-562-5033

EPA Region 6

Telephone: 214-655-8659

EPA Region 8

Telephone: 303-312-8774

Proposed NPL: Proposed National Priority List Sites

Source: EPA

Telephone: N/A

Date of Government Version: 01/28/03

Date Made Active at EDR: 03/04/03

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 02/04/03

Elapsed ASTM days: 28

Date of Last EDR Contact: 02/04/03

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA

Telephone: 703-413-0223

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 03/18/03

Date Made Active at EDR: 04/08/03

Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 03/24/03

Elapsed ASTM days: 15

Date of Last EDR Contact: 03/24/03

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Source: EPA

Telephone: 703-413-0223

As of February 1985, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 03/19/03
Date Made Active at EDR: 04/08/03
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 03/24/03

Elapsed ASTM days: 15

Date of Last EDR Contact: 03/24/03

CORRECTA: Corrective Action Report

Source: EPA

Telephone: 800-424-9346

CORRECTA identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 01/15/03

Date Made Active at EDR: 03/04/03

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 01/27/03

Elapsed ASTM days: 42

Date of Last EDR Contact: 03/10/03

RCRIS: Resource Conservation and Recovery Information System

Source: EPA/NTIS

Telephone: 800-424-9346

Resource Conservation and Recovery Information System: RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 08/09/02

Date Made Active at EDR: 10/28/02

Database Release Frequency: Varies

Date of Data Arrival at EDR: 08/24/02

Elapsed ASTM days: 34

Date of Last EDR Contact: 03/07/03

ERNS: Emergency Response Notification System

Source: National Response Center, United States Coast Guard

Telephone: 202-260-2342

Emergency Response Notification System: ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/01

Date Made Active at EDR: 07/15/02

Database Release Frequency: Annually

Date of Data Arrival at EDR: 07/02/02

Elapsed ASTM days: 13

Date of Last EDR Contact: 01/27/03

FEDERAL ASTM SUPPLEMENTAL RECORDS

BRS: Biennial Reporting System

Source: EPA/NTIS

Telephone: 800-424-9346

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/98

Database Release Frequency: Biennially

Date of Last EDR Contact: 03/17/03

Date of Next Scheduled EDR Contact: 06/16/03

CONSENT: Superfund (CERCLA) Consent Decrees

Source: EPA Regional Offices

Telephone: Varies

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: N/A

Database Release Frequency: Varies

Date of Last EDR Contact: N/A

Date of Next Scheduled EDR Contact: N/A

RCD: Records Of Decision

Source: EPA

Telephone: 703-413-0223

Record of Decision: RCD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 01/09/03
Database Release Frequency: Annually
Date of Last EDR Contact: 01/07/03
Date of Next Scheduled EDR Contact: 04/07/03

DELISTED NPL: National Priority List Deletions
Source: EPA
Telephone: N/A
 The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425 (e), sites may be deleted from the NPL where no further response is appropriate.
Date of Government Version: 01/29/03
Database Release Frequency: Quarterly
Date of Last EDR Contact: 02/04/03
Date of Next Scheduled EDR Contact: 05/05/03

FINDS: Facility Index System/Facility Identification Initiative Program Summary Report
Source: EPA
Telephone: N/A
 Facility Index System: FINDS contains both facility information and pointers to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aeronautic Information Federal System), DOCKET (Enforcement Docket used to manage and track information on civil judicial docket cases for all environmental statutes), FUDS (Federal Underground Injection Control), C-DOCKET (Criminal Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).
Date of Government Version: 01/14/03
Database Release Frequency: Quarterly
Date of Last EDR Contact: 01/06/03
Date of Next Scheduled EDR Contact: 04/07/03

HMIRS: Hazardous Materials Information Reporting System
Source: U.S. Department of Transportation
Telephone: 202-368-4555
 Hazardous Materials Incident Report System: HMIRS contains hazardous material spill incidents reported to DOT.
Date of Government Version: 11/30/02
Database Release Frequency: Annually
Date of Last EDR Contact: 01/23/03
Date of Next Scheduled EDR Contact: 04/21/03

MLTS: Material Licensing Tracking System
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
 MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.
Date of Government Version: 01/16/03
Database Release Frequency: Quarterly
Date of Last EDR Contact: 01/09/03
Date of Next Scheduled EDR Contact: 04/07/03

MINES: Mines Master Index File
Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5859
Date of Government Version: 09/10/02
Database Release Frequency: Semi-Annually
Date of Last EDR Contact: 03/31/03
Date of Next Scheduled EDR Contact: 08/30/03

NPL LIENS: Federal Superfund Liens
Source: EPA
Telephone: 202-564-4287
 Federal Superfund Liens: Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.
Date of Government Version: 01/09/03
Database Release Frequency: Annually
Date of Last EDR Contact: 01/07/03
Date of Next Scheduled EDR Contact: 04/07/03

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/15/01
Database Release Frequency: No Updates Planned
Date of Last EDR Contact: 02/27/03
Date of Next Scheduled EDR Contact: 05/26/03

PADS: PCB Activity Database System
Source: EPA
Telephone: 202-564-3987
 PCB Activity Database: PADS identifies generators, transporters, commercial stores and/or brokers and disposers of PCBs who are required to notify the EPA of such activities.
Date of Government Version: 12/12/02
Database Release Frequency: Annually
Date of Last EDR Contact: 02/10/03
Date of Next Scheduled EDR Contact: 05/17/03

RAATS: RCRA Administrative Action Tracking System
Source: EPA
Telephone: 202-564-4104
 RCRA Administrative Action Tracking System: RAATS contains records based on enforcement actions issued under RCRA pertaining to major violations and includes administrative and civil actions brought by the EPA. For administrative actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.
Date of Government Version: 04/17/95
Database Release Frequency: No Updates Planned
Date of Last EDR Contact: 03/10/03
Date of Next Scheduled EDR Contact: 06/09/03

TRIS: Toxic Chemical Release Inventory System
Source: EPA
Telephone: 202-260-1531
 Toxic Release Inventory System: TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.
Date of Government Version: 12/31/00
Database Release Frequency: Annually
Date of Last EDR Contact: 03/25/03
Date of Next Scheduled EDR Contact: 08/23/03

TSCA: Toxic Substances Control Act
Source: EPA
Telephone: 202-260-5521
 Toxic Substances Control Act: TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.
Date of Government Version: 12/31/98
Database Release Frequency: Every 4 Years
Date of Last EDR Contact: 03/06/03
Date of Next Scheduled EDR Contact: 06/09/03

FTTS MSP: FIFRA/TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
Source: EPA
Telephone: 202-564-2501
Date of Government Version: 01/28/03
Database Release Frequency: Quarterly
Date of Last EDR Contact: 08/24/03
Date of Next Scheduled EDR Contact: 06/23/03

§818: Section 7 Tracking Systems
Source: EPA
Telephone: 202-564-5008
 Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.
Date of Government Version: 12/31/00
Database Release Frequency: Annually
Date of Last EDR Contact: 01/21/03
Date of Next Scheduled EDR Contact: 04/21/03

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/SCA (Toxic Substances Control Act)
 Source: EPA/Office of Prevention, Pesticides and Toxic Substances
 Telephone: 202-564-2501
 FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.
 Date of Government Version: 01/28/03
 Date of Last EDR Contact: 03/24/03
 Date of Next Scheduled EDR Contact: 06/23/03
 Database Release Frequency: Quarterly

STATE OF CALIFORNIA ASTM STANDARD RECORDS

AWP: Annual Workplan Sites
 Source: California Environmental Protection Agency
 Telephone: 916-323-3400
 Known Hazardous Waste Sites: California DTSC's Annual Workplan (AWP), formerly BEP, identifies known hazardous substances sites targeted for cleanup.
 Date of Government Version: 01/06/03
 Date Made Active at EDR: 01/28/03
 Database Release Frequency: Annually
 Date of Data Arrival at EDR: 01/06/03
 Elapsed ASTM days: 22
 Date of Last EDR Contact: 01/06/03

CAL-SITES: Calsites Database

Source: Department of Toxic Substance Control
 Telephone: 916-323-3400
 The Calsites database contains potential or confirmed hazardous substance release properties in 1986. California EPA reevaluated and significantly reduced the number of sites in the Calsites database.
 Date of Government Version: 02/28/03
 Date Made Active at EDR: 03/21/03
 Database Release Frequency: Quarterly
 Date of Last EDR Contact: 03/11/03

CHMIRS: California Hazardous Material Incident Report System

Source: Office of Emergency Services
 Telephone: 916-845-9400
 California Hazardous Material Incident Reporting System: CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).
 Date of Government Version: 12/31/01
 Date Made Active at EDR: 01/15/03
 Database Release Frequency: Varies
 Date of Data Arrival at EDR: 12/02/02
 Elapsed ASTM days: 44
 Date of Last EDR Contact: 02/24/03

CORTSE: Confuse Hazardous Waste & Substances Sites List

Source: CAL EPA/Office of Emergency Information
 Telephone: 916-323-8100
 The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWFLS), and the Department of Toxic Substances Control (Cal-Sites).
 Date of Government Version: 04/01/01
 Date Made Active at EDR: 07/28/01
 Database Release Frequency: No Update Planned
 Date of Data Arrival at EDR: 05/28/01
 Elapsed ASTM days: 58
 Date of Last EDR Contact: 02/18/03

NOTIFY 65: Proposition 65 Records

Source: State Water Resources Control Board
 Telephone: 916-323-3546
 Proposition 65 Notification Records: NOTIFY 65 contains facility notifications about any release which could impact drinking water and thereby expose the public to a potential health risk.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/21/93
 Date Made Active at EDR: 11/18/93
 Database Release Frequency: No Update Planned
 Date of Data Arrival at EDR: 11/01/93
 Elapsed ASTM days: 18
 Date of Last EDR Contact: 01/20/03

TOXIC PITS: Toxic Pits Cleanup Act Sites

Source: State Water Resources Control Board
 Telephone: 916-227-4354
 Toxic Pits Cleanup Act Sites: TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.
 Date of Government Version: 07/01/96
 Date Made Active at EDR: 09/29/96
 Database Release Frequency: No Update Planned
 Date of Data Arrival at EDR: 08/30/96
 Elapsed ASTM days: 27
 Date of Last EDR Contact: 02/03/03

SWFLF (SMIS): Solid Waste Information System

Source: Integrated Waste Management Board
 Telephone: 916-341-4320
 Active, Closed and Inactive Landfills: SWFLF records typically contain an inventory of solid waste disposal facilities or landfills. These may be active or inactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.
 Date of Government Version: 03/14/03
 Date Made Active at EDR: 04/04/03
 Database Release Frequency: Quarterly
 Date of Data Arrival at EDR: 03/17/03
 Elapsed ASTM days: 18
 Date of Last EDR Contact: 03/17/03

WMUDS/SWAT: Waste Management Unit Database

Source: State Water Resources Control Board
 Telephone: 916-227-4448
 Waste Management Unit Database System: WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Data, Chapter 15 Monitoring Parameters, TPCA Program Information, Closure Information, and interested Parties Information.
 Date of Government Version: 04/01/00
 Date Made Active at EDR: 05/10/00
 Database Release Frequency: Quarterly
 Date of Data Arrival at EDR: 04/10/00
 Elapsed ASTM days: 30
 Date of Last EDR Contact: 03/17/03

LUST: Leaking Underground Storage Tank Information System

Source: State Water Resources Control Board
 Telephone: 916-341-5740
 Leaking Underground Storage Tank Incident Reports: LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.
 Date of Government Version: 01/08/03
 Date Made Active at EDR: 02/04/03
 Database Release Frequency: Quarterly
 Date of Data Arrival at EDR: 01/08/03
 Elapsed ASTM days: 27
 Date of Last EDR Contact: 01/08/03

CA BOND EXP. PLAN: Bond Expenditure Plan

Source: Department of Health Services
 Telephone: 916-255-2118
 Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.
 Date of Government Version: 01/01/89
 Date Made Active at EDR: 08/02/94
 Database Release Frequency: No Update Planned
 Date of Data Arrival at EDR: 07/27/84
 Elapsed ASTM days: 8
 Date of Last EDR Contact: 05/31/94

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CA UST:

UST: Active UST Facilities

Source: SWRCB

Telephone: 916-341-5700

Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 01/06/03

Date Made Active at EDR: 01/28/03

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 01/08/03
Elapsed ASTM days: 20
Date of Last EDR Contact: 01/08/03

VCP: Voluntary Cleanup Program Properties

Source: Department of Toxic Substances Control

Telephone: 916-323-3400

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have requested that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 02/28/03

Date Made Active at EDR: 04/04/03

Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 03/05/03
Elapsed ASTM days: 30
Date of Last EDR Contact: 03/05/03

INDIAN UST: Underground Storage Tanks on Indian Land

Source: EPA Region 8

Telephone: 415-872-3368

Date of Government Version: N/A

Date Made Active at EDR: N/A

Database Release Frequency: Varies

Date of Data Arrival at EDR: N/A
Elapsed ASTM days: 0
Date of Last EDR Contact: N/A

CA FID UST: Facility Inventory Database

Source: California Environmental Protection Agency

Telephone: 916-445-6832

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resources Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/84

Date Made Active at EDR: 08/28/95

Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 08/05/95
Elapsed ASTM days: 24
Date of Last EDR Contact: 12/28/98

HIST UST: Hazardous Substance Storage Container Database

Source: State Water Resources Control Board

Telephone: 916-341-5700

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/90

Date Made Active at EDR: 02/12/81

Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 01/25/91
Elapsed ASTM days: 18
Date of Last EDR Contact: 07/26/01

STATE OF CALIFORNIA ASTM SUPPLEMENTAL RECORDS

AST: Aboveground Petroleum Storage Tank Facilities

Source: State Water Resources Control Board

Telephone: 916-341-5712

Registered Aboveground Storage Tanks

Date of Government Version: 03/18/03

Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/03/03
Date of Next Scheduled EDR Contact: 05/05/03

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CLEANERS: Cleaner Facilities

Source: Department of Toxic Substances Control

Telephone: 916-225-0873

A list of drycleaning-related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholstery cleaning; industrial laundries; laundry and garment services.

Date of Government Version: 03/18/02

Database Release Frequency: Annually

Date of Last EDR Contact: 01/15/03
Date of Next Scheduled EDR Contact: 04/07/03

CA WDS: Waste Discharge System

Source: State Water Resources Control Board

Telephone: 916-457-1571

Sites which have been issued waste discharge requirements.

Date of Government Version: 03/21/03

Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/24/03
Date of Next Scheduled EDR Contact: 06/23/03

DEED: List of Deed Restrictions

Source: Department of Toxic Substances Control

Telephone: 916-323-3400

The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes.

Date of Government Version: 01/03/03

Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/08/03
Date of Next Scheduled EDR Contact: 04/07/03

NFA: No Further Action Determination

Source: Department of Toxic Substances Control

Telephone: 916-323-3400

This category contains properties at which DTSC has made a clear determination that the property does not pose a problem to the environment or to public health.

Date of Government Version: 02/28/03

Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/03
Date of Next Scheduled EDR Contact: 06/02/03

REF: Unconfirmed Properties Referred to Another Agency

Source: Department of Toxic Substances Control

Telephone: 916-323-3400

This category contains properties where contamination has not been confirmed and which were determined as not requiring direct DTSC Site Mitigation Program action or oversight. Accordingly, these sites have been referred to another state or local regulatory agency.

Date of Government Version: 03/18/03

Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/03
Date of Next Scheduled EDR Contact: 06/02/03

SCH: School Property Evaluation Program

Source: Department of Toxic Substances Control

Telephone: 916-323-3400

This category contains properties and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CUSTIES category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 02/28/03

Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/03
Date of Next Scheduled EDR Contact: 06/02/03

NFE: Properties Needing Further Evaluation

Source: Department of Toxic Substances Control

Telephone: 916-323-3400

This category contains properties that are suspected of being contaminated. These are unconfirmed contaminated properties that need to be assessed using the PEA process. PEA in Progress indicates properties where DTSC is currently conducting a PEA. PEA Required indicates properties where DTSC has determined a PEA is required but not currently underway.

Date of Government Version: 02/28/03

Database Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/28/03
 Database Release Frequency: Quarterly
 Date of Last EDR Contact: 03/11/03
 Date of Next Scheduled EDR Contact: 08/02/03

HAZMET: Hazardous Waste Information System
 Source: California Environmental Protection Agency
 Telephone: 916-265-1136
 Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method.
 Date of Government Version: 12/31/01
 Database Release Frequency: Annually
 Date of Last EDR Contact: 02/10/03
 Date of Next Scheduled EDR Contact: 05/12/03

LOCAL RECORDS

ALAMEDA COUNTY:

Local Oversight Program Listing of UGT Cleanup Sites
 Source: Alameda County Environmental Health Services
 Telephone: 510-567-8700

Date of Government Version: 12/02/02
 Database Release Frequency: Semi-Annually
 Date of Last EDR Contact: 01/27/03
 Date of Next Scheduled EDR Contact: 04/28/03

Underground Tanks
 Source: Alameda County Environmental Health Services
 Telephone: 510-567-8700

Date of Government Version: 11/28/02
 Database Release Frequency: Semi-Annually
 Date of Last EDR Contact: 01/27/03
 Date of Next Scheduled EDR Contact: 04/28/03

CONTRA COSTA COUNTY:

Site List

Source: Contra Costa Health Services Department
 Telephone: 925-846-2286
 List includes sites from the underground tank, hazardous waste generator and business plan/2186 programs.

Date of Government Version: 06/05/02
 Database Release Frequency: Semi-Annually
 Date of Last EDR Contact: 03/03/03
 Date of Next Scheduled EDR Contact: 08/02/03

FRESNO COUNTY:

CUPA Resources List

Source: Dept. of Community Health
 Telephone: 556-445-3271
 Certified Unified Program Agency (CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 03/28/03
 Database Release Frequency: Semi-Annually
 Date of Last EDR Contact: 01/24/03
 Date of Next Scheduled EDR Contact: 06/12/03

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

KERN COUNTY:

Underground Storage Tank Sites & Tank Listing

Source: Kern County Environmental Health Services Department
 Telephone: 805-882-8700
 Kern County Sites and Tanks Listing.

Date of Government Version: 03/25/03
 Database Release Frequency: Quarterly
 Date of Last EDR Contact: 03/10/03
 Date of Next Scheduled EDR Contact: 06/08/03

LOS ANGELES COUNTY:

List of Solid Waste Facilities

Source: Los County Department of Public Works
 Telephone: 818-458-5185

Date of Government Version: 03/01/03
 Database Release Frequency: Varies
 Date of Last EDR Contact: 02/26/03
 Date of Next Scheduled EDR Contact: 05/19/03

City of El Segundo Underground Storage Tank

Source: City of El Segundo Fire Department
 Telephone: 310-507-2239

Date of Government Version: 03/01/03
 Database Release Frequency: Semi-Annually
 Date of Last EDR Contact: 02/18/03
 Date of Next Scheduled EDR Contact: 05/19/03

City of Long Beach Underground Storage Tank

Source: City of Long Beach Fire Department
 Telephone: 562-570-2543

Date of Government Version: 05/30/02
 Database Release Frequency: Annually
 Date of Last EDR Contact: 02/24/03
 Date of Next Scheduled EDR Contact: 05/28/03

City of Torrance Underground Storage Tank

Source: City of Torrance Fire Department
 Telephone: 310-618-2873

Date of Government Version: 02/25/03
 Database Release Frequency: Semi-Annually
 Date of Last EDR Contact: 02/18/03
 Date of Next Scheduled EDR Contact: 05/19/03

City of Los Angeles Landfills

Source: Engineering & Construction Division
 Telephone: 213-473-7888

Date of Government Version: 03/01/02
 Database Release Frequency: Varies
 Date of Last EDR Contact: 03/17/03
 Date of Next Scheduled EDR Contact: 06/16/03

HHS: Street Number List

Source: Department of Public Works
 Telephone: 626-458-3517

Industrial Waste and Underground Storage Tank Sites.
 Date of Government Version: 11/27/02
 Database Release Frequency: Semi-Annually
 Date of Last EDR Contact: 02/18/03
 Date of Next Scheduled EDR Contact: 05/19/03

Site Mitigation List

Source: Community Health Services
 Telephone: 323-880-7286

Industrial sites that have had some sort of spill or complaint.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 01/07/03
Database Release Frequency: Annually
Date of Last EDR Contact: 02/19/03
Date of Next Scheduled EDR Contact: 06/19/03

San Gabriel Valley Area of Concern
Source: EPA Region 9
Telephone: 415-917-3178
San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.
Date of Government Version: 12/31/98
Database Release Frequency: No Update Planned
Date of Last EDR Contact: 06/29/99
Date of Next Scheduled EDR Contact: N/A

MARIN COUNTY:
Underground Storage Tank Sites
Source: Public Works Department Waste Management
Telephone: 415-498-6647
Currently permitted USTs in Marin County.
Date of Government Version: 03/04/03
Database Release Frequency: Semi-Annually
Date of Last EDR Contact: 02/03/03
Date of Next Scheduled EDR Contact: 06/05/03

MARIN COUNTY:
Sites With Reported Contamination
Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Date of Government Version: 03/31/03
Database Release Frequency: Semi-Annually
Date of Last EDR Contact: 03/31/03
Date of Next Scheduled EDR Contact: 08/30/03

Closed and Operating Underground Storage Tank Sites
Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Date of Government Version: 03/31/03
Database Release Frequency: Annually
Date of Last EDR Contact: 03/31/03
Date of Next Scheduled EDR Contact: 08/30/03

ORANGE COUNTY:
List of Underground Storage Tank Cleanups
Source: Health Care Agency
Telephone: 714-834-3446
Orange County Underground Storage Tank Cleanups (LUST).
Date of Government Version: 11/04/02
Database Release Frequency: Quarterly
Date of Last EDR Contact: 03/14/03
Date of Next Scheduled EDR Contact: 08/09/03

List of Underground Storage Tank Facilities
Source: Health Care Agency
Telephone: 714-834-3446
Orange County Underground Storage Tank Facilities (UST).
Date of Government Version: 11/27/01
Database Release Frequency: Quarterly
Date of Last EDR Contact: 03/14/03
Date of Next Scheduled EDR Contact: 08/09/03

List of Industrial Site Cleanups
Source: Health Care Agency
Telephone: 714-834-3446
Petroleum and non-petroleum spills.
Date of Last EDR Contact: 03/14/03
Date of Next Scheduled EDR Contact: 08/09/03

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/24/00
Database Release Frequency: Annually
Date of Last EDR Contact: 03/14/03
Date of Next Scheduled EDR Contact: 08/09/03

PLACER COUNTY:
Master List of Facilities
Source: Placer County Health and Human Services
Telephone: 530-868-7312
List includes aboveground tanks, underground tanks and cleanup sites.
Date of Government Version: 02/03/03
Database Release Frequency: Semi-Annually
Date of Last EDR Contact: 02/25/03
Date of Next Scheduled EDR Contact: 06/23/03

RIVERSIDE COUNTY:
List of Underground Tank Cleanup Sites
Source: Department of Public Health
Telephone: 951-358-5055
Riverside County Underground Storage Tank Cleanup Sites (LUST).
Date of Government Version: 02/24/03
Database Release Frequency: Quarterly
Date of Last EDR Contact: 01/20/03
Date of Next Scheduled EDR Contact: 04/21/03

Underground Storage Tank Tank List
Source: Health Services Agency
Telephone: 951-358-5055
Date of Government Version: 02/24/03
Database Release Frequency: Quarterly
Date of Last EDR Contact: 01/20/03
Date of Next Scheduled EDR Contact: 04/21/03

SACRAMENTO COUNTY:
CS - Contaminated Sites
Source: Sacramento County Environmental Management
Telephone: 916-875-8408
Date of Government Version: 10/26/02
Database Release Frequency: Quarterly
Date of Last EDR Contact: 02/03/03
Date of Next Scheduled EDR Contact: 06/06/03

MI - Regulatory Compliance Master List
Source: Sacramento County Environmental Management
Telephone: 916-875-8408
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.
Date of Government Version: 11/06/02
Database Release Frequency: Quarterly
Date of Last EDR Contact: 02/03/03
Date of Next Scheduled EDR Contact: 06/06/03

SAN BERNARDINO COUNTY:
Hazardous Material Permits
Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.
Date of Last EDR Contact: 02/03/03
Date of Next Scheduled EDR Contact: 06/06/03

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 01/16/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/10/03
Date of Next Scheduled EDR Contact: 06/09/03

SAN DIEGO COUNTY:

Solid Waste Facilities

Source: Department of Health Services
Telephone: 619-338-2200
San Diego County Solid Waste Facilities.
Date of Government Version: 08/01/00
Database Release Frequency: Varies

Date of Last EDR Contact: 02/24/03
Date of Next Scheduled EDR Contact: 05/26/03

Hazardous Materials Management Division Database

Source: Hazardous Materials Management Division
Telephone: 619-338-2288
The database includes: HESB - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HET7 - In addition to providing the same information provided in the HESB listing, HET7 provides inspection data, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 03/31/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/28/03
Date of Next Scheduled EDR Contact: 04/07/03

SAN FRANCISCO COUNTY:

Local Overfill Facilities

Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920

Date of Government Version: 03/17/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/10/03
Date of Next Scheduled EDR Contact: 06/09/03

Underground Storage Tank Information

Source: Department of Public Health
Telephone: 415-252-3920
Date of Government Version: 03/17/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/10/03
Date of Next Scheduled EDR Contact: 06/09/03

SAN MATEO COUNTY:

Fuel Leak List

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1821
Date of Government Version: 03/13/03
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/10/03
Date of Next Scheduled EDR Contact: 04/28/03

Business Inventory

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1821
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 05/01/02
Database Release Frequency: Annually

Date of Last EDR Contact: 01/13/03
Date of Next Scheduled EDR Contact: 04/14/03

SANTA CLARA COUNTY:

Fuel Leak Site Activity Report

Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Date of Government Version: 01/08/03
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 03/31/03
Date of Next Scheduled EDR Contact: 06/30/03

Hazardous Material Facilities

Source: City of San Jose Fire Department
Telephone: 408-271-4658
Date of Government Version: 01/03/02
Database Release Frequency: Annually

Date of Last EDR Contact: 03/10/03
Date of Next Scheduled EDR Contact: 06/09/03

SOLANO COUNTY:

Leaking Underground Storage Tanks

Source: Solano County Department of Environmental Management
Telephone: 707-421-6770
Date of Government Version: 12/20/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/17/03
Date of Next Scheduled EDR Contact: 06/18/03

Underground Storage Tanks

Source: Solano County Department of Environmental Management
Telephone: 707-421-6770
Date of Government Version: 12/18/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/17/03
Date of Next Scheduled EDR Contact: 06/18/03

SONOMA COUNTY:

Leaking Underground Storage Tank Sites

Source: Department of Health Services
Telephone: 707-565-5565
Date of Government Version: 01/01/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/27/03
Date of Next Scheduled EDR Contact: 04/28/03

SUTTER COUNTY:

Underground Storage Tanks

Source: Sutter County Department of Agriculture
Telephone: 530-822-7500
Date of Government Version: 07/01/01
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/06/03
Date of Next Scheduled EDR Contact: 04/07/03

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

VENTURA COUNTY:

Inventory of Illegal Abandoned and Inactive Sites

Source: Environmental Health Division
Telephone: 805-654-2813
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 08/01/02
Database Release Frequency: Annually

Date of Last EDR Contact: 02/24/03
Date of Next Scheduled EDR Contact: 05/28/03

Listing of Underground Tank Cleanup Sites

Source: Environmental Health Division
Telephone: 805-654-2813
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 03/10/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/13/03
Date of Next Scheduled EDR Contact: 04/14/03

Underground Tank Closed Sites List

Source: Environmental Health Division
Telephone: 805-654-2813
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 10/21/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/17/03
Date of Next Scheduled EDR Contact: 08/18/03

Business Plan, Hazardous Waste Producers, and Operating Underground Tanks

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 02/11/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/17/03
Date of Next Scheduled EDR Contact: 08/18/03

YOLO COUNTY:

Underground Storage Tank Comprehensive Facility Report

Source: Yolo County Department of Health
Telephone: 530-668-8846
Date of Government Version: 10/28/02
Database Release Frequency: Annually

Date of Last EDR Contact: 01/20/03
Date of Next Scheduled EDR Contact: 04/21/03

California Regional Water Quality Control Board (RWQCB) LUST Records

LUST REG 1: Active Toxic Site Investigation

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-576-2220
Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/01
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 02/24/03
Date of Next Scheduled EDR Contact: 05/28/03

LUST REG 2: Fuel Leak List

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/01/02
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/13/03
Date of Next Scheduled EDR Contact: 04/14/03

LUST REG 3: Leaking Underground Storage Tank Database

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-546-5147
Date of Government Version: 02/18/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/18/03
Date of Next Scheduled EDR Contact: 05/19/03

LUST REG 4: Underground Storage Tank Leak List

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-268-6800
Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 08/08/01
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 03/31/03
Date of Next Scheduled EDR Contact: 08/30/03

LUST REG 5: Leaking Underground Storage Tank Database

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 818-255-5125
Date of Government Version: 01/01/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/20/03
Date of Next Scheduled EDR Contact: 04/07/03

LUST REG 6: Leaking Underground Storage Tank Case Listing

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 818-542-5424
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 01/01/03
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 01/06/03
Date of Next Scheduled EDR Contact: 04/07/03

LUST REG 6: Leaking Underground Storage Tank Case Listing

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-346-7491
Date of Government Version: 01/24/03
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/06/03
Date of Next Scheduled EDR Contact: 04/07/03

LUST REG 7: Leaking Underground Storage Tank Case Listing

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-346-7491
Date of Government Version: 07/02/02
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 03/31/03
Date of Next Scheduled EDR Contact: 08/30/03

LUST REG 8: Leaking Underground Storage Tanks

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 805-762-4498
California Regional Water Quality Control Board's LUST database.
to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/14/03
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 02/18/03
Date of Next Scheduled EDR Contact: 05/12/03

LUST REG 8: Leaking Underground Storage Tank Report

Source: California Regional Water Quality Control Board San Diego Region (8)
Telephone: 855-467-5280
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 03/01/01
 Database Release Frequency: No Update Planned
 Date of Last EDR Contact: 02/03/03
 Date of Next Scheduled EDR Contact: 04/21/03

California Regional Water Quality Control Board (RWQCB) SLIC Records

SLIC REG 1: Active Toxic Site Investigations
 Source: California Regional Water Quality Control Board, North Coast Region (1)
 Telephone: 707-576-2220

Date of Government Version: 02/01/01
 Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 03/10/03
 Date of Next Scheduled EDR Contact: 05/28/03

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
 Source: Regional Water Quality Control Board San Francisco Bay Region (2)
 Telephone: 510-286-0457
 Any contaminated site that impacts groundwater or has the potential to impact groundwater.

Date of Government Version: 10/01/02
 Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/13/03
 Date of Next Scheduled EDR Contact: 04/14/03

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
 Source: California Regional Water Quality Control Board Central Coast Region (3)
 Telephone: 805-548-3147
 Any contaminated site that impacts groundwater or has the potential to impact groundwater.

Date of Government Version: 02/18/03
 Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/18/03
 Date of Next Scheduled EDR Contact: 05/18/03

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
 Source: Regional Water Quality Control Board Los Angeles Region (4)
 Telephone: 213-576-8800
 Any contaminated site that impacts groundwater or has the potential to impact groundwater.

Date of Government Version: 02/01/03
 Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/27/03
 Date of Next Scheduled EDR Contact: 04/28/03

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
 Source: Regional Water Quality Control Board Central Valley Region (5)
 Telephone: 916-865-3075
 Unregulated sites that impact groundwater or have the potential to impact groundwater.

Date of Government Version: 01/01/03
 Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/06/03
 Date of Next Scheduled EDR Contact: 04/07/03

SLIC REG 6: SLIC Sites
 Source: California Regional Water Quality Control Board, Latonian Region
 Telephone: 530-542-5574

Date of Government Version: 03/01/03
 Database Release Frequency: Varies

Date of Last EDR Contact: 03/10/03
 Date of Next Scheduled EDR Contact: 06/09/03

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
 Source: Regional Water Quality Control Board, Victoria Branch
 Telephone: 818-241-6683

Date of Government Version: 07/19/01
 Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/27/03
 Date of Next Scheduled EDR Contact: 04/07/03

SLIC REG 7: SLIC List
 Source: California Regional Water Quality Control Board, Colorado River Basin Region
 Telephone: 760-346-7491

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 03/01/03
 Database Release Frequency: Varies

Date of Last EDR Contact: 02/28/03
 Date of Next Scheduled EDR Contact: 05/28/03

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
 Source: California Regional Water Quality Control Board Santa Ana Region (8)
 Telephone: 800-782-3298

Date of Government Version: 09/01/02
 Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/08/03
 Date of Next Scheduled EDR Contact: 04/07/03

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
 Source: California Regional Water Quality Control Board San Diego Region (9)
 Telephone: 656-467-2880

Date of Government Version: 03/03/03
 Database Release Frequency: Annually

Date of Last EDR Contact: 03/03/03
 Date of Next Scheduled EDR Contact: 06/02/03

EDR PROPRIETARY HISTORICAL DATABASES

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

STATE OF CALIFORNIA BROWNFIELD DATABASES RECORDS

VCP: Voluntary Cleanup Program Properties

Source: Department of Toxic Substances Control
 Telephone: 916-323-3400

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have requested that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 02/28/03
 Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/05/03
 Date of Next Scheduled EDR Contact: 06/02/03

OTHER DATABASES

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

USGS Wetlands: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

STREET AND ADDRESS INFORMATION

© 2003 Geographic Data Technology, Inc. Real 07/2001. This product contains proprietary and confidential property of Geographic Data Technology, Inc. Unauthorized use, including copying for other than testing and standard backup procedures, of this product is expressly prohibited.

GEOCHECK ®. PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

VISITOR CTR-SITE #4/MONTEREY TRAIN DEPOT
DEL MONTE AVENUE/WASHINGTON ST
MONTEREY, CA 93940

TARGET PROPERTY COORDINATES

Latitude (North):	36 50'29.9 - 36 36' 4.7"
Longitude (West):	121 50'18.0 - 121 53' 30.5"
Universal Transverse Mercator:	Zone 10
UTM X (Meters):	599118.9
UTM Y (Meters):	4051014.2

EDR's GeoCheck Physical Setting Source Addendum has been developed to assist the environmental professional with the collection of physical setting source information in accordance with ASTM 1527-00, Section 7.2.3. Section 7.2.3 requires that a current USGS 7.5 Minute Topographic Map (or equivalent, such as the USGS Digital Elevation Model) be reviewed. It also requires that one or more additional physical setting sources be sought when (1) conditions have been identified in which hazardous substances or petroleum products are likely to migrate to or from the property, and (2) more information than is provided by the current USGS 7.5 Minute Topographic Map (or equivalent) is generally obtained, pursuant to local good practice or customary practice, to assess the impact of migration of recognized environmental conditions in connection with the property. Such additional physical setting sources generally include information about the topographic, hydrologic, hydrogeologic, and geologic characteristics of a site, and wells in the area.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata. EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

USGS TOPOGRAPHIC MAP ASSOCIATED WITH THIS SITE

Target Property: 2436121-EB MONTEREY, CA
Source: USGS 7.5 min quad index

GENERAL TOPOGRAPHIC GRADIENT AT TARGET PROPERTY

Target Property: General ENE

Source: General Topographic Gradient has been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County: FEMA Flood
MONTEREY, CA: Electronic Data
YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 0602000003C

Additional Panels in search area: 0602000002C

NATIONAL WETLAND INVENTORY

NWI Quind at Target Property: NWI Electronic
MONTEREY: Data Coverage
YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Site Specific Hydrogeological Data*

Search Radius: 2.0 miles
Status: Not found

AQUIFLOW®

Search Radius: 2,000 Miles.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION	GENERAL DIRECTION
Not Reported	FROM TP	GROUNDWATER FLOW

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Stratigraphic Unit	Geologic Age Identification
Era: Mesozoic	Category: Plutonic and Intrusive Rocks
System: Cretaceous	
Series: Cretaceous granitic rocks	
Code: Kg (deposited above as Era, System & Series)	

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schuchman, R.E. Arndt and W.J. Bawiec, Geology of the Continental U.S. at 1:2,500,000 Scale, a digital representation of the 1974 P.B. King and H.M. Belkman Map, USGS Digital Data Series DDS - 11 (1984).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map is a map showing the distribution of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing from detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

* EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Component Name: SANTA VINEZ

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Moderately well drained. Soils have a layer of low hydraulic conductivity, wet state high in the profile. Depth to water table is 3 to 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: MODERATE

Depth to Bedrock Min: > 60 inches

Depth to Bedrock Max: > 60 inches

Soil Layer Information					
Boundary		Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil
1	0 inches	18 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soil.	COARSE-GRAINED SOLS, Sands, Silts with fines, Silty Sand.
				Max: 2.00 Min: 0.60	Max: 7.30 Min: 5.60
2	18 inches	43 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soil.	FINE-GRAINED SOLS, Silts and Clays (liquid limit less than 50%), Lean Clay.
				Max: 0.06 Min: 0.00	Max: 7.80 Min: 5.60
3	43 inches	61 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soil.	COARSE-GRAINED SOLS, Sands, Silts with fines, Clayey sand.
				Max: 0.20 Min: 0.06	Max: 7.80 Min: 5.60

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subinherent soil types may appear within the general area of large property.

Soil Surface Textures: sandy loam
very fine sandy loam
sandy clay loam
silty clay
loam

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Surficial Soil Types:

gravelly - loam
sandy loam
very fine sandy loam
sandy clay loam
silty clay
loam
gravelly - loam

Shallow Soil Types:

gravelly - sandy clay loam
sandy clay loam
gravelly - sandy loam
stratified
clay loam

Deeper Soil Types:

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

According to ASTM E 1527-00, Section 7.2.2, "one or more additional state or local sources of environmental records may be checked, in the discretion of the environmental professional, to enhance and supplement federal and state sources... Factors to consider in determining which local or additional state records, if any, should be checked include (1) whether they are reasonably ascertainable, (2) whether they are sufficiently useful, accurate, and complete in light of the objective of this records review (see 7.1.1) and (3) whether they are obtained, pursuant to local, good commercial or customary practice." One of the record sources listed in Section 7.2.2 is water well information. Water well information can be used to assist the environmental professional in assessing sources that may impact groundwater flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1,000
Federal FRDS PWS	National PWS within 1 mile
State Database	1,000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	CA2710019	1/8 - 1/4 Mile WSW

Note: PWS System location is not always the same as well location.


GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID _____
WELL ID _____
No Wells Found

LOCATION
FROM TP _____

PHYSICAL SETTING SOURCE MAP - 0960024.13s



TARGET PROPERTY: Visitor Ctr-Site #4/Monterey Train Depot
ADDRESS: Del Monte Ave/Washington St
CITY/STATE/ZIP: Monterey CA 93940
LAT/LONG: 36.6013 / 121.8918

CUSTOMER: Weber, Hayes, & Associates
CONTACT: Pat Hoban
INQUIRY #: 0960024.13s
DATE: April 15, 2003 11:36 AM

Copyright © 2003 ESRI, Inc. © 2003 ESRI, Inc. All Rights Reserved.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID: 18714
 Direction: 18714
 Distance: 18714
 Elevation: 18714

Database: EDR ID Number: CA2710019

PWS ID: CA2710019
 Date Initiated: Not Reported
 PWS Name: CWSC OAK HILLS
 Date Deactivated/Not Reported: Not Reported
 SAN JOSE, CA 95108

Addressee / Facility: Not Reported

Facility Latitude: Not Reported
 City Served: OAK HILLS
 Treatment Class: Mixed (treated and untreated)
 Facility Longitude/Not Reported
 Population: 2300

PWS currently has or had major violation(s) or enforcement: Yes

Violations information not reported.

ENFORCEMENT INFORMATION:

System Name: CWSC OAK HILLS
 Violation Type: Initial Tap Sampling for Pb and Cu
 Contaminant: LEAD & COPPER RULE
 Compliance Period: 1993-07-01 - 2000-04-04
 Violation ID: 85V0001
 Enforcement Date: 2000-04-04
 System Name: CWSC OAK HILLS
 Violation Type: Initial Tap Sampling for Pb and Cu
 Contaminant: LEAD & COPPER RULE
 Compliance Period: 1993-07-01 - 2015-12-31
 Violation ID: 95V0001
 Enforcement Date: Not Reported
 Analytical Value: 0000000.000000000
 Enforcement ID: 0098998
 Enfr. Action: State Compliance Achieved
 Analytical Value: 0000000.000000000
 Enforcement ID: Not Reported
 Enfr. Action: Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for MONTEREY County: 2
 Note: Zone 1 indoor average level > 4 pCi/L.
 : Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
 : Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 93940				
Number of sites tested: 2				
Area	Average Activity	% <= 4 pCi/L	% 4-20 pCi/L	% > 20 pCi/L
Living Area - 1st Floor	0.770 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1989 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW[®] Information System

Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schindler, R.E. Arnold and W.J. Bewick, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1874 P.B. King and H.M. Beekman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO - State Soil Geographic Database

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the national Cooperative Soil Survey (NCS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generating more detailed (SSURGO) soil survey maps.

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System: A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1985: Prior to August 1985, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STATE RECORDS

California Drinking Water Quality Database

Source: Department of Health Services

Telephone: 916-324-2319

The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

California Oil and Gas Well Locations for District 2, 3, 5 and 6

Source: Department of Conservation

Telephone: 916-323-1779

RADON

Area Radon Information

Source: USGS

Telephone: 703-556-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1985 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA

Telephone: 703-556-4020

Sections 307 & 309 of RAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.


OTHER

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United States Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

DETAIL MAP - 0960024.13s - Weber, Hayes, & Associates



★ Target Property

▲ Sites at elevations higher than or equal to the target property

◆ Sites at elevations lower than the target property

▲ Coal Gasification Sites

▲ Sensitive Receptors

■ National Priority List Sites

■ Landfill Sites

— Power transmission lines

— Oil & Gas pipelines

▨ 100-year flood zone

▨ 500-year flood zone

■ Wetlands

▨ Areas of Concern

0 1/16 1/8 1/4 Miles

TARGET PROPERTY: Visitor Ctr-Site #4/Monterey Train Depot
ADDRESS: Del Monte Ave/Washington St
CITY/STATE/ZIP: Monterey CA 93940
LAT/LONG: 36.6013 / 121.8918

CUSTOMER: Weber, Hayes, & Associates
CONTACT: Pat Hoban
INQUIRY #: 0960024.13s
DATE: April 15, 2003 11:38 am

Copyright © 2003 EDR, Inc. © 2003 GDT, Inc. Rel. 07/2002. All Rights Reserved.



EDR[®] Environmental Data Resources, Inc.

The EDR Radius Map with GeoCheck[®]

Visitor Ctr-Site #4/Monterey Train Depot
Del Monte Ave/Washington St
Monterey, CA 93940
Inquiry Number: 0960024.13s

April 15, 2003

The Source For Environmental Risk Management Data

3530 Post Road
Southport, Connecticut 06890

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary.....	ES-1
Overview Map.....	2
Detail Map.....	3
Map Findings Summary.....	4
Map Findings.....	6
Orphan Summary.....	104
Government Records Searched/Data Currency Tracking.....	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum.....	A-1
Physical Setting Source Summary.....	A-2
Physical Setting Source Map.....	A-7
Physical Setting Source Map Findings.....	A-8
Physical Setting Source Records Searched.....	A-10

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer

This report contains information obtained from a variety of public and other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. Entire contents copyright 2003 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission. EDR and the edr logos are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-00. Search distances are per ASTM standard or custom distances requested by the user.

TARGET PROPERTY INFORMATION

ADDRESS

DEL MONTE AVE/WASHINGTON ST
MONTEREY, CA 93940

COORDINATES

Latitude (North): 36.601300 - 36.36 4.7"
Longitude (West): 121.891800 - 121.53 30.5"
Universal Transverse Mercator: Zone 10
UTM X (Meters): 589118.9
UTM Y (Meters): 4051014.2

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property: 2436121-EB MONTEREY, CA
Source: USGS 7.5 min quad index

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable") government records either on the target property or within the ASTM E 1527-00 search radius around the target property for the following databases:

FEDERAL ASTM STANDARD

NPL..... National Priority List
Proposed NPL..... Proposed National Priority List Sites
CERCLIS..... Comprehensive Environmental Response, Compensation, and Liability Information System
CERCLIS No Further Remedial Action Planned
CORRECTS..... Corrective Action Report
RCRIS-TSD..... Resource Conservation and Recovery Information System
RCRIS-LQG..... Resource Conservation and Recovery Information System
ERNS..... Emergency Response Notification System

STATE ASTM STANDARD

AWP..... Annual Workplan Sites

EXECUTIVE SUMMARY

Cal Sites..... Caltrans Database
Toxic Plus..... Toxic Plus Cleanup Act Sites
SWIFL..... Solid Waste Information System
WMLDS/SWAT..... Waste Management Unit Database
CA BOND EXP. PLAN..... Bond Expenditure Plan
VCP..... List of Underground Storage Tank Facilities
VCP..... Voluntary Cleanup Program Properties
INDIAN UST..... Underground Storage Tanks on Indian Land

FEDERAL ASTM SUPPLEMENTAL

CONSENT..... Superfund (CERCLA) Consent Decrees
ROD..... Records Of Decision
Deleted NPL..... National Priority List Deletions
FINDS..... Facility Index System/Facility Identification Initiative Program Summary Report
HMRS..... Hazardous Materials Information Reporting System
MLTS..... Material Licensing Tracking System
MINES..... Mines Master Index File
NPL Liens..... Federal Superfund Liens
PAOS..... PCB Activity Database System
RAATRS..... RCRA Administrative Action Tracking System
TRIG..... Toxic Chemical Release Inventory System
TSCA..... Toxic Substances Control Act
SSTS..... Section 7 Tracking Systems
FTTS..... FIFRA/TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

STATE OR LOCAL ASTM SUPPLEMENTAL

AST..... Aboveground Petroleum Storage Tank Facilities
CA WDS..... Waste Discharge System
DEED..... List of Dead Restrictions
NFA..... No Further Action Determination
REF..... Unconfirmed Properties Referred to Another Agency
SCH..... School Property Evaluation Program
NFE..... Properties Needing Further Evaluation

BROWNFIELD DATABASES

VCP..... Voluntary Cleanup Program Properties

SURROUNDING SITES SEARCH RESULTS

Surrounding sites were identified.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. EDR's definition of a site with an elevation equal to the target property includes a tolerance of +/- 10 feet. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property (by more than 10 feet). Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

FEDERAL ASTM STANDARD

RCRIS: The Resource Conservation and Recovery Act database includes selected information on sites that generate, store, treat, or dispose of hazardous waste as defined by the Act. The source of this database is the U.S. EPA.

A review of the RCRIS-SQG list, as provided by EDR, and dated 09/09/2002 has revealed that there are 5 RCRIS-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
TOSCO NORTHWEST CO NO 11168	312 DEL MONTE AVE	0 - 1/8 SSW A1	6	
AUTOMOTIVE CARE	WASHINGTON & FRANKLIN	0 - 1/8 SSW C10	12	
RAINBOW CLEANERS	289 BONIFACIO	1/8 - 1/4SSW G25	26	
JACK FOX AUTO SVC	485 WASHINGTON & PEARL	1/8 - 1/4S 30	30	
RUSSELL'S CAMERA WEST	400 ALVARADO ST	1/8 - 1/4SSW K38	35	

STATE ASTM STANDARD

CHMIRS: The California Hazardous Material Incident Report System contains information on reported hazardous material incidents, i.e., accidental releases or spills. The source is the California Office of Emergency Services.

A review of the CHMIRS list, as provided by EDR, and dated 12/31/2001 has revealed that there are 8 CHMIRS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
Not reported	FIGUERO ST / DEL MONT	0 - 1/8 SE B12	14	
Not reported	ROYAL SEAFOODS COMMERC	1/4 - 1/2NNE 45	43	
ARCO PRODUCTS COMPANY	400 FREMONT BLVD	1/4 - 1/2S N55	40	
COAST GUARD STATION MONTEREY	100 LIGHTHOUSE AVE	1/2 - 1 NNW Q87	82	
Not reported	32 CANNERY ROW	1/2 - 1 NNW 69	86	
Not reported	SLOAT / 4TH STREETS	1/2 - 1 ESE 73	91	
MONTEREY PLAZA HOTEL	400 CANNERY ROW	1/2 - 1 NNW 75	84	
Not reported	HWY 1 S BOUND FREMONT S	1/2 - 1 SE 77	96	

CORTSE: This database identifies public drinking water wells with detectable levels of contamination, hazardous substance sites selected for remedial action, sites with known toxic material identified through the abandoned site assessment program, sites with USTs having a reportable release and all solid waste disposal facilities from which there is known migration. The source is the California Environmental Protection Agency/Office of Emergency Information.

A review of the Cortese list, as provided by EDR, has revealed that there are 22 Cortese sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
BP OIL COMPANY	312 DEL MONTE AVE	0 - 1/8 SSW A3	7	
COCHRAN AUTOSHOP SITE	417 FIGUEROA ST	1/8 - 1/4SSE F23	23	
BLANCH SITE	600 FRANKLIN ST E	1/8 - 1/4SSE J35	33	
DOUGHERTY'S AUTO PAINT	288 PEARL ST (2)	1/8 - 1/4SSW L40	36	
BRITISH MOTORS	735 DEL MONTE AVE	1/4 - 1/2ESE 47	46	
MISSION MORTUARY	450 CAMINO EL ESTERO	1/4 - 1/2SE 48	48	

EXECUTIVE SUMMARY

Equal/Higher Elevation

Address	Dist / Dir	Map ID	Page
CHEVRON 91060	1/4 - 1/2S M52	55	
ARCO PRODUCTS COMPANY	1/4 - 1/2S M55	60	
UNOCAL SERVICE STATION #M424	1/4 - 1/2S M56	64	
BP FACILITY	1/4 - 1/2S M57	67	
MONTEREY FIRE DEPT	1/4 - 1/2SSW 59	72	
RECOVERY CENTER (CHOMP)	1/4 - 1/2SSW 60	74	
ELESTERO CARMASH	1/4 - 1/2SSW 62	78	
PRESIDIO OF MONTEREY	1/4 - 1/2SSW 65	82	
EXXON SERVICE STATION	1/2 - 1 E 66	82	
U.S. COAST GUARD	1/2 - 1 NNW Q88	84	
Z & S AUTO SALES	1/2 - 1 E 70	87	
MONTEREY PENINSULA COLLEGE	1/2 - 1 SE 72	89	
CORNER STORE	1/2 - 1 NNW 74	92	
DANA PROPERTY	1/2 - 1 NNW 78	97	
MR TOM O'NEAL	1/2 - 1 NNW 79	99	
FORMER CHEVRON #9-3687	1/2 - 1 SE 80	101	

NOTIFY 65: Notify 65 records contain facility notifications about any release that could impact drinking water and thereby expose the public to a potential health risk. The data come from the State Water Resources Control Board's Proposition 65 database.

A review of the Notify 65 list, as provided by EDR, has revealed that there are 4 Notify 65 sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
PG&E	DEL MONTE / FIGUEROA	0 - 1/8 SE 6	11	
Not reported	FRANKLIN / FIGUEROA	1/8 - 1/4SSE 19	20	
Not reported	REESIDE PUMP STATION NEAR WAVE	1/2 - 1 NNW 71	89	
Not reported	WAVE AND DRAKE STREETS	1/2 - 1 NNW 76	96	

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the State Water Resources Control Board Leaking Underground Storage Tank Information System.

A review of the LUST list, as provided by EDR, and dated 01/06/2003 has revealed that there are 24 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
BP OIL COMPANY	312 DEL MONTE AVE	0 - 1/8 SSW A3	7	
MARQUITT MONTEREY	350 CALLE PRINCIPAL	1/8 - 1/4WSW 22	21	
COCHRAN AUTOSHOP SITE	417 FIGUEROA ST	1/8 - 1/4SSE F23	23	
BLANCH SITE	600 FRANKLIN ST E	1/8 - 1/4SSE J35	33	
DOUGHERTY'S AUTO PAINT	288 PEARL ST (2)	1/8 - 1/4SSW L40	36	
DOUGHERTY'S AUTO PAINT	288 PEARL ST (3)	1/8 - 1/4SSW L42	39	
CALIFORNIA BANK TRUST	438 ALVARADO ST.	1/4 - 1/2SSW 44	41	
SHERWIN-WILLIAMS CO THE	505 TYLER ST	1/4 - 1/2SSW 46	44	
BRITISH MOTORS	735 DEL MONTE AVE	1/4 - 1/2ESE 47	46	
MISSION MORTUARY	450 CAMINO EL ESTERO	1/4 - 1/2SE 48	48	
HONEST ENGINES	553 MURNAS AVE	1/4 - 1/2SSW 49	50	
FORMER EXXON-74228	595 MURNAS ST	1/4 - 1/2SSW 50	52	
UNKNOWN	663 MURNAS	1/4 - 1/2SSW 51	53	
CHEVRON SERVICE #91060	351 FREMONT ST	1/4 - 1/2S M53	56	

EXECUTIVE SUMMARY

Equal/Higher Elevation

Address	Dist / Dir	Map ID	Page
TOSCO - FACILITY #0424	1/4 - 1/2S	N54	58
ARCO PRODUCTS COMPANY	1/4 - 1/2S	N55	60
UNOCAL SERVICE STATION #0424	1/4 - 1/2S	N56	64
BP FACILITY	1/4 - 1/2S	N57	67
CITY OF MONTEREY	1/4 - 1/2ESE	58	69
MONTEREY FIRE DEPT	1/4 - 1/2SW	59	72
RECOVERY CENTER (CHOMP)	1/4 - 1/2SSW	60	74
EL ESTERO CAR WASH	1/4 - 1/2ESE	C61	76
HONDA KAWASAKI OF MONTEREY	1/4 - 1/2ESE	P63	79
FORMER VAPOR CLEANERS SITE	1/4 - 1/2ESE	P64	80

CA FID: The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.

A review of the CA FID UST list, as provided by EDR, has revealed that there are 4 CA FID UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation

Address	Dist / Dir	Map ID	Page
BP OIL COMP #11168	0 - 1/8 SSW A4		9
PACIFIC HEATING & PLUMBING CO.	1/8 - 1/4ESE E20	21	21
TRAFFIC UNDERPASS	1/8 - 1/4NW H27		28
MACKENZIE SLYE PARTNERSHIP	1/8 - 1/4SE	J37	35

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 4 HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation

Address	Dist / Dir	Map ID	Page
MOBIL SERVICE STATION	0 - 1/8 SSW A5		10
PACIFIC HEATING & PLUMBING CO.	1/8 - 1/4ESE E21	21	21
TRAFFIC UNDERPASS	1/8 - 1/4NW H26		27
H AND B PROPERTIES	1/8 - 1/4SE	J36	35

STATE OR LOCAL ASTM SUPPLEMENTAL

DRYCLEANERS: A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaners; agents; linen supply; coin-operated laundries and cleaning; drycleaning plants except rugs, carpet and upholstery cleaning; industrial laundries; laundry and garment services.

A review of the CLEANERS list, as provided by EDR, and dated 03/18/2002 has revealed that there is 1 CLEANERS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation

Address	Dist / Dir	Map ID	Page
RAINBOW CLEANERS	1/8 - 1/4SSW G25		26

EXECUTIVE SUMMARY

CA SLIC: SLIC Region comes from the California Regional Water Quality Control Board.

A review of the CA SLIC list, as provided by EDR, has revealed that there is 1 CA SLIC site within approximately 0.5 miles of the target property.

Equal/Higher Elevation

Address	Dist / Dir	Map ID	Page
RUSCOS MARINE FUELING STATION	0 - 1/8 SE	B11	13

HAZNET: The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 gallons of waste. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency.

A review of the HAZNET list, as provided by EDR, has revealed that there are 24 HAZNET sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation

Address	Dist / Dir	Map ID	Page
TOSCO NORTHWEST CO #11168	0 - 1/8 SSW A2		6
BP OIL COMPANY	0 - 1/8 SSW A3		7
PG&E	0 - 1/8 SE 6		11
CATELLUS DEVELOPMENT CORPORAT	0 - 1/8 ESE 8		12
CATELLUS DEVELOPMENT CORP	0 - 1/8 ESE B9		12
AUTOMOTIVE CARE	0 - 1/8 SSW C10		12
PACIFIC MOTOR SERVICE INC	1/8 - 1/4S 13		16
1X CITY OF MONTEREY	1/8 - 1/4WNW D14		17
AMERICAN ACADEMY OF ORTHOPEDIC	1/8 - 1/4WNW D15		18
FUJI PHOTO FILM USA INC C/O: M	1/8 - 1/4WNW D16		18
CITY OF MONTEREY - MONTEREY CO	1/8 - 1/4WNW D17		19
PHOTO DRIVE UP	1/8 - 1/4SSW C18		19
MANROTT MONTEREY	1/8 - 1/4WNW 22		27
KITTY HAWK, ET AL	1/8 - 1/4SSW G24		25
RAINBOW CLEANERS	1/8 - 1/4SSW G25		26
PACIFIC MOTOR SERVICE INC	1/8 - 1/4SE F28		28
MONTEREY CUSTOM COLOR LAB	1/8 - 1/4SE F29		29
SHERWIN WILLIAMS	1/8 - 1/4SE J31		31
MAIORANA FAMILY PARTNERSHIP	1/8 - 1/4SE J32		31
ATAIDE GENERAL TIRE	1/8 - 1/4SE J33		32
ROSSIS TIRE AND AUTO SERVICE	1/8 - 1/4SE J34		32
HOME SAVINGS OF AMERICA	1/8 - 1/4SW K39		36
SAUCITO LAND CO	1/8 - 1/4SSW L41		38
SAUCITO LAND CO	1/8 - 1/4SSW 43		40


PROPRIETARY DATABASES

Former Manufactured Gas (Coal Gas) Sites:

The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

A review of the Coal Gas list, as provided by EDR, has revealed that there is 1 Coal Gas site within

OVERVIEW MAP - 0960024.13s - Weber, Hayes, & Associates




TARGET PROPERTY: Visitor Ctr-Site #4/Monterey Train Depot
 ADDRESS: Del Monte Ave/Washington St
 CITY/STATE/ZIP: Monterey CA 93940
 LAT/LONG: 36.8013 / 121.8918

CUSTOMER: Weber, Hayes, & Associates
 CONTACT: Pat Hoban
 INQUIRY #: 0960024.13s
 DATE: April 15, 2003 11:38 AM

Copyright © 2003 ERM, Inc. © 2003 GSI, Inc. All Rights Reserved.

DETAIL MAP - 0960024.13s - Weber, Hayes, & Associates



TARGET PROPERTY: Visitor Ctr-Site #4/Monterey Train Depot
 ADDRESS: Del Monte Ave/Washington St
 CITY/STATE/ZIP: Monterey CA 93940
 LAT/LONG: 36.8013 / 121.8918

CUSTOMER: Weber, Hayes, & Associates
 CONTACT: Pat Hoban
 INQUIRY #: 0960024.13s
 DATE: April 15, 2003 11:38 AM

Copyright © 2003 ERM, Inc. © 2003 GSI, Inc. All Rights Reserved.

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL ASTM STANDARD								
NPL		1,000	0	0	0	0	NR	0
Proposed NPL		1,000	0	0	0	0	NR	0
CERCLIS		0,500	0	0	0	NR	NR	0
CERCLIS-APP		0,250	0	0	NR	NR	NR	0
RCRA-APP		1,000	0	0	0	NR	NR	0
RCRA-APP		0,500	0	0	NR	NR	NR	0
RCRA-APP		0,250	2	3	NR	NR	NR	5
ERNS		TP	NR	NR	NR	NR	NR	0
STATE ASTM STANDARD								
AWP		1,000	0	0	0	0	NR	0
Cal-Sites		1,000	1	0	2	5	NR	8
CHMIRS		1,000	1	3	10	8	NR	22
Cortese		1,000	1	1	0	2	NR	4
Notify 65		1,000	1	0	0	NR	NR	0
Toxic Pills		0,500	0	0	0	NR	NR	0
State Landfill		0,500	0	0	0	NR	NR	0
WMUDS/SMAT		0,500	1	5	18	NR	NR	24
LUST		1,000	0	0	0	NR	NR	0
CA Bond Exp. Plan		0,250	0	0	0	NR	NR	0
UST		0,250	0	0	0	NR	NR	0
VCP		0,250	0	0	0	NR	NR	0
INDIAN UST		0,250	0	0	0	NR	NR	0
CA FID UST		0,250	1	3	NR	NR	NR	4
HIST UST		0,250	1	3	NR	NR	NR	4
FEDERAL ASTM SUPPLEMENTAL								
CONSENT		1,000	0	0	0	0	NR	0
ROD		1,000	0	0	0	0	NR	0
Dated NPL		1,000	0	0	0	0	NR	0
FINDS		TP	NR	NR	NR	NR	NR	0
HMBRS		TP	NR	NR	NR	NR	NR	0
MUTS		TP	NR	NR	NR	NR	NR	0
MINES		0,250	0	0	NR	NR	NR	0
NPL Lens		TP	NR	NR	NR	NR	NR	0
PADS		TP	NR	NR	NR	NR	NR	0
RAATS		TP	NR	NR	NR	NR	NR	0
TRIS		TP	NR	NR	NR	NR	NR	0
TSCA		TP	NR	NR	NR	NR	NR	0
SSTS		TP	NR	NR	NR	NR	NR	0
FTS		TP	NR	NR	NR	NR	NR	0
STATE OR LOCAL ASTM SUPPLEMENTAL								
AST		TP	NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
CLEANERS								
CA WDS		0,250	0	1	NR	NR	NR	1
DEED		TP	NR	NR	NR	NR	NR	0
NFA		0,250	0	0	NR	NR	NR	0
REF		0,250	0	0	NR	NR	NR	0
NFE		0,250	0	0	NR	NR	NR	0
CA SLIC		0,250	1	0	NR	NR	NR	1
HAZNET		0,250	6	18	NR	NR	NR	24
EDR PROPRIETARY HISTORICAL DATABASES								
Coal Gas		1,000	1	0	0	0	NR	1
BROWNFIELD DATABASES								
VCP		0,500	0	0	0	NR	NR	0

NOTES:
AQUIFLOW - see EDR Physical Siting Source Addendum
TP = Target Property
NR = Not Requested at this Search Distance
Sites may be listed in more than one database

MAP FINDINGS

Map ID
Direction
Distance (ft.)
Elevation
Site

A1
SSW
< 1/8
272 ft.
Higher

Database(s)
EPA ID Number
EPA ID Number

TOSCO NORTHWEST CO NO 11188
312 DEL MONTE AVE
MONTEREY, CA 93940
Site 1 of 5 in cluster A
RCRIS-SCG
FINDS
CA0001035344
Owner: TOSCO NORTHWEST CO
(208) 442-7000
EPA ID: CA0001035344
Contact: LYNN CHUN
(208) 442-7183
Classification: Small Quantity Generator
Used Oil Recg: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:
Other Permitted Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

A2
SSW
< 1/8
272 ft.
Higher

HAZNET
8103982277
N/A

TOSCO NORTHWEST CO #11188
312 DEL MONTE AVE
MONTEREY, CA 93940
Site 2 of 5 in cluster A
HAZNET:
Gapaid: CA0001035344
Tepaid: CAD00946392
Gen County: Monterey
Tad County: San Mateo
Tons: 12.5100
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: TOSCO NORTHWEST CO
Telephone: (602) 200-4528
Mailing Address: PO BOX 52085
PHOENIX, AZ 85072 - 2085
County: Monterey
Gapaid: CA0001035344
Tepaid: CAD00946392
Gen County: Monterey
Tad County: 7
Tons: 15,000
Category: Other empty containers 30 gallons or more
Disposal Method: Disposal, Other
Contact: TOSCO NORTHWEST CO
Telephone: (602) 200-4528
Mailing Address: PO BOX 52085
PHOENIX, AZ 85072 - 2085
County: Monterey

MAP FINDINGS

Map ID
Direction
Distance (ft.)
Elevation
Site

TOSCO NORTHWEST CO #11188 (Continued)

8103982277

Gapaid: CA0001035344
Tepaid: CAD00161741
Gen County: Monterey
Tad County: 1
Tons: 8.2987
Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: TOSCO NORTHWEST CO
Telephone: (602) 200-4528
Mailing Address: PO BOX 52085
PHOENIX, AZ 85072 - 2085
County: Monterey
Gapaid: CA0001035344
Tepaid: CAD00946392
Gen County: Monterey
Tad County: 7
Tons: 0.2
Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Contact: TOSCO NORTHWEST CO
Telephone: (602) 200-4528
Mailing Address: PO BOX 52085
PHOENIX, AZ 85072 - 2085
County: Monterey

A3
SSW
< 1/8
272 ft.
Higher

HAZNET
8101307602
LUST
Contest

BP OIL COMPANY
312 DEL MONTE AVE
MONTEREY, CA 93940
Site 3 of 5 in cluster A
Site LUST:
Cross Street: Not reported
City Leased: Not reported
Case Number: 1031
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Pollution Characterization
County: Monterey
Abate Method: U
Review Date: Not reported
Workplan: Not reported
Pollution Char: 5/27/1992
Remed Action: Not reported
Case Date: Not reported
Release Date: 2/4/1991
Cleanup Fund Id: Not reported
Discovery Date: 1/1/1985
Enforcement Dt: Not reported
Ent Type: LET
Enter Date: 1/1/1985
Funding: Not reported
Staff Initials: UST

Map ID
Direction
Distance
Elevation
Site

EDR ID Number
EPA ID Number
Database(s)

BP OIL COMPANY (Continued)

5101307802

How Discovered: OM
How Stopped: Not reported
Inlet: No
Leak Cause: LINK
Leak Source: LINK
MTBE Date: 8/6/2002
Max MTBE GW: 549 Parts per Billion
MTBE Tested: 343
Priority: 343
Local Case #: Not reported
Beneficial: MLN
Staff: WNL
GW Qualifier: =
Max MTBE Sol: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 8.50
Operator: Not reported
Overnight Pgm: RB Lead Underground Storage Tank
Review Date: 8/6/2002
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: SCOTT HOOTON
RP Address: 295 41ST ST SW BLDG 13 STE N
Global ID: T096530013
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 12
Mile Fuel: 1
Well Name: Not reported
Water System Name: Not reported
Distance To Lul: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
LUST Region 3:
Case Number: 1031
Cross Street: Not reported
Responsible Party: SCOTT HOOTON
Local Agency: US
Discovered: 07/01/1985
How Found: Not reported
Source: Other
Cause: UNK
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Pollution Characterization
Facility County: Monterey
Review Date: 8/6/02
Confirm Leak: //
Prelim Assess: //
Remedial Plan: 05/21/1992
Monitoring: Not reported
Enforce Type: LET
Enforce Date: //
Infirm Action: 0
Mile Concentration: 0
Release Date: 02/04/1991
Enter Date: 1/1/85
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported
Staff Initials: WNL
Funding: Not reported
Workplan: //
Pollution Char: 11/20/1998
Remedial Action: //
Close Date: //
Pilot Program: UST
Region: 3

Map ID
Direction
Distance
Elevation
Site

EDR ID Number
EPA ID Number
Database(s)

BP OIL COMPANY (Continued)

5101307802

Mile Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: 549
Max MTBE Sol: Not reported
Max MTBE Data: 08/02/2002
MTBE Tested: YES
Lat/Long: 36.500553 / -121.8822838
Soil Qualifier: Not reported
Groundwater Qualifier: =
Summary: Not reported
HAZNET:
Gapaid: CAL000038097
Tepaid: CAT098011059
Gen County: Monterey
Tad County: Los Angeles
Tons: 4587
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Contact: TOSCO NORTHWEST COMPANY
Telephone: (000) 000-0000
Mailing Address: 601 UNION STREET
SEATTLE, WA 98101
County: Monterey
Gapaid: CAL000038097
Tepaid: CAT098011059
Gen County: Monterey
Tad County: Los Angeles
Tons: 1,1467
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: TOSCO NORTHWEST COMPANY
Telephone: (000) 000-0000
Mailing Address: 601 UNION STREET
SEATTLE, WA 98101
County: Monterey
CORTSE:
Reg Id: 1031
Region: CORTSE
Reg By: Leaking Underground Storage Tanks

A4
SSW
< 1/8
272 ft.
Higher
BP OIL COMP #11188
312 DEL MONTE AVE
MONTEREY, CA 93940
Site 4 of 5 in cluster A

CA FID UST 5101588701
N/A

Map ID
Direction
Distance
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MAP FINDINGS

BP OIL COMP #11188 (Continued)

Facility ID: 27000108
Reg By: Active
Status: Not reported
SIC Code: Not reported
Facility Tel: (408) 375-7555
Mail To: Not reported
Contact: 2868 PROSPECT DR
MONTEREY, CA 93940
Contact Tel: Not reported
NPDES No: Not reported
Modified: 00/00/00
EPA ID: Not reported
Comments: Not reported

A5
SSW
< 1/8
272 ft.
Higher

MOBIL SERVICE STATION

312 DEL MONTE
MONTEREY, CA 93940

HIST UST
U007193368
N/A

Site 5 of 5 in cluster A

UST HIST:

Facility ID: 38610
Tank Num: 1
Tank Capacity: 12000
Type of Fuel: PRODUCT
Leak Detection: UNLEADED
Contact Name: STEPHEN MOULTON
Total Tanks: 3
Facility Type: 2
Container Num: 1
Year Installed: 1982
Tank Construction: Not reported
Telephone: (408) 375-7555
Region: STATE
Other Type: Not reported

Facility ID: 38610
Tank Num: 2
Tank Capacity: 10000
Type of Fuel: PRODUCT
Leak Detection: Not Reported
Contact Name: STEPHEN MOULTON
Total Tanks: 3
Facility Type: 2
Container Num: 2
Year Installed: 1981
Tank Construction: Not reported
Telephone: (408) 375-7555
Region: STATE
Other Type: Not reported

Facility ID: 38610
Tank Num: 3
Tank Capacity: 8000
Type of Fuel: PRODUCT
Leak Detection: REGULAR
Contact Name: STEPHEN MOULTON
Total Tanks: 3
Facility Type: 2
Container Num: 3
Year Installed: 1981
Tank Construction: Not reported
Telephone: (408) 375-7555
Region: STATE
Other Type: Not reported

Map ID
Direction
Distance
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MAP FINDINGS

6
SE
< 1/8
420 ft.
Higher

PG&E
DEL MONTE / FIGUEROA
MONTEREY, CA 92184

Notify 65
HAZNET
N/A

HAZNET:
Genid: CAL00005328
Trepid: CAD003168728
Gen County: Monterey
Tel County: Stanislaus
Tons: 18 6900
Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: MOBIL
Telephone: (703) 846-5734
Mailing Address: PO BOX 142667
AUSTIN, TX 78714 - 2667

County: Monterey
Genid: CAL00005328
Trepid: CAD003168728
Gen County: Monterey
Tel County: Los Angeles
Tons: 0250
Category: Unspecified oil-containing waste
Disposal Method: Treatment, Tank
Contact: MOBIL
Telephone: (703) 846-5734
Mailing Address: PO BOX 142667
AUSTIN, TX 78714 - 2667

NOTIFY 65:
Data Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Incident Description: 92184

7
South
< 1/8
482 ft.
Higher

MONTEREY COUNTY GAS & ELECTRIC CO.
402-428 DEL MONTE
MONTEREY, CA 91016

Coal Gas
G000000972
N/A

COAL GAS SITE DESCRIPTION:
1905 Monterey Co. Gas and Electric Co. is located on the entire block between Ad na Streets,
south of Del Monte Street and north of Franklin Street. By 1912, s by Gas and Electric Co.
By 1925, site occupies entire block. By 1925, gas road site is storage for Pacific Gas and
Electric Co.

©Copyright 1983 Real Property Scan, Inc.

Map ID
Direction
Distance
Elevation (ft.)
Site

Database(s)
EPA ID Number

8
ESE
< 1/8
585 ft.
Higher

CATELLUS DEVELOPMENT CORPORATION
256 FIGUEROA
MONTEREY, CA 93940

HAZNET
810452726
N/A

HAZNET:
Gepaid: CAL0020888
Tepaid: CAD08087418
Gen County: Monterey
Tad County: 1
Tons: 1,456
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: CATELLUS DEVT CORP
Telephone: (000) 000-0000
Mailing Address: 201 MISSION ST
SAN FRANCISCO, CA 94105
County: Monterey

B9
ESE
< 1/8
611 ft.
Higher

CATELLUS DEVELOPMENT CORP
281 FIGUEROA ST.
MONTEREY, CA 93940

HAZNET
810457903
N/A

HAZNET:
Gepaid: CAC002140137
Tepaid: CAT080033861
Gen County: Monterey
Tad County: Los Angeles
Tons: 1.8
Category: Other organic solids
Disposal Method: Disposal, Land Fill
Contact: CATELLUS DEVELOPMENT CORP
Telephone: (415) 974-4507
Mailing Address: 201 MISSION ST. 2ND FLR
SAN FRANCISCO, CA 94105
County: Monterey

C10
SSW
< 1/8
632 ft.
Higher

AUTOMOTIVE CARE
WASHINGTON & FRANKLIN
MONTEREY, CA 93940

RCRIS-SOG
FINDS
HAZNET
1000335046
CAD081872381

Site 1 of 2 in cluster C

Map ID
Direction
Distance
Elevation (ft.)
Site

Database(s)
EPA ID Number

AUTOMOTIVE CARE (Continued)

1000335046

RCRIS:
Owner: FRANK CONTE
EPA ID: CAD081872381
Contact: ENVIRONMENTAL MANAGER
(408) 373-1534
Classification: Small Quantity Generator
Used Oil Recg: No
TSDF Activities: Not reported
Violation Status: No violations found

FINDS:
Other Potentially Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information System (RCRAINFO)

HAZNET:

Gepaid: CAD081872381
Tepaid: CAD008302903
Gen County: Monterey
Tad County: Los Angeles
Tons: 2710
Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Recycler
Contact: Not reported
Telephone: (000) 000-0000
Mailing Address: WASHINGTON & FRANKLIN
MONTEREY, CA 93940
County: Monterey

Gepaid: CAD081872381
Tepaid: CAD008302903
Gen County: Monterey
Tad County: Los Angeles
Tons: 5004
Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Not reported
Contact: Not reported
Telephone: (000) 000-0000
Mailing Address: WASHINGTON & FRANKLIN
MONTEREY, CA 93940
County: Monterey

B11
SE
< 1/8
656 ft.
Higher

RUBSO'S MARINE FUELING STATION
DEL MONTE / FIGUEROA
MONTEREY, CA

CA SLIC
8101539724
N/A

SLIC Region 3:
Entered into Database:
How Contamination Occurred:
Waterfired:
PROPS Mail:
Emergency Action Taken:

Not reported
ASSORTED
8.50
False
False

Map ID
Direction
Distance
Elevation (ft)
Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

8101539724

RUSCO'S MARINE FUELING STATION (Continued)

Unique Case Number: 2831
Date First Reported: Not reported
Person Who Reported Leak: Not reported
Who Reporting Party Represents: Not reported
Reporting Party's Address: Not reported
Operator: Not reported
Responsible Party Search Status: Not reported
Responsible Party: CATELLUS DEVELOPMENT CORPORATION
Responsible Party's Address: 201 MISSION ST SAN FRANCISCO CA 941052
Responsible Party Phone: JAMES ADAMS
Responsible Party PO Box: (415) 874-4500
Facility Phone: Not reported
Leak Site Cross Street: Not reported
Local Agency: Not reported
Primary Substance leaked: 8006819 GASOLINE/DIESEL
Quantity Leaked (Gall): Not reported
Date Leak Found: Not reported
How Leak Was Discovered: Not reported
Date Leak Stopped: Not reported
How Leak Was Discovered: Not reported
Lead Agency: Regional Board
Priority Level: Priority 1 (Top Priority)
Case Type: Other ground water affected
Facility Status: Post Remediation Action Monitoring
Abatement Method: GW CLEANUP
Staff Member: WNL
Date Case Given to Regional Board: Not reported
Cost Recovery: Not reported
Confirmation of Leak Date: Not reported
Preliminary Site Assessment Workplan Date: Not reported
Preliminary Site Assessment Began Date: Not reported
Pollution Characterization Began Date: Not reported
Remediation Plan Submitted Date: Not reported
Remedial Action Underway Date: 9/25/87
Post Remedial Action Monitoring Date: 11/13/90
Enforcement Action Taken: Not reported
Emergency Response Date: Not reported
Case Closed Date: Not reported
Significant Interim Remedial Actions: False
Basin Plan: MUN
Summary: FREE PRODUCT ENTERS STORM DRAIN AND IS DISCHARGED TO OCEAN

B12
SE
118
658 ft.
Higher
FIGUEROA ST / DEL MONTE
MONTREY, CA
Site 3 of 3 in cluster B

CHMIRS
S105630987
N/A

Map ID
Direction
Distance
Elevation (ft)
Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

5105630987

(Continued)

CHMIRS:
OES Control Number: 27814
DOT Hazard Class: Not Reported
Chemical Name: unknown alien
Extent of Release: Not reported
CAS Number: Not reported
Environmental Contamination: None Reported
Incident Date: Not reported
Time Completed: Not reported
Physical State Stored: Not reported
Physical State Released: Not reported
Release Unit: Not reported
Container Description: Not reported
Container Type: Not reported
Container Material: Not reported
Level Of Container: Not reported
Container Capacity: Not reported
Extent Of Release (code): Not reported
Agency Of Release (code): Not reported
Agency Incident Number: Not reported
OES Incident Number: 27814
Time Notified: Not reported
Surrounding Area: Not reported
Estimated Temperature: Not reported
Property Management: Not reported
More Than Two Substances Involved?: Not reported
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
Responding Agency Personnel # Of Injuries: Not reported
Responding Agency Personnel # Of Fatalities: Not reported
Resp. Agency Personnel # Of Decontaminated: Not reported
Other Number Of Decontaminated: Not reported
Other Number Of Injuries: Not reported
Other Number Of Fatalities: Not reported
Vehicle Make/Year: Not reported
Vehicle License Number: Not reported
Vehicle # of Number: Not reported
CA/DOT/PU/CIC/C Number: Not reported
Company Name: Not reported
Reporting Officer Name/ID: Not reported
Report Date: Not reported
Comments: Not reported
Facility Telephone Number: Not reported
Waterway Involved: Not reported
Spill Site: Not reported
Cleanup By: Not reported
Containment: Not reported
What Happened: YES
a sheen was reported seen by a citizen, mso s.t. called me and reported that
Date/Time: 4/78

Map ID
Direction
Distance
Elevation
Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

(Continued)

Evacuations:
Type: Not reported
Other: Not reported
Chemical 1: Not Reported
Chemical 2: Not Reported
Chemical 3: Not Reported

13
South
1/8-1/4
657 ft.
Higher

PACIFIC MOTOR SERVICE INC
389 ADAMS ST
MONTEREY, CA 93940

HAZNET
S100941537
N/A

HAZNET:

Geopid: CAD98204893
Trepid: CAD980618045
Gen County: Monterey
Tad County: Kern
Tons: .0000
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Transfer Station
Contact: WM WAYNE & CHERYLL L DAVID
Telephone: (408) 375-9571
Mailing Address: 550 E FRANKLIN STREET
MONTEREY, CA 93940
County: Monterey

Geopid: CAD98204893
Trepid: CAD009452657
Gen County: Monterey
Tad County: San Mateo
Tons: .0003
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: WM WAYNE & CHERYLL L DAVID
Telephone: (408) 375-9571
Mailing Address: 550 E FRANKLIN STREET
MONTEREY, CA 93940
County: Monterey

Geopid: CAD98204893
Trepid: CAD009452657
Gen County: Monterey
Tad County: San Mateo
Tons: .2818
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: WM WAYNE & CHERYLL L DAVID
Telephone: (408) 375-9571
Mailing Address: 550 E FRANKLIN STREET
MONTEREY, CA 93940
County: Monterey

Map ID
Direction
Distance
Elevation
Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

PACIFIC MOTOR SERVICE INC (Continued)

Geopid: CAD98204893
Trepid: Not reported
Gen County: Monterey
Tad County: Monterey
Tons: 0
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: WM WAYNE & CHERYLL L DAVID
Telephone: (408) 375-9571
Mailing Address: 550 E FRANKLIN STREET
MONTEREY, CA 93940
County: Monterey

Geopid: CAD98204893
Trepid: CAT08025711
Gen County: Monterey
Tad County: San Bernardino
Tons: .2293
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Not reported
Contact: WM WAYNE & CHERYLL L DAVID
Telephone: (408) 375-9571
Mailing Address: 550 E FRANKLIN STREET
MONTEREY, CA 93940
County: Monterey

The CA HAZNET database contains 7 additional records for this site.
Please contact your EDR Account Executive for more information.

D14
WNV
1/8-1/4
666 ft.
Higher

1X CITY OF MONTEREY
1 PORTOLA PLAZA
MONTEREY, CA 93940
Site 1 of 4 in cluster D

HAZNET
S104565275
N/A

HAZNET:
Geopid: CAC001071088
Trepid: NYN200000044
Gen County: Monterey
Tad County: Monterey
Tons: 2.0530
Category: Polychlorinated biphenyls and material containing PCB's
Disposal Method: Recycler
Contact: CITY OF MONTEREY
Telephone: (000) 000-0000
Mailing Address: 1 PORTOLA PLAZA
MONTEREY, CA 93940
County: Monterey

Map ID
Direction
Distance
Elevation
Site

Database(s)
EDR ID Number
EPA ID Number

1X CITY OF MONTEREY (Continued)

Geopaid: CAC001071088
Tepaid: NYN20000044
Gen County: Monterey
Tsd County: 0
Tons: .0000
Category: Treatment, Incineration
Disposal Method: City of Monterey
Contact: (000) 000-0000
Telephone: 1 PORTOLA PLAZA
Mailing Address: MONTEREY, CA 93940
County: Monterey

D15
WNW
1/8-1/4
666 ft.
Higher

HAZNET
8103619465
N/A

Site 2 of 4 in cluster D

HAZNET:
Geopaid: CAC000878880
Tepaid: CAT080022146
Gen County: Monterey
Tsd County: San Bernardino
Tons: 8255
Category: Liquids with polychlorinated biphenyls > 50 mg/l
Disposal Method: Transfer Station
Contact: Not reported
Telephone: (000) 000-0000
Mailing Address: 1 PORTOLA PLAZA
MONTEREY, CA 00000
County: Monterey

D16
WNW
1/8-1/4
666 ft.
Higher

HAZNET
8103685285
N/A

Site 3 of 4 in cluster D

HAZNET:
Geopaid: CAC000745472
Tepaid: CAC000084517
Gen County: Monterey
Tsd County: Sacramento
Tons: 4587
Category: Photocemical/photoprocessing waste
Disposal Method: Transfer Station
Contact: FUJI PHOTO FILM USA INC
Telephone: (000) 000-0000
Mailing Address: 555 TAXTER RD
ELMSFORD, NY 10523
County: Monterey

Map ID
Direction
Distance
Elevation
Site

Database(s)
EDR ID Number
EPA ID Number

D17
WNW
1/8-1/4
666 ft.
Higher

HAZNET
8103687130
N/A

CITY OF MONTEREY - MONTEREY CONFERENCE

Geopaid: CAC001160880
Tepaid: CAL000027741
Gen County: Monterey
Tsd County: 5
Tons: 2,107
Category: Asbestos-containing waste
Disposal Method: Disposal, Land Fill
Contact: CITY OF MONTEREY
Telephone: (000) 000-0000
Mailing Address: 1 PORTOLA PLAZA
MONTEREY, CA 93940
County: Monterey

C18
SSW
1/8-1/4
696 ft.
Higher

HAZNET
8103681828
N/A

PHOTO DRIVE UP

Geopaid: CAL000135387
Tepaid: CAL000121846
Gen County: Monterey
Tsd County: Marin
Tons: 4378
Category: Photocemical/photoprocessing waste
Disposal Method: Recycler
Contact: DAVID LLOYD
Telephone: (000) 000-0000
Mailing Address: 408 WASHINGTON STREET #100
MONTEREY, CA 93940
County: Monterey

MAP FINDINGS

Map ID	Direction	Distance	Elevation	Site	Database(s)	EOR ID Number	EPA ID Number

PHOTO DRIVE UP (continued)

Gapaid: CAL000135367
 Trepid: CAL000121946
 Gen County: Monterey
 Tied County: Marin
 Tons: 1,4134
 Category: Photochemical/photocrosslinking waste
 Disposal Method: Recycler
 Contact: DAVID LLOYD
 Telephone: (000) 000-0000
 Mailing Address: 408 WASHINGTON STREET #100
 MONTEREY, CA 83940
 County: Monterey
 Gapaid: CAL000135367
 Trepid: CAL000383592
 Gen County: Monterey
 Tied County: Santa Clara
 Tons: 07050
 Category: Metal sludge - Alkaline solution (pH <12.5 with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, sodium, vanadium, and zinc)
 Disposal Method: Recycler
 Contact: DAVID LLOYD
 Telephone: (000) 000-0000
 Mailing Address: 408 WASHINGTON STREET #100
 MONTEREY, CA 83940
 County: Monterey
 Gapaid: CAL000135367
 Trepid: CAL000383592
 Gen County: Monterey
 Tied County: Santa Clara
 Tons: 2293
 Category: Photochemical/photocrosslinking waste
 Disposal Method: Recycler
 Contact: DAVID LLOYD
 Telephone: (000) 000-0000
 Mailing Address: 408 WASHINGTON STREET #100
 MONTEREY, CA 83940
 County: Monterey

19
 SSE
 1/8-1/4
 704 ft.
 Higher

NOTIFY 65:
 Date Reported: Not reported
 Board File Number: Not reported
 Facility Type: Not reported
 Discharge Date: Not reported
 Incident Description: 82184

Notify 65 \$100177985
 N/A

MAP FINDINGS

Map ID	Direction	Distance	Elevation	Site	Database(s)	EOR ID Number	EPA ID Number

E20
 ESE
 1/8-1/4
 837 ft.
 Higher
 PACIFIC HEATING & PLUMBING CO.
 554 DEL MONTE AVE
 MONTEREY, CA 83940
 Site 1 of 2 in cluster E

CA FID UST
 \$101622888
 N/A

E21
 ESE
 1/8-1/4
 837 ft.
 Higher
 PACIFIC HEATING & PLUMBING CO.
 554 DEL MONTE AVE
 MONTEREY, CA 83940
 Site 2 of 2 in cluster E

HIST UST
 U0515833689
 N/A

UST HIST:
 Facility ID: 42049
 Tank Num: 1
 Tank Capacity: 0
 Tank Used for: PRODUCT
 Type of Fuel: Not Reported
 Leak Detection: None
 Contact Name: FRED SCHERPINSKI
 Total Tanks: 2
 Facility Type: 2
 Facility ID: 42049
 Tank Num: 2
 Tank Capacity: 1000
 Tank Used for: PRODUCT
 Type of Fuel: REGULAR
 Leak Detection: None
 Contact Name: FRED SCHERPINSKI
 Total Tanks: 2
 Facility Type: 2
 Container Num: 2
 Year Installed: 1941
 Tank Construction: Not reported
 Telephone: (408) 372-3102
 Region: STATE
 Other Type: PLUMBING & HEATING

22
 WSW
 1/8-1/4
 816 ft.
 Higher
 MARIOTT MONTEREY
 350 CALLE PRINCIPAL
 MONTEREY, CA 83940

HAZNET
 \$102588596
 LUST
 N/A

State LUST:
 Cross Street: Not reported
 City/Land: Not reported
 Case Number: 2784
 Reg Board: Central Coast Region
 District: Central Coast Region
 Local Agency: Local Agency
 Lead Agency: 27700
 Case Type: Other ground water affected
 Status: Case Closed
 County: Monterey
 Abate Method: Excesses and Treat - remove contaminated soil and treat (includes spreading or land farming)
 Review Date: Not reported
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: Not reported
 Confirm Leak: Not reported
 Prelim Assess: Not reported
 Remed Plan: Not reported
 Monitoring: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Date(s)
EPA ID Number

5102509596

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Date(s)
EPA ID Number

5102509596

MARRIOTT MONTEREY (Continued)

Cose Date: 10/1/1992
Release Date: 12/10/1996
Cleanup Fund Id: Not reported
Discover Date: 1/1/1985
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 1/6/1997
Funding: 0
Staff Initials: UST
How Discovered: Tank Closure
How Stopped: Not reported
Interim: No
Leak Cause: UNK
Leak Source: UNK
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE includes Unknown and Not Analyzed.
Priority: Not reported
Local Case #: Not reported
Borehole: Not reported
Staff: Not reported
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hyd Basin #: 9.50
Overnight Pgm: Not reported
Overnight Pgm: RSL Lead Underground Storage Tank
Release Date: Not reported
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
PP Address: Not reported
Global ID: T060530170
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mbs Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Last: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 3:
Case Number: 2784
Cross Street: Not reported
Responsible Party: Not reported
Local Agency: 03
Discover Date: 01/01/1985
How Found: Tank Closure
Source: Other
Cause: UNK
Lead Agency: Local Agency
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey

Release Date: 12/10/1996
Enter Date: 1/6/97
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported

Staff Initials: HDC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Date(s)
EPA ID Number

5102509596

MARRIOTT MONTEREY (Continued)

Review Date: Not reported
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Type: Not reported
Enforce Date: / /
Interim Action: 0
Mbs Concentration: / /
Mbs Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Date: / /
MTBE Tested: NT
Lat/Long: 36.800583 / -121.88486
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: Not reported

HAZNET:
Genid: CAC001053024
Trepid: CAD003168728
Gen County: Monterey
Trel County: Stanislaus
Tone: 3127
Category: Unspecified oil-containing waste
Disposal Method: SAN CARLOS ASSOCIATES
Contact: (000) 000-0000
Telephone: 360 CALLE PRINCIPAL
Mailing Address: MONTEREY, CA 93940
County: Monterey

Funding: 0
Workplan: / /
Pollution Char: / /
Remedial Action: / /
Close Date: 10/01/1992
Pilot Program: UST
Region: 3

F23
SSE
108-114
954 ft.
Higher

COCHRAN AUTOSHOP SITE

417 FIGUEROA ST
MONTEREY, CA

Site 1 of 2 in cluster F

Site LUST:
Cross Street: Not reported
City Leased: Not reported
Case Number: 514
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Case Closed
County: Monterey
Asate Method: U
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Action: Not reported
Close Date: 3/25/1992

LUST
5102428195
Contase
N/A

Confirm Leak: Not reported
Prelim Assess: Not reported
Remedial Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Elevation
Site

MAP FINDINGS

Database(s)
EPA ID Number
EDR ID Number

COCHRAN AUTOSHOP SITE (Continued)

5102428195

Release Date: 12/19/1988
Cleanup Fund ID: Not reported
Discover Date: 1/1/1985
Enforcement Dt: Not reported
EPA Type: Not reported
Enter Date: 2/25/1989
Funding: Not reported
Staff Initials: UST
How Discovered: OK
How Stopped: Not reported
Infirm: Not reported
Leak Source: UNK
Leak Status: UNK
MTBE Data: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT tested for MTBE includes Unknown and Not Analyzed
Priority: Low priority, Priority ranking can change over time.
Local Case #: Not reported
Specific: Not reported
Staff: JWG
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hyd Basin #: 9.50
Operator: Not reported
Oversight Pgm: RB, Lead Underground Storage Tank
Review Date: 3/25/1992
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party/Not reported
RP Address: TDB0300319
Global ID: Not reported
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mile Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Last: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Release Date: 12/19/1988
Enter Date: 2/25/89
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported
Cause: UNK
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey
Review Date: 3/25/82
Staff Initials: JWG
Funding: Not reported

Map ID
Direction
Distance
Elevation
Site

MAP FINDINGS

Database(s)
EPA ID Number
EDR ID Number

COCHRAN AUTOSHOP SITE (Continued)

5102428195

Confirm Leak: / /
Palm Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Type: Not reported
Enforce Date: / /
Infirm Action: 0
Mile Concentration: / /
Mile Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Data: / /
MTBE Tested: NT
Lat/Long: 36.590061 / -121.880048
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: NO USEABLE WATER RESOURCES AFFECTED. CASE DELEGATED TO CONTY HEALTH DEPARTMENT 5/13/92.

CORTESE: 514
Reg ID: CORTESE
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

G24
SSW
108-1/4
980 ft.
Higher

KITTY HAWK, ET AL
431 TYLER ST
MONTEREY, CA 83940

HAZNET: 5102428195
Gepaid: CAC001141976
Tepaid: CAD009466392
Gen County: Monterey
Ted County: 7
Tons: 1,1000
Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Contact: KITTY HAWK, ET AL
Telephone: (000) 000-0000
Mailing Address: 80 GARDEN CT
MONTEREY, CA 83940

County: Monterey
Gepaid: CAC001141976
Tepaid: NYD082356483
Gen County: Monterey
Ted County: 98
Tons: 6.8720
Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: KITTY HAWK, ET AL
Telephone: (000) 000-0000
Mailing Address: 80 GARDEN CT
MONTEREY, CA 83940
County: Monterey

Map ID
Direction
Distance
Elevation
Site

Database(s)
EPA ID Number

625
SW
1/8-1/4
1023 ft.
Higher

RAINBOW CLEANERS
288 BONIFACIO
MONTEREY, CA 93940
Site 2 of 2 in cluster G

RCRIS:

Owner: DON KEARNS
EPA ID: CAD981579493
Contact: ENVIRONMENTAL MANAGER
(408) 373-6743

Classification: Small Quantity Generator
Used Oil Recg: No
TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
National Toxics Inventory (NTI)
Resource Conservation and Recovery Act Information System (RCRAINFO)

CA Cleaners:

Create Date: 04/10/1987
Inactive Date: 0
EPA ID: CAD981579493
County: Monterey

Create Date: 02/27/1985
Inactive Date: 04/30/1988
EPA ID: CAX000201459
County: Monterey

HAZNET:

Geopid: CAD981579493
Trepid: CAX000084517
Gen County: Monterey
Tsd County: Sacramento

Tons: .7575

Category: Liquids with halogenated organic compounds > 1000 mg/l

Disposal Method: Transfer Station

Contact: DON KEARNS

Telephone: (408) 373-6435

Mailing Address: 288 BONIFACIO PL
MONTEREY, CA 93940 - 3042

County: Monterey

Geopid: CAD981579493

Trepid: CAX000084517

Gen County: Monterey

Tsd County: 0

Tons: .0800

Category: Liquids with halogenated organic compounds > 1000 mg/l

Disposal Method: Transfer Station

Contact: DON KEARNS

Telephone: (408) 373-6435

Mailing Address: 288 BONIFACIO PL
MONTEREY, CA 93940 - 3042

Map ID
Direction
Distance
Elevation
Site

Database(s)
EPA ID Number

RAINBOW CLEANERS (Continued)

1000307859

County: Monterey
Geopid: CAD981579493
Trepid: CAT000613850
Gen County: Monterey
Tsd County: Sacramento
Tons: .0800
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Transfer Station
Contact: DON KEARNS
Telephone: (408) 373-6435
Mailing Address: 288 BONIFACIO PL
MONTEREY, CA 93940 - 3042

County: Monterey
Geopid: CAD981579493
Trepid: CAX000084517
Gen County: Monterey
Tsd County: Sacramento
Tons: .8475
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Transfer Station
Contact: DON KEARNS
Telephone: (408) 373-6435
Mailing Address: 288 BONIFACIO PL
MONTEREY, CA 93940 - 3042

County: Monterey
Geopid: CAD981579493
Trepid: CAT000613850
Gen County: Monterey
Tsd County: Sacramento
Tons: .5325
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Transfer Station
Contact: DON KEARNS
Telephone: (408) 373-6435
Mailing Address: 288 BONIFACIO PL
MONTEREY, CA 93940 - 3042

County: Monterey
Geopid: CAD981579493
Trepid: CAT000613850
Gen County: Monterey
Tsd County: Los Angeles
Tons: .5325
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Transfer Station
Contact: DON KEARNS
Telephone: (408) 373-6435
Mailing Address: 288 BONIFACIO PL
MONTEREY, CA 93940 - 3042

The CA HAZNET database contains 8 additional records for this site.
Please contact your EDR Account Executive for more information.

H2S
NW
1/8-1/4
1025 ft.
Higher

TRAFFIC UNDERPASS
149 OLIVER ST
MONTEREY, CA 93940
Site 1 of 2 in cluster H

UST HIST:

Facility ID: 56583
Tank Num: 1
Tank Capacity: 80
Type of Fuel: DIESEL
Leak Detection: Visual
Contact Name: B. W. RUHL, MECH. DIV. SUPT.
Telephone: (408) 946-3566

HIST UST
U001593710
N/A

MAP FINDINGS

Map ID
Direction
Distance
Elevation
Site

Database(s)
EPA ID Number
EDR ID Number

TRAFFIC UNDERPASS (Continued)

Total Tanks: 2
Facility Type: 2
Facility ID: 5663
Tank Num: 2
Tank Capacity: 1000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Liquor Disposal: Solid material
Contact Name: B.V. ROHL, MECH. DIV. SUPT.
Total Tanks: 2
Facility Type: 2

Region: STATE
Other Type: EMERGENCY GEN.
Container Num: 11
Year Installed: Not reported
Tank Construction: 123 inches
Telephone: (408) 946-3956
Region: STATE
Other Type: EMERGENCY GEN.

H17
NW
148 OLIVER ST
108-1/4
1025 ft.
Higher

TRAFFIC UNDERPASS
MONTEREY, CA 93940
Site 2 of 2 in cluster H

CA FID UID
S101622902
N/A

128
SE
148-1/4
1033 ft.
Higher

PACIFIC MOTOR SERVICE INC
550 E FRANKLIN STREET
MONTEREY, CA 93940
Site 1 of 3 in cluster I

HAZNET
S103844561
N/A

HAZNET:
Gepaid: CAL000028150
Tepaid: CAD008452657
Gen County: Monterey
Tad County: San Mateo
Tone: 4378
Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Contact: WM WAYNE & CHERYL L DANIEL
Telephone: (000) 000-0000
Mailing Address: 550 E FRANKLIN ST
MONTEREY, CA 93940
County: Monterey
Gepaid: CAL000028150
Tepaid: CAD008452657
Gen County: Monterey
Tad County: Santa Cruz
Tone: 4387
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Contact: WM WAYNE & CHERYL L DANIEL
Telephone: (000) 000-0000
Mailing Address: 550 E FRANKLIN ST
MONTEREY, CA 93940
County: Monterey

MAP FINDINGS

Map ID
Direction
Distance
Elevation
Site

Database(s)
EPA ID Number
EDR ID Number

PACIFIC MOTOR SERVICE INC (Continued)

Gepaid: CAL000028150
Tepaid: CAD008452657
Gen County: Monterey
Tad County: Los Angeles
Tone: 3065
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Not reported
Contact: WM WAYNE & CHERYL L DANIEL
Telephone: (000) 000-0000
Mailing Address: 550 E FRANKLIN ST
MONTEREY, CA 93940
County: Monterey

F28
SSE
148-1/4
1046 ft.
Higher

MONTEREY CUSTOM COLOR LAB
437 FIGUEROA STREET
MONTEREY, CA 93940
Site 2 of 2 in cluster F

HAZNET
S102819132
N/A

HAZNET:
Gepaid: CAL000112112
Tepaid: CAD003963592
Gen County: Monterey
Tad County: Santa Clara
Tone: 0500
Category: Other inorganic solid waste
Disposal Method: Recycler
Contact: CLARENCE HUELMERIK
Telephone: (949) 470-1257
Mailing Address: 777 VIA LOS ALTOS UNIT D
LAGUNA HILLS, CA 92653-3056
County: Monterey
Gepaid: CAL000112112
Tepaid: CAD003963592
Gen County: Monterey
Tad County: Santa Clara
Tone: 0700
Category: Metal sludge - Alkaline solution (pH <11.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, titanium, vanadium, and zinc)
Disposal Method: Recycler
Contact: CLARENCE HUELMERIK
Telephone: (949) 470-1257
Mailing Address: 777 VIA LOS ALTOS UNIT D
LAGUNA HILLS, CA 92653-3056
County: Monterey

Map ID
Direction
Distance
Elevation

Site

Database(s)

EDR ID Number
EPA ID Number

MAP FINDINGS

MONTEREY CUSTOM COLOR LAB (Continued)

5102819132

Geopaid: CAL000112112
Tepaid: CAD0003963592
Gen County: Monterey
Tad County: Santa Clara
Tons: 1500
Category: Metal sludge - Alkaline solution (pH <LN> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)
Disposal Method: Recycler
Contact: CLARENCE HJELMERVIK
Telephone: (949) 476-1257
Mailing Address: 777 VIA LOS ALTOS UNIT D
LAGUNA HILLS, CA 92653 - 3056
County: Monterey
Geopaid: CAL000112112
Tepaid: CAD0003963592
Gen County: Monterey
Tad County: Santa Clara
Tons: 0750
Category: Metal sludge - Alkaline solution (pH <LN> 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)
Disposal Method: Recycler
Contact: CLARENCE HJELMERVIK
Telephone: (949) 476-1257
Mailing Address: 777 VIA LOS ALTOS UNIT D
LAGUNA HILLS, CA 92653 - 3056
County: Monterey
Geopaid: CAL000112112
Tepaid: CAD0003963592
Gen County: Monterey
Tad County: Santa Clara
Tons: 0375
Category: Other inorganic solid waste
Disposal Method: Recycler
Contact: CLARENCE HJELMERVIK
Telephone: (949) 476-1257
Mailing Address: 777 VIA LOS ALTOS UNIT D
LAGUNA HILLS, CA 92653 - 3056
County: Monterey

30
South
1/8-1/4
1079 ft.
Higher

JACK FOX AUTO SVC
485 WASHINGTON & PEARL
MONTEREY, CA 93940

RCRIS-SQG 1009286477
FINDS CAD981434012

Map ID
Direction
Distance
Elevation

Site

Database(s)

EDR ID Number
EPA ID Number

MAP FINDINGS

JACK FOX AUTO SVC (Continued)

1009286477

RCRIS:
Owner: RICHARD L. LESHER
(415) 555-1212
EPA ID: CAD981434012
Contact: ENVIRONMENTAL MANAGER
(408) 375-2816
Classification: Small Quantity Generator
Used Oil Recycle: No
TSDF Activities: Not reported
Violation Status: No violations found
FINDS:
Other Potentially Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information System (RCRAINFO)

131
SE
1/8-1/4
1095 ft.
Higher

SHERWIN WILLIAMS
571 E. FRANKLIN ST
MONTEREY, CA 93940

HAZNET 5103987795
N/A

HAZNET:
Geopaid: CAC001485128
Tepaid: CAD000088262
Gen County: Monterey
Tad County: Los Angeles
Tons: 1042
Category: Unspecified solvent mixtures waste
Disposal Method: Transfer Station
Contact: SHERWIN WILLIAMS
Telephone: (209) 456-3701
Mailing Address: 571 E. FRANKLIN ST
MONTEREY, CA 93940
County: Monterey

132
SE
1/8-1/4
1096 ft.
Higher

MAIORANA FAMILY PARTNERSHIP
571 EAST FRANKLIN STREET
MONTEREY, CA 93940

HAZNET 5103976033
N/A

HAZNET:
Geopaid: CAC001006232
Tepaid: CAD981398962
Gen County: Monterey
Tad County: Shasta
Tons: 0500
Category: Asbestos-containing waste
Disposal Method: Disposal, Land Fill
Contact: MAIORANA FAMILY PARTNERSHIP
Telephone: (000) 000-0000

MAP FINDINGS

Map ID
Direction
Distance (ft)
Elevation

EDR ID Number
EPA ID Number

MAIORANA FAMILY PARTNERSHIP (Continued)

Mailing Address: 58 EL CAMINITO DEL NORTE
MONTEREY, CA 93940
County: Monterey

Site 1039708033

J23
SE
118-1/4
1183 ft.
Higher

ATAIDE GENERAL TIRE

591 E FRANKLIN STREET
MONTEREY, CA 93940
Site 1 of 5 in cluster J

HAZNET
5102812554
N/A

HAZNET:

Geopaid: CAL000043904
Tepaid: CAD083459485
Gen County: Monterey
Tad County: Fresno
Tons: 0332
Category: Unspecified solvent mixture Waste
Disposal Method: Transfer Station
Contact: ATAUDE MEL OWNER
Telephone: (000) 000-0000
Mailing Address: 591 E FRANKLIN ST
MONTEREY, CA 93940 - 3010

County:

Geopaid: CAL000043904
Tepaid: CAD083459485
Gen County: Monterey
Tad County: Fresno
Tons: 0332

Category:

Unspecified solvent mixture Waste
Disposal Method: Transfer Station
Contact: ATAUDE MEL OWNER
Telephone: (000) 000-0000
Mailing Address: 591 E FRANKLIN ST
MONTEREY, CA 93940 - 3010

County:

Geopaid: CAL000043904
Tepaid: CAD083459485
Gen County: Monterey
Tad County: Fresno
Tons: 0332

Category:

Aqueous solution with less than 10% total organic residues
Disposal Method: Transfer Station
Contact: ATAUDE MEL OWNER
Telephone: (000) 000-0000
Mailing Address: 591 E FRANKLIN ST
MONTEREY, CA 93940 - 3010

County:

Monterey

J24
SE
118-1/4
1218 ft.
Higher

ROSSIS TIRE AND AUTO SERVICE

588 E FRANKLIN
MONTEREY, CA 93905
Site 2 of 5 in cluster J

HAZNET
5105722441
N/A

MAP FINDINGS

Map ID
Direction
Distance (ft)
Elevation

EDR ID Number
EPA ID Number

ROSSIS TIRE AND AUTO SERVICE (Continued)

Site 5105722441

HAZNET:
Geopaid: CAL000029805
Tepaid: CAT080013352
Gen County: Monterey
Tad County: Los Angeles
Tons: 0.2
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: FRANK MCCALLUM
Telephone: (831) 424-3441
Mailing Address: 81 N SANBORN RD
SALINAS, CA 93905
County: Monterey

J25
SE
118-1/4
1218 ft.
Higher

BIANCHI SITE

600 FRANKLIN ST E
MONTEREY, CA 93940
Site 3 of 5 in cluster J

State LUST:

Cross Street: ANTHONY
City Leaked: Not reported
Case Number: 647
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Case Closed
County: Monterey

Able Method:

Excavate and Dispose - remove contaminated soil and dispose in approved site

Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 6/6/1990
Release Date: 12/6/1988
Cleanup Fund ID: Not reported
Discover Date: 1/1/1986
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 2/25/1989
Funding: Not reported
Staff initials: UST
How Discovered: OMI
How Stopped: Not reported
Interim: No
Leak Cause: UNK
Leak Source: UNK
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not reported
Site NOT Tested for MTBE includes Unknown and Not Analyzed
Priority: Low priority. Priority ranking can change over time
Local Case #: Not reported

LUST
5102423229
Corfesse
N/A

Map ID
Direction
Distance (ft.)
Elevation

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BLANCH SITE (Continued)

Beneficial: Not reported
Staff: JWG
SUV Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hyd Blank #: 930
Overhead: Not reported
Overhead Pgm: BL Lead Underground Storage Tank
Overhead Pgm: UST
Release Date: 22/4/1989
Stop Date: 10/25/1989
Work Suspended: Not reported
Responsible Party/STATE
RP Address: 801 GARDEN STREET - SUITE 201
Global ID: T060300304
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Misc Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 3:
Case Number: 847
Cross Street: ANTHONY
Responsible Party/STATE
Local Agency: 03
Discovered: 01/01/1985
How Found: Not reported
Source: Other
Cause: UNK
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey
Review Date: 22/4/89
Confirm Leak: //
Prelim Assess: //
Remedial Plan: //
Monitoring: 22/4/89
Efficacy Type: Not reported
Efficacy Date: //
Interim Action: 0
Media Concentration: //
Media Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
MTBE Tested: //
Lab/Long: 36.5964141 / -121.8925375
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: THIS CASE IS CLOSED

Release Date: 12/06/1989
Enter Date: 22/5/89
Regional Board: Central Coast Region
Stop Date: 10/25/89
How Stopped: Not reported

Staff Initials: JWG
Funding: Not reported
Workplan: //
Pollution Char: //
Remedial Action: //
Close Date: 06/06/1990
Pilot Program: UST
Region: 3

Map ID
Direction
Distance (ft.)
Elevation

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BLANCH SITE (Continued)

CORTESE
Reg ID: 847
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

J35
SE
1/8-1/4
1218 ft.
Higher

H AND B PROPERTIES
600 E FRANKLIN ST
MONTEREY, CA 93940

Site 4 of 5 in cluster J

UST HIST:
Facility ID: 56273
Tank Num: 1
Tank Capacity: 0
Tank Used for: PRODUCT
Type of Fuel: Not Reported
Leak Detection: None
Contact Name: Not reported
Total Tanks: 1
Facility Type: 2

Container Num: 1
Year Installed: Not reported
Tank Construction: Not reported
Telephone: (408) 394-6465
Region: STATE
Other Type: REAL ESTATE

J37
SE
1/8-1/4
1218 ft.
Higher

MACKENZIE SILVE PARTNERSHIP
600 E FRANKLIN
MONTEREY, CA 93940

Site 5 of 5 in cluster J

FID:
Facility ID: 27022177
Reg By: Active Underground Storage Tank Location
Contact Code: Not reported
Status: Active
Mail To: 800 E FRANKLIN
MONTEREY, CA 93940
Contact: Not reported
DUNA No: Not reported
Creation: 10/22/83
EPA ID: Not reported
Comments: Not reported

Regulate ID: 00056273
SIC Code: Not reported
Facility Tel: (408) 394-6465
Contact Tel: Not reported
NPDES No: Not reported
Modified: 0000000

K38
SW
1/8-1/4
1231 ft.
Higher

RUSSELLS CAMERA WEST
400 ALVARADO ST
MONTEREY, CA 93940

Site 1 of 2 in cluster K

RCRIS-606 1000883687
FINDS CA0893525443

Map ID
Direction
Distance
Elevation
Site

EDR ID Number
EPA ID Number
Database(s)

RUSSELL'S CAMERA WEST (Continued)

100985587

RCRS:

Owner: RUSCAM INC
(408) 848-0220
EPA ID: CAD83525443
Contact: ROBB HALLOCK
(408) 848-0220
Classification: Small Quantity Generator
Used Oil Recy: No
TSDF Activities: Not reported
Violation Status: No violations found

FINOS:

Other Potential Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

K39
SW
1/8-1/4
1231 ft.
Higher

HAZNET
810387458
N/A

HOME SAVINGS OF AMERICA
401 ALVARADO ST
MONTEREY, CA 93940
Site 2 of 2 in cluster K

HAZNET:

Genpaid: CAC001240889
Tepaid: NYD888980233
Gen County: Monterey
Tst County: 88
Tons: 4862
Category: Polychlorinated biphenyls and material containing PCB's
Disposal Method: Not reported
Contact: CORPORATION
Telephone: (800) 000-0000
Mailing Address: 401 ALVARADO ST
MONTEREY, CA 93940
County

L40
SSW
1/8-1/4
1243 ft.
Higher

LUST
8105025040
N/A

DOUGHERTY'S AUTO PAINT
228 PEARL ST (2)
MONTEREY, CA 93940
Site 1 of 3 in cluster L

State LUST:

Cross Street: HOUSTON ST
Qty Leaked: Not reported
Case Number: 8
Reg Board: Central Coast Region
Chemical: Solvents
Lead Agency: Local Agency
Local Agency: 27000
Case Type: Soil only
Status: Case Closed

Map ID
Direction
Distance
Elevation
Site

EDR ID Number
EPA ID Number
Database(s)

DOUGHERTY'S AUTO PAINT (Continued)

8105025040

County:

Monterey

Abate Method: U
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Close Date: 12/31/1989
Release Date: 6/21/1989
Cleanup Fund ID: Not reported
Discover Date: 1/1/1985
Enforcement DL: 1/1/1985
Enf Type: None Taken
Enter Date: 7/22/1989
Funding: Responsible Party
Staff Initials: UST
How Discovered: Tank Closure
How Stopped: Not reported
Infirm: No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not Required to be Tested
Priority: 0
Local Case #: Not reported
Beneficial: Not reported
Staff: JWG
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 8.50
Operator: Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Review Date: 2/24/1994
Stop Date: 6/21/1989
Work Suspended: Not reported
Responsible Party/Not reported
RP Address: Not reported
Global ID: T0905300377
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
MTBE Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Luel: 0
Waste Discharge Global ID: Not reported
Waste Dsch Assigned Name: Not reported

LUST Region 3:

Cross Street: 8
Case Number: HOUSTON ST
Responsible Party/Not reported
Local Agency: 108
Discover Date: 01/01/1985
How Found: Tank Closure
Source: Tank

Release Date: 08/21/1989
Enter Date: 7/22/89
Regional Board: Central Coast Region
Stop Date: 6/21/89
How Stopped: Not reported

Map ID
Direction
Distance (ft)
Elevation
Site
MAP FINDINGS
Database(s)
EPA ID Number
EPA ID Number

DOUGHERTY'S AUTO PAINT (Continued)

Cause: Structure Failure
Lead Agency: Solano
Case Type: Not reported
Contact: Not reported
Facility Status: Case Closed
Review Date: 2/24/04
Confirm Leak: /
Prelim Assess: /
Remedial Plan: /
Monitoring: Not reported
Enforce Type: None Taken
Enforce Date: 01/01/1995
Interim Action: 0
Mile Concentration: 0
Mile Fuel: 0
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
MTBE Data: /
MTBE Tested: NRO
Lat/Long: 38.687231 / -121.8832489
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: NO WATER SEE PAGE BUT EVIDENCE OF WATER AT 8 FEET SAMPLE TAKEN.
CORTESE:
Reg id: 8
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

L41
SSW
118-1/4
1288 ft.
Higher
SAUCITO LAND CO
488 WASHINGTON
MONTEREY, CA 93940
Site 2 of 3 in cluster L

HAZNET
510398847
N/A

HAZNET:
Geopaid: CAC001407528
Tepaid: CAD882042475
Gen County: Monterey
Tad County: Solano
Tone: 4.2140
Category: Asbestos-containing waste
Disposal Method: Disposal, Land Fill
Contact: SAUCITO LAND COMPANY
Telephone: (000) 000-0000
Mailing Address: 480 WASHINGTON
MONTEREY, CA 93940
County: Monterey

Map ID
Direction
Distance (ft)
Elevation
Site
MAP FINDINGS
Database(s)
EPA ID Number
EPA ID Number

DOUGHERTY'S AUTO PAINT

Cross Street: HOUSTON ST
Qty Leaked: Not reported
Case Number: 2886
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency: 27000
Case Type: Sol only
Status: Case Closed
County: Monterey
Apella Method: U
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Case Date: 12/31/1989
Release Date: 5/4/1988
Cleanup Fund id: Not reported
Discover Date: 1/1/1985
Enforcement Dt: 1/1/1985
Ent Type: None Taken
Enter Date: 7/22/1989
Funding: Responsible Party
Staff Initials: UST
How Discovered: Tank Closure
How Stopped: Not reported
Interim: No
Leak Cause: Overfill
Leak Source: UNK
MTBE Data: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE includes Unknown and Not Analyzed.
Priority: 0
Local Case #: Not reported
Beneficial: Not reported
Staff: JWG
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 9.50
Operator: Not reported
Oversight Pgm: RB Land Underground Storage Tank
Oversight Pgm: UST
Review Date: 2/24/1994
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
RP Address: Not reported
Global id: T0805300148
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0

L42
SSW
118-1/4
1288 ft.
Higher
DOUGHERTY'S AUTO PAINT
288 PEARL ST (S)
MONTEREY, CA 93942
Site 3 of 3 in cluster L

LUST
5102428925
N/A

Map ID
Direction
Distance (ft)
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MAP FINDINGS

DOUGHERTY'S AUTO PAINT (Continued)

Map ID: 1
Direction: Not reported
Distance (ft): 0
Elevation: Not reported
Site: Not reported
Database(s): Not reported
EDR ID Number: Not reported
EPA ID Number: Not reported

Release Date: 05/04/1989

Enter Date: 7/22/89

Regional Board: Central Coast Region

Stop Date: Not reported

How Stopped: Not reported

Staff Initials: JWG

Funding: Responsible Party

Workplan: / /

Pollution Char: / /

Remedial Action: / /

Close Date: 12/31/1989

Pilot Program: UST

Region: 3

Case Number: 2886
Case Street: HOUSTON ST
Responsible Party/Not reported
Local Agency: 03
Discovered: 01/01/1986
How Found: Tank Closure
Source: Other
Cause: Overfill
Lead Agency: Local Agency
Case Type: Soil only
Contact: Not reported
Facility Status: Case Closed
Review Date: 2/24/94
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Type: None Taken
Enforce Date: 01/01/1986
Interim Action: 0
MTBE Concentration: 1
MTBE Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: / /
MTBE Data: / /
MTBE Tested: NT
Lat/Long: 36.5977231 / -121.8932499
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: Not reported

SAUCITO LAND CO
488 WASHINGTON ST
MONTEREY, CA 93940

HAZNET 8102783706

N/A

HAZNET:
CASID: CAC000739704
TSPID: CAD982042475
Gen County: Monterey
Tid County: D
TSPID: 27300
Category: Asbestos-containing waste
Disposal Method: Not reported
Contact: SAUCITO LAND CO INC
Telephone: (800) 000-0000

Map ID
Direction
Distance (ft)
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MAP FINDINGS

SAUCITO LAND CO (Continued)

Mailing Address: 488 WASHINGTON ST
MONTEREY, CA 93940
County: Monterey
Geopid: CAC000739704
TSPID: CAD982042475
Gen County: Monterey
Tid County: D
TSPID: 27300
Category: Asbestos-containing waste
Disposal Method: Landfill
Contact: SAUCITO LAND CO INC
Telephone: (800) 000-0000
Mailing Address: 488 WASHINGTON ST
MONTEREY, CA 93940
County: Monterey

8102783706

44
SW
114-112
1371 ft.
Higher

CALIFORNIA BANK TRUST
488 WASHINGTON ST.
MONTEREY, CA 93940

LUST 8105620266

N/A

State LUSTR:
Cross Street: TYLER
Qty Leaked: Not reported
Case Number: 3448
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Not reported
County: Monterey
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Action: Not reported
Close Date: Not reported
Release Date: 7/28/2002
Cleanup Fund ID: Not reported
Discover Date: 7/28/2002
Enforcement DI: Not reported
Enf Type: Not reported
Enter Date: Not reported
Funding: Not reported
Staff Initials: SAS
How Discovered: Close Tank
Interim: Not reported
Leak Cause: UNK
Leak Source: UNK
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE includes Unknown and Not Analyzed.
Priority: Not reported
Local Case #: Not reported

Map ID
Direction
Distance (ft)
Elevation
Site
Database(s)
EPA ID Number
EPA ID Number

CALIFORNIA BANK TRUST (Continued)

Beneficial: Not reported
Staff: WNL
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hyd Basin #: Not reported
Operator: Not reported
Oversight Prgm: Not reported
Review Date: Not reported
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party/VICTORIA UNDERWOOD CALIFORNIA BANK
RP Address: 300 LAKESIDE DR. 8 WEST
Global ID: 10805347152
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
MTBE Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Leach: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
LUST Region 3:
Case Number: 3448
Cross Street: TYLER
Responsible Party/VICTORIA UNDERWOOD CALIFORNIA BANK
Local Agency: 03
Discovered: 07/28/2002
How Found: CT
Source: Other
Cause: UNK
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Monterey
Confirm Date: Not reported
Review Date: Not reported
Prelim Assess: Not reported
Remedial Plan: Not reported
Monitoring: Not reported
Enforce Type: Not reported
Enforce Date: Not reported
Interim Action: Not reported
Miles Concentration: 1
Mile Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Data: Not reported
MTBE Tested: NT
Lat/Long: 0/0
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: Not reported

Map ID
Direction
Distance (ft)
Elevation
Site
Database(s)
EPA ID Number
EPA ID Number

45
NNE
1/4-1/2
1388 ft
Same
ROYAL SEAFOODS, COMMERCIAL WHARF
MONTEREY, CA 93940

CHMIRS:
OES Control Number: 8904983
DOT Hazard Class: DOT ID: 1005
Chemical Name: AMMONIUM ANHYDROUS
Extrat of Release: Not reported
CAS Number: 7664417
Environmental Contamination: Air
Incident Date: 21-FEB-89
Time Completed: 22-FEB-89
Physical State Stored: 1830
Physical State Released: Liquid
Release Unit: Cu. Ft
Container Description: 1
Container Type: 01
Container Material: Undetermined
Level Of Container: 10
Container Capacity: 200
Extrat Of Release (code): Cu. Ft
Agency Id Number: 27704
Agency Incident Number: 86-0013
OES Incident Number: 8604983
Time Notified: 1515
Surrounding Area: 942
Estimated Temperature: 70
Property Management: C
More Than Two Substances Involved: Not reported
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
Responding Agency/Personnel # Of Injuries: 0
Responding Agency/Personnel # Of Fatalities: 0
Resp Agency Personnel # Of Decontaminated: 0
Others Number Of Decontaminated: 0
Others Number Of Injuries: 0
Others Number Of Fatalities: 0
Vehicle Make/year: Not reported
Vehicle License Number: Not reported
Vehicle State: Not reported
Vehicle Id Number: Not reported
CADOT/PUC/ICC Number: Not reported
Company Name: Not reported
Reporting Officer Name/ID: JAMES G. FLAREY
Report Date: 22-FEB-89
Comments: Not reported
Facility Telephone Number: 408 755-4511
Waterway Involved: Not reported
Waterway: Not reported
Spill Site: Not reported
Cleanup By: Not reported

Map ID
Direction
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number
EPA ID Number

(Continued)

Containment: Not reported
What Happened: Not reported
Date/Time: Not reported
Evacuations: Not reported
Type: Not reported
Other: Not reported
Chemical 1: Not Reported
Chemical 2: Not Reported
Chemical 3: Not Reported

1000371821

46
SSW
14-1/2
1478 ft.
Higher

RCRIS-SQG
FINDS
HAZNET
LUST

RCRIS:

Owner: NOT REQUIRED

EPA ID: (415) 555-1212

CA005286995

Contact: ENVIRONMENTAL MANAGER

(219) 566-3098

Classification: Small Quantity Generator

Used Oil Recy: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Facility Registry System (FRS)

Resource Conservation and Recovery Act Information system (RCRANFIO)

State LUST:

Cross Street: PEARL ST

City/County: Not reported

Case Number: 2521

Reg Board: Central Coast Region

Chemical: Mineral Spills

Lead Agency: Regional Board

Local Agency: 27000

Case Type: Other ground water affected

Status: Leak being confirmed

County: Monterey

Asble Method: U

Review Date: 1/12/1995

Workplan: Not reported

Pollution Char: Not reported

Remed Action: Not reported

Case Date: 1/12/1995

Release Date: 1/12/1995

Discovery Date: 1/12/1995

Enforcement Dt: Not reported

Enf Type: Not reported

Enter Date: 2/14/1995

Confirm Leak: 1/12/1995
Prelim Assess: Not reported
Remed Plan: Not reported
Monitoring: Not reported

TC0960024.13s Page 44

Map ID
Direction
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number
EPA ID Number

SHERWIN-WILLIAMS CO THE (Continued)

1000371821

Funding: Not reported
Staff Initials: LUST
How Discovered: Tank Closure
How Stopped: Not reported
Invent: No
Leak Cause: Corrosion
Leak Source: Tank
MTBE Source: Not reported
MTBE TBE GW: Not reported
MTBE TBE GW: Not Required to be Tested.
Priority: 302
Local Case #: Not reported
Benetic: Not reported
Staff: WNL
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hyd Basin #: 8.50
Operator: Not reported
Oversight Firm: R&L Lead Underground Storage Tank
Oversight Firm: UST
Review Date: 8/21/1998
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party/TIM LEAHY
R-Address: 101 PROSPECT AVE
Global ID: 10805300130
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
MTBE Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 3:
Case Number: 2521
Cross Street: PEARL ST
Responsible Party/TIM LEAHY
Local Agency: 03
Discovered: 01/01/1995
How Found: Tank Closure
Source: Tank
Cause: Corrosion
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Leak being confirmed
Facility County: Monterey
Review Date: 8/21/98
Confirm Leak: 01/12/1995
Prelim Assess: //
Remedial Plan: //
Monitoring: Not reported
Enforce Type: Not reported
Enforce Date: //

Release Date: 01/12/1995
Enter Date: 2/14/95
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported

Staff Initials: WNL
Funding: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Action: Not reported
Close Date: //
Pilot Program: UST

TC0960024.13s Page 45

Map ID
Direction
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number

SHERWIN-WILLIAMS CO THE (Continued)

Interim Action: 0
Mile Fuel: 0
Mile Concentration: 0
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Date: / /
MTBE Tested: NRQ
Leak Source: 36.597321 / -121.8938159
Leak Date: / /
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not reported
Priority: Not reported
Local Case #: Not reported
Beneficial: Not reported
Staff: JWG
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 8.50
Operator: Not reported
Oversight Prgm: Local Implementing Agency UST (includes non-LOP cases within LOP jurisdiction)
HZNEXT:
Gapaid: CAD05296985
Tepaid: CAD009466382
Gen County: Monterey
Tad County: 7
Tons: 2750
Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Contact: THE SHERWIN WILLIAMS CO
Telephone: (000) 000-0000
Mailing Address: 505 TYLER ST
MONTEREY, CA 93940
County: Monterey

BRITISH MOTORS
735 DEL MONTE AVE
MONTEREY, CA 93940

LUST
5103425766
Cortese N/A

State LUST:
Case Street: Not reported
City Leaked: Not reported
Case Number: 828
Bag Band: Central Coast Region
Case Date: 01/01/1985
Local Agency: Local Agency
Local Agency: 27000
Class Type: Other ground water affected
Status: Case Closed
County: Monterey
Abate Method: U
Remedial Date: Not reported
Workable Date: Not reported
Pollution Char: Not reported
Remedial Plan: Not reported
Release Date: 10/1/1983
Release Date: 5/14/1990
Cleanup Fund ID: Not reported
Discovery Date: 11/1/1985
Enforcement ID: Not reported
Enforcement ID: Not reported
Enter Date: 6/8/1990

Map ID
Direction
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number

BRITISH MOTORS (Continued)

Funding: Not reported
Staff Initials: UST
How Discovered: Tank Closure
How Stopped: Not reported
Infirm: Not reported
Leak Cause: Overfill
Leak Source: Tank
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE includes Unknown and Not Analyzed.
Priority: Not reported
Local Case #: Not reported
Beneficial: Not reported
Staff: JWG
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 8.50
Operator: Not reported
Oversight Prgm: Local Implementing Agency UST (includes non-LOP cases within LOP jurisdiction)
Review Prgm: LIA
Review Date: 2/24/1994
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
PP Address: Not reported
Global ID: T0905300386
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mile Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
LUST Region 3:
Case Number: 828
Case Street: Not reported
Responsible Party: Not reported
Local Agency: 03
Discovery: 01/01/1985
How Found: Tank Closure
Source: Tank
Cause: Overfill
Leak Agency: Local Agency
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey
Review Date: 2/24/94
Confirm Leak: / /
Prin Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Type: Not reported
Funding: Not reported
Workplan: / /
Pollution Char: / /
Remedial Action: / /
Close Date: 10/01/1983

Map ID
Direction
Distance
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MAP FINDINGS

BRITISH MOTORS (Continued)

Enforce Date: / /
Interim Action: Not reported
Mile Concentration: 1
Mile Fuel: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
MTBE Tested: / /
Leakage: 36.000131/-121.084627
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: CONTAMINATED SOIL EXCAVATED AND REMOVED IN AREA OF NON BENEFICAL
USE OF GROUNDWATER
CORTESE
Reg ID: 828
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

48
SE
1/4-1/2
1671 ft.
Higher

LUST
\$101307800
Cortese N/A

State LUST:
Cross Street: Not reported
City Listed: Not reported
Case Number: 2227
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Case Closed
County: Monterey
Abate Method: U
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Action: Not reported
Release Date: 10/17/1986
Cleanup Fund ID: Not reported
Discover Date: 1/1/1986
Enforcement DI: Not reported
Enf Type: Not reported
Enter Date: 8/31/1982
Funding: Not reported
Staff Initials: UST
How Discovered: Inventory Control
Interim: No
Leak Cause: UNK
Leak Source: UNK
MTBE Date: Not reported

Map ID
Direction
Distance
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MAP FINDINGS

MISSION MORTUARY (Continued)

Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE includes Unknown and Not Analyzed.
Priority: 3A3
Local Case #: Not reported
Beneficial: Not reported
Staff: JWG
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 9.50
Operator: Not reported
Oversight Pgmt: RB Lead Underground Storage Tank
Review Date: 11/2/1992
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: UNKNOWN
RP Address: 450 CAMINO EL ESTERO
Global ID: 10605300075
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mile Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 0
Waste Discharge Global ID: Not reported
Waste Discharge Assigned Name: Not reported
Case Number: 2227
Cross Street: Not reported
Responsible Party: UNKNOWN
Local Agency: 03
Discover Date: 01/01/1986
How Found: Inventory Control
Source: Other
Cause: UNK
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey
Review Date: 11/2/1992
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Date: / /
Enter Date: Not reported
Interim Action: / /
Mile Concentration: / /
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Date: / /
MTBE Tested: / /

Map ID
Direction
Distance
Elevation
Site

EDR ID Number
EPA ID Number

MISSION MORTUARY (Continued)

Leak Log : 36.598414 / -121.8876127
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: MONTEREY FIRE DEPT. AUTHORIZED TANK PULL SITE
INVESTIGATION IS IN PROGRESS.
CORTESE:
Reg ID: 2227
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

49
SSW
1/4-1/2
1719 ft.
Higher

HONEST ENGINES
553 MUNRAS AVE
MONTEREY, CA 93940

LUST 1000222440
N/A

Site LUST:
Case Street: TYLER
City: Not reported
Case Number: 2777
Reg Board: Central Coast Region
Chemical: Gasoline
Leak Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Pollution Characterization
County: Monterey
Admit Method: Unknown - action taken at site is unknown
Release Date: Not reported
Workshop: Not reported
Pollution Char: Not reported
Remedial Action: Not reported
Release Date: Not reported
Release Date: 10/15/1986
Release Fund ID: Not reported
Enforcement Date: 1/1/1985
Enforcement ID: Not reported
Enter Date: 12/16/1986
Funding: 0
Staff Initials: UST
How Discovered: Tank Closure
How Stopped: Not reported
Infirm: No
Leak Cause: Structure Failure
Leak Source: Tank
MTBE Date: 5/29/2002
Max MTBE GW: 4000 Parts per Billion
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: 3A3
Local Case #: Not reported
Beneficial: WNL
Staff: =
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported

Map ID
Direction
Distance
Elevation
Site

EDR ID Number
EPA ID Number

HONEST ENGINES (Continued)

Hydr Basin #: 9.50
Operator: Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Oversight Prgm: UST
Review Date: 8/18/2002
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party/TOM BURNS
RP Address: 1225 SCHOLL LN
Global ID: 70603300185
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 9
Mibe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Luit: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 3:

Case Number: 2777
Case Street: TYLER
Responsible Party/TOM BURNS
Local Agency: 03
Discovered: 01/01/1985
How Found: Tank Closure
Source: Tank
Cause: Structure Failure
Leak Agency: Regional Board
Case Type: Not reported
Facility Status: Pollution Characterization
Facility County: Monterey
Review Date: 8/18/02
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Type: LEFT
Enforce Date: / /
Infirm Action: 0
Mibe Concentration: 1
Mibe Fuel: Not reported
Org Name: Not reported
Max MTBE Ground Water: 4000
Max MTBE Soil: Not reported
Max MTBE Data: 08/29/2002
MTBE Tested: YES
Leak Log: 36.5972401 / -121.8841629
Soil Qualifier: Not reported
Groundwater Qualifier: =
Summary: 6 UST'S REMOVED. ONE UST PREVIOUSLY ABANDONED REMAINS. EXTENSIVE
CONTAMINATION DISCOVERED THROUGHOUT SITE. SITE CHARACTERIZATION PENDING
TO DELINEATE PLUME. POSSIBLE OFFSITE MIGRATION.

MAP FINDINGS

Map ID: 50
 Direction: SSW
 Distance: 1/4-1/2
 Elevation: 18/3 ft.
 Site: FORMER EXION 7-0228
 588 MUNRAS ST
 MONTEREY, CA 93940

Database(s): LUST
 EDR ID Number: S105224426
 EPA ID Number: N/A

State LUST:
 Cross Street: WEBSTER
 City Leased: Not reported
 Case Number: 2875
 Regional Board: Central Coast Region
 Chemical: Gasoline
 Lead Agency: Regional Board
 Local Agency: 27000
 Case Type: Other ground water affected
 Status: Pollution Characterization
 County: Monterey
 Aisle Method: Unknown - action taken at site is unknown
 Review Date: Not reported
 Workplan: 10/24/1986
 Pollution Char: Not reported
 Remed Plan: Not reported
 Release Date: 10/24/1986
 Cleanup Fund ID: Not reported
 Enforcement Date: 1/1/1986
 Enforcement Dt: Not reported
 Enter Date: LET
 Funding: 0
 Staff Initials: UST
 How Discovered: Subsurface Monitoring
 How Stopped: Not reported
 Interim: No
 Leak Cause: UNK
 Leak Source: UNK
 MTBE Date: 5/30/2002
 Max MTBE GW: 9300 Parts per Billion
 MTBE Tested: MTBE Detected, Site tested for MTBE & MTBE detected
 Priority: 3A3
 Local Case #: Not reported
 Beneficial: WNL
 Staff: WNL
 GW Qualifier: =
 Max MTBE Soil: Not reported
 Soil Qualifier: Not reported
 Hydr Basin #: 9.50
 Operator: Not reported
 Oversight Pgm: RB Lead Underground Storage Tank
 Review Date: 9/23/2002
 Stop Date: Not reported
 Work Suspended: Not reported
 Responsible Party: ABAS NAZEMI
 RP Address: 1415 OCEAN STREET
 Global ID: T0905300202
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 13

MAP FINDINGS

Map ID: 51
 Direction: SSW
 Distance: 1/4-1/2
 Elevation: 2031 ft.
 Site: FORMER EXION 7-0228 (Continued)

Database(s): LUST
 EDR ID Number: S105224426
 EPA ID Number: N/A

MTBE Fuel: 1
 Water System Name: Not reported
 Well Name: Not reported
 Distance To Leat: 0
 Waste Discharge Global ID: Not reported
 Waste Disch Assigned Name: Not reported
 Case Number: 2875
 Cross Street: WEBSTER
 Responsible Party: ABAS NAZEMI
 Local Agency: 03
 Discovered: 01/01/1986
 How Found: Subsurface Monitoring
 Source: Other
 Cause: UNK
 Lead Agency: Regional Board
 Case Type: Other ground water affected
 Pollution Char: Not reported
 Facility Status: Pollution Characterization
 Facility County: Monterey
 Review Date: 8/23/02
 Confirm Leak: / /
 Prelim Assess: 10/24/1986
 Remedial Plan: / /
 Monitoring: Not reported
 Enforcement Type: LET
 Enter Date: / /
 Interim Action: 0
 MTBE Concentration: 1
 Org Name: Not reported
 Max MTBE Ground Water: 9300
 Max MTBE Soil: Not reported
 Max MTBE Date: 08/29/2002
 MTBE Tested: YES
 Lat/Long: 36.596811/-121.083259
 Soil Qualifier: Not reported
 Groundwater Qualifier: =
 Summary: ENTERED FROM ERI MONITORING REPORT
 Release Date: 10/24/1986
 Enter Date: 8/8/87
 Regional Board: Central Coast Region
 Stop Date: Not reported
 How Stopped: Not reported
 Staff Initials: WNL
 Funding: 0
 Workplan: / /
 Pollution Char: 05/05/1988
 Remedial Action: / /
 Case Date: / /
 Pilot Program: UST
 Region: 3

MAP FINDINGS

Map ID	Direction	Distance	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	-----------	------	-------------	---------------	---------------

CHEVRON 91060 (Continued)

Mailing Address: PO BOX 6004

County: Monterey

Geopaid: CAL00032214

Tepaid: CAD00846392

Tad County: Monterey

Tad County: 7

Tad County: 2500

Category: Empty containers less than 30 gallons

Disposal Method: Recycler

Contact: CHEVRON PRODUCTS CO

Telephone: (925) 842-5931

Mailing Address: PO BOX 6004

County: Monterey

Geopaid: CAL00032214

Tepaid: CAD00846392

Tad County: Monterey

Tad County: San Mateo

Tad County: 8046

Category: Hydrocarbon solvents (benzene, toluene, xylene, etc.)

Disposal Method: Recycler

Contact: CHEVRON PRODUCTS CO

Telephone: (925) 842-5931

Mailing Address: PO BOX 6004

County: Monterey

Geopaid: CAL00032214

Tepaid: CAD00846392

Tad County: Monterey

Tad County: San Mateo

Tad County: 2877

Category: Aqueous solution with 10% or more total organic residues

Disposal Method: Recycler

Contact: CHEVRON PRODUCTS CO

Telephone: (925) 842-5931

Mailing Address: PO BOX 6004

County: Monterey

Geopaid: CAL00032214

Tepaid: CAD00846392

Tad County: Monterey

Tad County: San Mateo

Tad County: 2877

Category: Aqueous solution with 10% or more total organic residues

Disposal Method: Recycler

MAP FINDINGS

Map ID	Direction	Distance	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	-----------	------	-------------	---------------	---------------

CHEVRON SERVICE #91060 (Continued)

City Listed: Not reported

Case Number: 887

Reg Board: Central Coast Region

Chemical: Gasoline

Lead Agency: Regional Board

Local Agency: 27000

Case Type: Other ground water affected

Status: Remediation Plan

County: Monterey

Asbestos Method: U

Review Date: Not reported

Workplan: Not reported

Position Char: 1/14/2000

Remed Action: Not reported

Close Date: Not reported

Release Date: 11/1/1980

Cleanup Fund ID: Not reported

Discover Date: 1/1/1985

Enforcement ID: Not reported

Enl Type: LET

Enter Date: 11/1/1980

Funding: Not reported

Staff Initials: UST

How Discovered: Tank Closure

How Stopped: Not reported

Interm: No

Leak Cause: Structure Failure

Leak Source: Tank

MTBE Date: 1/8/2002

Max MTBE GW: 630 Parts per Billion

MTBE Tested: MTBE Detected, Site tested for MTBE & MTBE detected

Priority: SAS

Local Case #: Not reported

Beneficial: WML

Staff: Not reported

GW Qualifier: =

Max MTBE Soil: Not reported

Soil Qualifier: Not reported

Hydr Basin #: 9.50

Operator: Not reported

Overnight Pgm: R8 Lead Underground Storage Tank

MAP FINDINGS

Map ID	Direction	Distance	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	-----------	------	-------------	---------------	---------------

CHEVRON SERVICE #91060 (Continued)

City Listed: Not reported

Case Number: 887

Reg Board: Central Coast Region

Chemical: Gasoline

Lead Agency: Regional Board

Local Agency: 27000

Case Type: Other ground water affected

Status: Remediation Plan

County: Monterey

Asbestos Method: U

Review Date: Not reported

Workplan: Not reported

Position Char: 1/14/2000

Remed Action: Not reported

Close Date: Not reported

Release Date: 11/1/1980

Cleanup Fund ID: Not reported

Discover Date: 1/1/1985

Enforcement ID: Not reported

Enl Type: LET

Enter Date: 11/1/1980

Funding: Not reported

Staff Initials: UST

How Discovered: Tank Closure

How Stopped: Not reported

Interm: No

Leak Cause: Structure Failure

Leak Source: Tank

MTBE Date: 1/8/2002

Max MTBE GW: 630 Parts per Billion

MTBE Tested: MTBE Detected, Site tested for MTBE & MTBE detected

Priority: SAS

Local Case #: Not reported

Beneficial: WML

Staff: Not reported

GW Qualifier: =

Max MTBE Soil: Not reported

Soil Qualifier: Not reported

Hydr Basin #: 9.50

Operator: Not reported

Overnight Pgm: R8 Lead Underground Storage Tank

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Database(s)
EPA ID Number

CHEVRON SERVICE #91869 (Continued)

8103247534

LUST Region 3:
Case Number: 887
Cross Street: ABRIGO
Responsible Party/MARK LAFERTY
Local Agency: 03
Discovered: 01/01/1985
How Found: Tank Closure
Source: Tank
Cause: Structure Failure
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Remediation Plan
Facility County: Monterey
Review Date: 9/11/02
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: 01/14/2000
Monitoring: Not reported
Enforce Date: / /
Enforce Type: LET
Intern Action: 0
Mits Concentration: / /
Mits Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: 630
Max MTBE Soil: Not reported
Max MTBE Date: 07/01/2002
MTBE Tested: YES
Leak/Dmg: 36.6954771 / -121.8826789
Soil Qualifier: Not reported
Groundwater Qualifier: =
Summary: PARAGON ENVIRONMENTAL SERVICES SUBMITTED A REPORT REGARDING 865 MUNRAS AVE. CLAIMING CONTAMINATION IS A RESULT FROM LEAK AT 351 FREMONT

Release Date: 11/01/1980
Enter Date: 11/1980
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported

Staff Initials: WNL

Funding: Not reported
Workplan: / /
Pollution Char: 03/25/1992
Remedial Action: 11/22/1989
Close Date: / /
Pilot Program: UST
Region: 3

NS4
South
1/4-1/2
2218 ft.
Higher

TOSCO - FACILITY #9424
358 FREMONT ST
MONTEREY, CA 93940
Site 1 of 4 in cluster N

LUST 8103224815
N/A

State LUST:
Cross Street: ABRIGO ST
Case Number: 3259
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Pollution Characterization
County: Monterey
Cause: Unknown - action taken at site is unknown
Aerial Method: Not reported
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported

Confirm Leak: Not reported
Prelim Assess: Not reported
Remed Plan: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Database(s)
EPA ID Number

TOSCO - FACILITY #9424 (Continued)

8103224815

Remed Action: Not reported
Close Date: Not reported
Release Date: 2/22/2000
Cleanup Fund ID: Not reported
Discovered: 1/1/1985
Enforcement DI: Not reported
Enter Date: 3/28/2000
Funding: Not reported
How Discovered: COR
Staff Initials: WNL
How Stopped: Not reported
Intern: Not reported
Leak Cause: UNK
Leak Source: UNK
MTBE Date: 7/1/2002
Max MTBE GW: 590 Parts per Billion
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case #: Not reported
Beneficial: Not reported
Staff: WNL
GW Qualifier: =
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Review Date: 5/15/2002
Stop Date: 6/17/1989
Work Suspended: Not reported
Responsible Party/MR: ED RALSTON
RP Address: 1380 LEAD HILL ROAD, SUITE 120
Global ID: T0805300286
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 4
Mits Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

Release Date: 02/02/2000
Enter Date: 3/28/00
Regional Board: Central Coast Region
Stop Date: 6/17/89
How Stopped: Not reported

Staff Initials: WNL

LUST Region 3:
Case Number: 3259
Cross Street: ABRIGO ST
Responsible Party/MR: ED RALSTON
Local Agency: 03
Discovered: 01/01/1985
How Found: Not reported
Source: UNK
Cause: Other
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Pollution Characterization

Map ID
Direction
Distance (ft)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TOSCO - FACILITY #0424 (Continued)

8105224615

Facility County: Monterey
Review Date: 5/15/02
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Type: LET
Enforce Date: / /
Interim Action: Not reported
Mile Concentration: / /
Mile Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: 590
Max MTBE Soil: Not reported
MTBE Tested: 07/01/2002
Lailong: YES
Lailong: 36.595261 / -121.692246
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: Not reported

Funding: Not reported
Workplan: / /
Pollution Char: 04/28/2000
Remedial Action: / /
Close Date: / /
Pilot Program: UST
Region: 3

NBS
South
14-1/2
2218 ft.
Higher

HAZNET
UST
CHMRS
CONFIRM

ARCO PRODUCTS COMPANY

400 FREEMONT BLVD
MONTEREY, CA 93940

Site 2 of 4 in cluster N

State UST:

Cross Street: ABREGO
City/Loc: Not reported
Case Number: 650
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Post remedial action monitoring
Cause: Monitory
Acute Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Plan: Not reported
Review Date: 6/7/1996
Release Date: 4/7/1987
Cleaning Fund ID: Not reported
Discover Date: 1/7/1985
Enforcement Dt: Not reported
Enf Type: LET
Enf Date: 9/4/1987
Staff Initials: UST
How Discovered: Inventory Control
How Stopped: Not reported
Interim: Not reported
Leak Cause: Overfill

Map ID
Direction
Distance (ft)
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARCO PRODUCTS COMPANY (Continued)

8103657287

Leak Source: Tank
MTBE Date: 7/1/2002
Max MTBE GW: 555 Parts per Billion
Max MTBE Soil: MTBE Detected. Site tested for MTBE & MTBE detected
MTBE Tested: / /
Priority: Not reported
Local Case #: Not reported
Beneficial: MUN
Staff: WNL
GW Qualifier: =
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 9.50
Operator: Not reported
Oversight Prgm: RB Lead Underground Storage Tank
Review Date: 5/15/2002
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party/RAV VOSE
RP Address: PO BOX 8386
Global ID: T0605300337
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 16
Mile Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Leak: 0
Waste Discharge Global ID: Not reported
Waste Discharge Assigned Name: Not reported

UST Region 3:

Case Number: 650
Cross Street: ABREGO
Responsible Party/RAV VOSE
Local Agency: 03
Discover: 01/01/1985
How Found: Inventory Control
Source: Tank
Cause: Overfill
Lead Agency: Regional Board
Case Type: Other ground water affected
Review Date: Not reported
Facility Status: Post remedial action monitoring
Review Date: 5/15/02
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: 6/7/96
Monitoring: LET
Enforce Type: LET
Enforce Date: / /
Interim Action: Not reported
Mile Concentration: 1
Mile Fuel: Not reported
Org Name: Not reported
Max MTBE Ground Water: 6100
Max MTBE Soil: Not reported

Release Date: 04/17/1987
Enter Date: 9/4/87
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported

Staff Initials: WNL

Funding: Not reported
Workplan: / /
Pollution Char: 08/18/1987
Remedial Action: 03/23/1992
Close Date: / /
Pilot Program: UST
Region: 3

Map ID
Direction
Distance
Elevation
Site

MAP FINDINGS

Database(s)
EPA ID Number
EOR ID Number

ARCO PRODUCTS COMPANY (Continued)

Max MTBE Data : 1008/2002
MTBE Tested : YES
Lat/Long : 36.5952611 / -121.8922508
Soil Qualifier :
Groundwater Qualifier :
Summary : ALL TANKS WERE REMOVED IN '86. THE SITE IS DEVELOPED AS A MINI MARKET.
THREE OTHER ACTIVE SERVICE STATIONS LOCATED AT THE SAME INTERSECTION
HAVE HAD RELEASES, AND ARE PERFORMING/TAKING CORRECTIVE ACTIONS.

HAZNET:

Geopaid: CAL000025859
Tepaid: CAD003186728
Gen County: Monterey
Tad County: Stanislaus
Tons: 3127
Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: ATLANTIC RICHFIELD COMPANY
Telephone: (213) 486-0494
Mailing Address: PO BOX 8038
ARTESIA, CA 90702 - 6038

County: Monterey
Geopaid: CAL000025859
Tepaid: CAT080013352
Gen County: Monterey
Tad County: Los Angeles
Tons: 2293
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: ATLANTIC RICHFIELD COMPANY
Telephone: (213) 486-0494
Mailing Address: PO BOX 8038
ARTESIA, CA 90702 - 6038

County: Monterey
Geopaid: CAL000025859
Tepaid: CAT080013352
Gen County: Monterey
Tad County: Los Angeles
Tons: 1,3135
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: ATLANTIC RICHFIELD COMPANY
Telephone: (213) 486-0494
Mailing Address: PO BOX 8038
ARTESIA, CA 90702 - 6038

County: Monterey
Geopaid: CAL000025859
Tepaid: CAD009452657
Gen County: Monterey
Tad County: San Mateo
Tons: 1,0608
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Contact: ATLANTIC RICHFIELD COMPANY
Telephone: (213) 486-0494
Mailing Address: PO BOX 8038

Map ID
Direction
Distance
Elevation
Site

MAP FINDINGS

Database(s)
EPA ID Number
EOR ID Number

ARCO PRODUCTS COMPANY (Continued)

County: Monterey
Geopaid: CAL000025859
Tepaid: CAD043260702
Gen County: Monterey
Tad County: San Mateo
Tons: 2,2101
Category: Unspecified oil-containing waste
Disposal Method: Recycler
Contact: ATLANTIC RICHFIELD COMPANY
Telephone: (213) 486-0494
Mailing Address: PO BOX 8038
ARTESIA, CA 90702 - 6038

County: Monterey
The CA HAZNET database contains 5 additional records for this site.
Please contact your EDR Account Executive for more information.

CORTESE:

Reg Id: 650
Region: CORTESE
Reg By: Lasting Underground Storage Tanks

CHMRS:

OES Control Number: 1910
DOT Hazard Class: Not Reported
Chemical Name: gasoline
Extent of Release: Not reported
CAS Number: Not reported
Environmental Contamination: None Reported
Incident Date: Not reported
Time Completed :
Physical State Stored :
Physical State Released :
Release Unit :
Container Description :
Container Type :
Container Material :
Level Of Container :
Container Capacity :
Extent Of Release (code) :
Agency Id Number :
Agency Incident Number :
OES Incident Number :
Time Notified :
Surrounding Area :
Estimated Temperature :
Property Management :
More Than Two Substances Involved? :
Special Studies 1 :
Special Studies 2 :
Special Studies 3 :
Special Studies 4 :
Special Studies 5 :
Special Studies 6 :
Responding Agency Personnel # or Injuries :
Responding Agency Personnel # or Fatalities :
Quantity Released: approx. 2 gals
Property Use: Not reported
Date Completed: Not reported

MAP FINDINGS

Map ID
Direction
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number
EDR ID Number

ARCO PRODUCTS COMPANY (Continued)

810307287

Resp Agency Personnel # Of Decontaminated : Not reported
 Oils Number Of Decontaminated : Not reported
 Oils Number Of Injuries : Not reported
 Oils Number Of Fatalities : Not reported
 Vehicle Make/Year : Not reported
 Vehicle License Number : Not reported
 Vehicle State : Not reported
 Vehicle ID Number : Not reported
 CADOT/PU/CIC Number : Not reported
 Company Name : Not reported
 Reporting Officer Name/ID : Not reported
 Report Date : Not reported
 Comments : Not reported
 Facility Telephone Number : Not reported
 Material Involved : Not reported
 Material Involved : Not reported
 Spill Site : Not reported
 Cleanup By : Not reported
 Containment : Not reported
 When Happened : Not reported
 Date/Time : Not reported
 Evacuations : Not reported
 Type : Not reported
 Cause : Not reported
 Chemical 1 : Not reported
 Chemical 2 : Not reported
 Chemical 3 : Not reported

MSB
South
14-12
2218 ft.
Higher

UNOCAL SERVICE STATION #0424
398 FREEMONT ST
MONTEREY, CA 93940

State LUST:
Case Number:
Cross Street:
City Leased:
Case Number:
Reg Board:
Chemical:
Lead Agency:
Local Agency:
Case Type:
Status:
County:
Abate Method:
Review Date:
Workplan:
Pollution Char:
Remed Action:
Close Date:
Release Date:
Cleanup Fund ID:
Discover Date:
Enforcement DI:
Ent Type:
Enter Date:

ABREGO ST
Not reported
1023
Central Coast Region
Gasoline
Regional Board
27000
Other ground water affected
U
1/28/1994
Not reported
Not reported
9/10/1997
9/10/1997
1/28/1994
Not reported
Not reported
9/10/1997
1/28/1994
Not reported
Not reported
1/1/1985
Not reported
1/1/1985

MAP FINDINGS

Map ID
Direction
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number
EDR ID Number

UNOCAL SERVICE STATION #0424 (Continued)

810307605

Funding: Not reported
 Staff Initials: UST
 How Discovered: OM
 How Stopped: Not reported
 Interim: No
 Leak Cause: UNK
 Leak Source: UNK
 MTBE Date: 4/7/2002
 Max MTBE GW: 41.8 Parts per Billion
 MTBE Tested: MTBE Detected. Site used for MTBE & MTBE detected
 Priority: Not reported
 Local Case #: Not reported
 Beneficial: Not reported
 Staff: WNL
 GW Qualifier: =
 Max MTBE Soil: Not reported
 Soil Qualifier: Not reported
 Hyd Basin #: 9.50
 Operator: Not reported
 Oversight Pgm: R8 Lead Underground Storage Tank
 Oversight Pgm: UST
 Review Date: 8/22/2002
 Stop Date: Not reported
 Work Suspended: Not reported
 Responsible Party/MR: ED RALSTON
 RP Address: 1380 LEAD HILL ROAD, SUITE 120
 Global ID: 10605300008
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 4
 MTBE Fuel: 1
 Water System Name: Not reported
 Well Name: Not reported
 Distance To LUST: 0
 Waste Discharge Global ID: Not reported
 Waste Disch Assigned Name: Not reported

LUST Region 3:

Case Number: 1023
 Cross Street: ABREGO ST
 Responsible Party/MR: ED RALSTON
 Local Agency: 03
 Discovered: 01/01/1985
 How Found: Not reported
 Source: Other
 Cause: UNK
 Lead Agency: Regional Board
 Case Type: Other ground water affected
 Contact: Not reported
 Facility Status: Case Closed
 Facility County: Monterey
 Review Date: 8/2/02
 Confirm Leak: 01/28/1994
 Prelim Assess: / /
 Remedial Plan: / /
 Monitoring: 9/10/97
 Ent Type: LET
 Enter Date: / /

Release Date: 02/07/1991
 Enter Date: 1/1/89
 Regional Board: Central Coast Region
 Stop Date: Not reported
 How Stopped: Not reported
 Staff Initials: WNL
 Funding: Not reported
 Workplan: / /
 Pollution Char: / /
 Remedial Action: / /
 Close Date: 01/01/1985
 Pilot Program: UST

Map ID
Direction
Distance (ft)
Elevation

MAP FINDINGS

Database(s)
EPA ID Number
5101307605

UNOCAL SERVICE STATION #0424 (Continued)

Interim Action: 0
Miles Concentration: 1
Miles Fuel: 1
Miles Ground Water: 550
Miles MTBE Soil: Not reported
Miles MTBE Data: 1008/2002
MTBE Tested: YES
Soil Quality: 38.5952651 / -121.8922248
Groundwater Qualifier: Not reported
Summary: CASE WAS CLOSED IN 1998, HOWEVER, DURING THE UST UPGRADE, ELEVATED MTBE AND ETHER GASOLINE RELATED COMPOUNDS WERE DETECTED. NEW INVESTIGATIONS AND CONNECTIVE ACTIONS ARE REQUIRED.

HAZNET:

Geopid: CAD082042095
Tepid: CAD008452657
Gen County: Monterey
Tad County: San Mateo
Tone: 3127
Category: Aqueous solution with 10% or more total organic residues
Disposal Method: Recycler
Contact: UNION OIL COMPANY OF CALIFORNIA
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92798 - 5376
County: Monterey
Geopid: CAD082042095
Tepid: CAD008452708
Gen County: Monterey
Tad County: Santa Cruz
Tone: 2293
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: UNION OIL COMPANY OF CALIFORNIA
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92798 - 5376
County: Monterey
Geopid: CAD082042095
Tepid: CAD008452708
Gen County: Monterey
Tad County: Los Angeles
Tone: 2085
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: UNION OIL COMPANY OF CALIFORNIA
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92798 - 5376
County: Monterey

Map ID
Direction
Distance (ft)
Elevation

MAP FINDINGS

Database(s)
EPA ID Number
5101307605

UNOCAL SERVICE STATION #0424 (Continued)

Geopid: CAD082042095
Tepid: CAD008452708
Gen County: Monterey
Tad County: Los Angeles
Tone: 0.22
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: CHRISTOPHER Z HILL
Telephone: (714) 328-8602
Mailing Address: PO BOX 25376
SANTA ANA, CA 92798 - 5376
County: Monterey
Geopid: CAD082042095
Tepid: CAD008452708
Gen County: Monterey
Tad County: Los Angeles
Tone: 0.8798
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Recycler
Contact: UNION OIL COMPANY OF CALIFORNIA
Telephone: (714) 328-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92798 - 5376
County: Monterey

CORTESE: 1023
Reg Id: CORTESE
Region: Leaking Underground Storage Tanks
Reg By:

N57
South
14-12
2218 ft
Higher

BP FACILITY
401 FREMONT ST
MONTEREY, CA 93940

Site 4 of 4 in cluster N

State LUST:

Cross Street: ABERGO
City Leaked: Not reported
Case Number: 682
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Status: Other ground water affected
Case Type: Post remedial action monitoring
County: Monterey
Adeq Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: 4/20/2000
Close Date: Not reported
Release Date: 3/19/1988
Cleanup Fund Id: Not reported

LUST 5104310428
Cortese N/A

Map ID
Direction
Distance (ft.)
Elevation
Site

MAP FINDINGS

Database(s)
EPA ID Number
EDR ID Number

BP FACILITY (Continued)

Discover Date: 11/1986
Enforcement ID: 8201986
Ent Type: LET
Enter Date: 7/27/1987
Funding: Not reported
Staff Initials: UST
How Discovered: Tank Trail
How Stopped: Not reported
Interim: Not reported
Last Cause: Overfill
Last Source: Piping
MTBE Date: 7/1/2002
Max MTBE GW: 848 Parts per Billion
MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
Priority: 343
Local Case #: Not reported
Beneficial: MUN
Staff: WNL
GW Qualifier: =
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 9.50
Operator: Not reported
Oversight Pgm: 88 Lead Underground Storage Tank
Oversight Pgm: UST
Review Date: 9/25/2002
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: SCOTT HOOTON
RP Address: 296 41ST ST SW BLDG 13 STE N
Global ID: 1060530039
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 15
Mile Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 3:
Case Number: 652
Cross Street: ABREGO
Responsible Party: SCOTT HOOTON
Local Agency: 03
Discover Date: 07/01/1986
How Found: Tank Trail
Source: Piping
Cause: Overfill
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Post remedial action monitoring
Facility County: Monterey
Review Date: 9/25/02
Confirm Leak: Not reported
Prelim Assess: Not reported
Funding: Not reported
Workplan: Not reported
Pollution Char: 03/25/1989

Map ID
Direction
Distance (ft.)
Elevation
Site

MAP FINDINGS

Database(s)
EPA ID Number
EDR ID Number

BP FACILITY (Continued)

Remedial Plan: Not reported
Monitoring: 4/20/00
Enter Date: LET
Enforce Date: 06/20/1986
Interim Action: Not reported
Mile Concentration: 1
Mile Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: 310
Max MTBE Soil: Not reported
Max MTBE Date: 10/08/2002
MTBE Tested: YES
Lat/Long: 36.5954751 / -121.8922528
Soil Qualifier: Not reported
Groundwater Qualifier: =
Summary: 3 GAS TANKS & 1 WASTE OIL TANK WERE REMOVED. SAMPLING FREQUENCY OF THE MONITORING WELLS WAS REDUCED TO ONCE EVERY 6 MONTHS BEGINNING OCT. 1987.

CORTESE:
Reg ID: 652
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

58
ESE
1/4-1/2
2222 ft.
Higher

CITY OF MONTEREY
551 DEL MONTE AVE
MONTEREY, CA 93940

HAZNET
LUST
N/A

State LUST:
Cross Street: EL ESTERO
City Leaked: Not reported
Case Number: 2831
Reg Board: Central Coast Region
Chemical: Waste Oil
Lead Agency: Local Agency
Local Agency: 27000
Case Type: Other ground water affected
Status: No Action
County: Monterey
Action Method: Unknown - action taken at site is unknown
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Action: Not reported
Release Date: 12/27/1987
Cleanup Fund ID: Not reported
Discover Date: 1/1/1986
Enforcement ID: Not reported
Enter Date: 3/15/1998
Funding: 0
Staff Initials: RIC
How Discovered: OMI
How Stopped: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EPA ID Number
8103265955

CITY OF MONTEREY (Continued)

Interim: No
Leak Cause: Other Cause
Leak Source: Other Source
MTBE Date: 10/27/2000
Max MTBE GW: Not reported
MTBE Tested: MTBE Detected; Site tested for MTBE & MTBE detected
Priority: Not reported
Local Case #: Not reported
EPA Case #: Not reported
Site: WNL
Site Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hyd Depth #: 9.50
Operator: Not reported
Overnight Pgm: Not reported
Overnight Pgm: RB Lead Underground Storage Tank
Review Date: 7/19/1999
Stop Date: Not reported
Work Suspended: Not reported
Responsible Parties TURNBEAUGH
RP Address: 353 CAMINO EL ESTERO
Global ID: T08030222
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 1
Miles Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Last: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 3:
Case Number: 2831
Cross Street: EL ESTERO
Responsible Parties TURNBEAUGH
Local Agency: 03
Discovered: 01/01/1985
How Found: Not reported
Source: Other
Cause: Other Cause
Lead Agency: Local Agency
Case Type: Other ground water affected
Contact: Not reported
Facility Status: No Action
Facility County: Monterey
Review Date: 7/19/99
Confirm Leak: //
Prelim Assess: //
Remedial Plan: //
Monitoring: Not reported
Enforce Type: Not reported
Enforce Date: //
Interim Action: 0
Miles Concentration: Not reported
Miles Fuel: 0
Org Name: Not reported

Release Date: 12/02/1997
Enter Date: 3/19/88
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported

Staff Initials: WNL
Funding: 0
Workplan: //
Pollution Char: //
Remedial Action: //
Case Date: //
Pilot Program: UST
Region: 3

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Site

Database(s)

EPA ID Number
8103265955

CITY OF MONTEREY (Continued)

Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Date: 10/27/2000
MTBE Tested: YES
LULU Log: 36.800104 / -121.8843746
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: UST WAS DISCOVERED DURING BUILDING DEMOLITION. CONSULTANT ATTEMPTED TO
PLUG UST UNTIL REMOVAL. SUBSEQUENT RAINS RESULTING IN WATER ENTERING
AND DISPLACING OIL. PRODUCT REMOVAL & SOIL REMOVAL IN PROGRESS.

HAZNET:
Geopid: CAC001371480
Tapeid: CAC08244481
Gen County: Monterey
Tad County: San Bernardino
Tons: 0.425
Category: Other organic solids
Disposal Method: Transfer Station
Contact: CITY OF MONTEREY
Telephone: (408) 946-3987
Mailing Address: 353 CAMINO EL ESTERO
MONTEREY, CA 93940
County: Monterey
Geopid: CAC001371480
Tapeid: CAD009465392
Gen County: Monterey
Tad County: 7
Tons: 3250
Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Contact: CITY OF MONTEREY
Telephone: (408) 946-3987
Mailing Address: 353 CAMINO EL ESTERO
MONTEREY, CA 93940
County: Monterey
Geopid: CA100170895
Tapeid: CAT08013352
Gen County: Monterey
Tad County: Los Angeles
Tons: 0.8173
Category: Unrefined aqueous solution
Disposal Method: Recycler
Contact: CITY OF MONTEREY
Telephone: (831) 846-3986
Mailing Address: 353 CAMINO EL ESTERO
MONTEREY, CA 93940
County: Monterey

Map ID	Direction	Distance	Distance (ft.)	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
MAP FINDINGS								

59	MONTEREY FIRE DEPT	LIST	8101280857
SW	351 MADISON	Container	N/A
1/4-1/2	MONTEREY, CA 93940		
2334 ft.			
Midget			

MONTEREY FIRE DEPT (Continued)
 GW Qualifier : Not reported
 Max MTBE Soil : Not reported
 Soil Qualifier : Not reported
 Hydr Basin # : 9.50
 Operator : Not reported
 Oversight Firm: RB Lead Underground Storage Tank
 Oversight Firm: UST
 Review Date : 4/2/1983
 Stop Date : Not reported
 Work Suspended : Not reported
 Responsible Party/Not reported
 RP Address: Not reported
 Global ID: T0805300086
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 0
 Mibe Fuel: 1
 Water System Name: Not reported
 Well Name: Not reported
 Distance To Luit: 0
 Waste Discharge Global ID: Not reported
 Waste Ditch Assigned Name: Not reported
 LUST Region: 3
 Case Number: 2332
 Cross Street: PACIFIC
 Responsible Party/Not reported
 Local Agency: 03
 Discovered: 01/01/1965
 How Found: Not reported
 Source: Other
 Cause: UNK
 Lead Agency: Local Agency
 Case Type: Undefined
 Contact: Not reported
 Facility Status: Leak being confirmed
 Facility County: Monterey
 Review Date: 4/2/83
 Confirm Leak: 10/22/1982
 Prelim Assess: / /
 Remedial Plan: / /
 Monitoring: Not reported
 Enforcement Type: Not reported
 Enforcement Date: / /
 Interim Action: 0
 Mibe Concentration: 1
 Mibe Fuel: 1
 Org Name: Not reported
 Max MTBE Ground Water: Not reported
 Max MTBE Soil: / /
 Max MTBE Date: / /
 MTBE Tested: NT
 Luit/Org : 36.5986641 / 121.8976031
 Soil Qualifier: Not reported
 Groundwater Qualifier: Not reported
 Summary: CONTRACTOR OF THE CITY REMOVED FUEL TANK FROM UNDERGROUND WATER AND SOIL SAMPLE DISCLOSED CONTAMINATION ABOVE STATE ACTION LEVELS.

Map ID
Direction
Distance (ft.)
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MONTEREY FIRE DEPT (Continued)

CORTESE:
Rag Id: 2332
Region: CORTESE
Rag By: Leaking Underground Storage Tanks

5101239057

60
SSW
1/4-1/2
2326 ft.
Higher
RECOVERY CENTER (CHOMP)
578 HARTWELL ST
MONTEREY, CA 93940

LUST
1000109704
Cortese
N/A

State LUST:
Cross Street: Not reported
City: Not reported
Case Number: 511
Rag Board: Central Coast Region
Case Date: 8/12/1987
Local Agency: 27000
Case Type: Undefined
Status: Pollution Characterization
County: Monterey
Address Method: U
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Action: Not reported
Case Date: 8/12/1987
Cleanup Fund Id: Not reported
Disposal Date: 1/7/1986
Enforcement D: Not reported
EIR Type: Not reported
Enter Date: 10/7/1987
Funding: Not reported
Staff Initials: UST
How Discovered: Tank Test
Interim: No
Leak Cause: Piping
Leak Source: Not reported
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not Required to be Tested
Priority: 0
Local Case #: Not reported
Beneficial: Not reported
Staff: WNL
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 8.50
Operator: Not reported
Overnight Pgm: RB Land Underground Storage Tank
Overnight Pgm: UST
Review Date: 9/1/1987

Confirm Leak: Not reported
Pratin Assess: Not reported
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance (ft.)
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

RECOVERY CENTER (CHOMP) (Continued)

Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
RP Address: Not reported
Global Id: 10905300316
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
MTBE Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To LUST: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 3:

Case Number: 511
Cross Street: Not reported
Responsible Party: Not reported
Local Agency: 03
Discovered: 01/01/1985
How Found: Tank Test
Source: Piping
Cause: UST
Lead Agency: Local Agency
Case Type: Undefined
Contact: Not reported
Facility Status: Pollution Characterization
Facility County: Monterey
Review Date: 8/1/87
Confirm Leak: Not reported
Pratin Assess: Not reported
Remedial Plan: Not reported
Monitoring: Not reported
Enforce Date: Not reported
Enforce Type: Not reported
Human Action: Not reported
Human Action: Not reported
MTBE Concentration: Not reported
MTBE Fuel: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Date: Not reported
MTBE Tested: Not reported
Leak Long: 36.8557321 / -121.895208
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: LEAKAGE APPEARS TO BE LOCALIZED. CARBONA AND ASSOCIATES HAS BEEN RETAINED BY HOSPITAL TO DEVELOP A PLAN TO ADDRESS AND MITIGATE THE IDENTIFIED PROBLEM. TANK TESTED TIGHT & FUEL SUPPLY LINE LEAKING.

CORTESE:

Rag Id: 511
Region: CORTESE
Rag By: Leaking Underground Storage Tanks

1000109704

Map ID
Direction
Distance
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number

061
SSE
14-1/2
2370 ft.
Higher

LUST
HIST UST
N/A

EL ESTERO CAR WASH
590 FREMONT ST
MONTEREY, CA 93940
Site 1 of 2 in cluster 0

State LUST:
Cross Street: Not reported
City Label: Not reported
Case Number: 651
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Case Closed
County: Monterey
Advis Method: U
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remed Action: Not reported
Release Date: 12/23/1987
Cleaning Fund ID: Not reported
Discover Date: 1/1/1985
Enforcement Dt: Not reported
Erlf Type: Not reported
Erlf Date: 10/17/1987
Funding: Not reported
Start Initials: UST
How Discovered: Tank Test
Leak Source: Not reported
Leak Status: UNK
Leak Date: Not reported
MTBE Data: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not reported
MTBE Tested: 343
Local Case #: Not reported
Baseball: Not reported
Staff: WNL
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hyd Basin #: 850
Operator: Not reported
Overnight Prgm: Not reported
Reversal Prgm: Not reported
Reversal Date: 3/24/1992
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
RP Address: Not reported
Global ID: 10605500358
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0

Confirm Leak: Not reported
Prelim Assess: Not reported
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Distance (ft)
Elevation
Site

Database(s)
EPA ID Number

EL ESTERO CAR WASH (Continued)

1001593653

Water System Name: Not reported
Well Name: Not reported
Distance To Leat: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
LUST Region 3:
Case Number: 651
Cross Street: Not reported
Reg Board: Not reported
Responsible Party: Not reported
Local Agency: 03
Discover: 0/01/1985
How Found: Tank Test
Source: Tank Test
County: Monterey
Lead Agency: Regional Board
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey
Review Date: 3/24/92
Confirm Leak: Not reported
Prelim Assess: Not reported
Remedial Plan: Not reported
Monitoring: Not reported
Enforce Type: Not reported
Enforce Date: Not reported
Release Action: 0
Miles Concentration: Not reported
Miles Fuel: Not reported
On Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
MTBE Data: Not reported
MTBE Tested: NT
Leak Date: 36.5950511/-121.9883527
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: MONITORING WELLS HAVE BEEN DUG 3 OF THE 4 UNDERGROUND TANKS WERE FOUND TO LEAK. OWNER UNKNOWN AT THIS TIME. ADDRESS IS FOR LAW CORP. OF THOMPSON, HUBBARD, SCHWARTZ, OMETER GRAY WHO REQUESTED INVEST.

UST HIST:
Facility ID: 59653
Tank Num: 1
Tank Capacity: 10000
Type of Fuel: UNLEADED
Leak Detection: Visual, Stock Inventory
Contact Name: ATLANTIC RICHFIELD
Total Tanks: 1
Facility Type: CAR WASH
Facility ID: 59653
Tank Num: 2
Tank Capacity: 3000
Type of Fuel: PRODUCT
Tank Used for: PRODUCT

Container Num: 1
Year Installed: Not reported
Tank Construction: Not reported
Telephone: (408) 373-1801
Region: STATE
Other Type: CAR WASH
Container Num: 2
Year Installed: Not reported

Map ID
Direction
Distance
Elevation

Site

Database(s)

EPA ID Number
EPA ID Number

MAP FINDINGS

EL ESTERO CAR WASH (Continued)

Type of Fuel: DIESEL
Leak Detection: Stock Inventory
Contact Name: ATLANTIC RICHFIELD
Total Tanks: 3
Facility Type: 1
Facility ID: 5653
Tank Num: 3
Tank Capacity: 10000
Type Used for: PRODUCT
Type of Fuel: PREMIUM
Leak Detection: Visual, Stock Inventory
Contact Name: ATLANTIC RICHFIELD
Total Tanks: 3
Facility Type: 1
Tank Construction: Not reported
Telephone: (408) 373-1801
Region: STATE
Other Type: CAR WASH
Container Num: 3
Year Installed: Not reported
Tank Construction: Not reported
Telephone: (408) 373-1801
Region: STATE
Other Type: CAR WASH

082
SSE
1/4-1/2
2370 ft.
Higher

EL ESTERO CARWASH
590 FREMONT
MONTEREY, CA 93940
Site 2 of 2 in cluster O

HAZNET
S104161670
Corteese
N/A

HAZNET:

Geopac: CAC001051312
Tepac: CAC004771168
Gen County: Monterey
Tad County: San Francisco
Tone: 18,0000
Category: Other empty containers 30 gallons or more
Disposal Method: Recycle
Contact: GARY PEDERSON
Telephone: (000) 000-0000
Mailing Address: 590 FREMONT ST
MONTEREY, CA 93940 - 3216
County: Monterey
Geopac: CAC001051312
Tepac: CAC004771168
Gen County: Monterey
Tad County: Stanislaus
Tone: 22,8350
Category: Unspecified oil-containing waste
Disposal Method: Recycle
Contact: GARY PEDERSON
Telephone: (000) 000-0000
Mailing Address: 590 FREMONT ST
MONTEREY, CA 93940 - 3216
County: Monterey
Corteese: 651
Rag Id: CORTESE
Region: CORTESE
Rag By: Leaking Underground Storage Tanks

Map ID
Direction
Distance
Elevation

Site

Database(s)

EPA ID Number
EPA ID Number

MAP FINDINGS

P83
ESE
1/4-1/2
2510 ft.
Higher

HONDA KAWASAKI OF MONTEREY
815 DEL MONTE AVE
MONTEREY, CA 93940
Site 1 of 2 in cluster P

LUST
S100937062
N/A

State LUST:

Cross Street: EL ESTERO
Qty Leaked: Not reported
Case Number: 2785
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Local Agency
Local Agency: 2700
Case Type: Other ground water affected
Status: Case Closed
County: Monterey
Abate Method: Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming)
Review Date: Not reported
Work Item: Not reported
Pollution Chart: Not reported
Remed Action: Not reported
Case Date: 10/1/1992
Release Date: 12/01/1986
Cleanup Fund Id: Not reported
Discover Date: 1/1/1985
Enforcement Dt: Not reported
Enf Type: Not reported
Enter Date: 1/6/1987
Funding: 0
Staff Initials: UST
How Discovered: Tank Closure
How Stopped: Not reported
Intram: No
Leak Cause: UNK
Leak Source: UNK
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Site NOT Tested for MTBE, includes Unknown and Not Analyzed.
Priority: Not reported
Local Case #: Not reported
Beneficial: Not reported
Staff: Not reported
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 9.50
Operator: Not reported
Oversight Pgm: RB Lead Underground Storage Tank
Review Date: Not reported
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
RP Address: Not reported
Global Id: T0805300171
Org Name: Not reported
Contact Person: Not reported

Confirm Leak: Not reported
Prelim Assess: Not reported
Remed Plan: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MAP FINDINGS

HONDA KAWASAKI OF MONTEREY (Continued)

5106937082

MTBE Conc: 0
Miba Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Leak: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
LUST Region 3:
Case Number: 2765
Cross Street: EL ESTERO
Responsible Party: Not reported
Local Agency: 03
Discovered: 01/01/1965
How Found: Tank Closure
Source: UNK
Cause: UNK
Lead Agency: Local Agency
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Case Closed
Facility County: Monterey
Review Date: Not reported
Confirm Leak: / /
Prelim Assess: / /
Remedial Plan: / /
Monitoring: Not reported
Enforce Type: Not reported
Enforce Date: / /
Interim Action: 0
Miba Concentration: / /
Miba Fuel: 1
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Data: / /
MTBE Tested: NT
Lat/Long: 36.600095 / -121.8633985
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: Not reported
Release Date: 12/01/1966
Enter Date: 1/6/67
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported
Staff Initials: HDC
Funding: 0
Workplan: / /
Pollution Char: / /
Remedial Action: / /
Close Date: 10/01/1992
Pilot Program: UST
Region: 3

FORMER VAPOR CLEANERS SITE
951 DEL MONTE AVE
MONTEREY, CA 93940
LUST 8104891018
N/A

Site 2 of 2 in cluster P
State LUST:
Cross Street: Not reported
Oily Liquid: Not reported
Case Number: 3316
Reg Board: Central Coast Region
Chemical: 12004
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Undefined

Map ID
Direction
Distance
Elevation
Site
Database(s)
EDR ID Number
EPA ID Number

MAP FINDINGS

FORMER VAPOR CLEANERS SITE (Continued)

5104891018

Status: Preliminary site assessment workplan submitted
County: Monterey
Review Date: Not reported
Workplan: Not reported
Pollution Char: Not reported
Remedial Action: Not reported
Close Date: Not reported
Release Date: 2/14/2001
Cleanup Fund ID: Not reported
Discover Date: 1/1/1965
Enforcement DL: Not reported
Ent Type: LET
Enter Date: Not reported
Funding: Not reported
Staff Initials: CDR
How Discovered: Tank Closure
How Stopped: Not reported
Interim: Not reported
Leak Cause: UNK
Leak Source: Tank
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tested: Not required to be tested
Priority: Not reported
Local Case #: 3316
Beneficial: Not reported
Staff: JWG
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: Not reported
Operator: Not reported
Oversight Prgm: RB Used Underground Storage Tank
Oversight Prgm: UST
Review Date: Not reported
Stop Date: 2/1/2001
Work Suspended: Not reported
Responsible Party: Not reported
RP Address: Not reported
Global ID: 10605398983
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Miba Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Leak: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported
LUST Region 3:
Case Number: 3316
Cross Street: Not reported
Responsible Party: Not reported
Local Agency: 03
Discovered: 01/01/1965
How Found: Tank Closure
Source: Tank
Release Date: 02/14/2001
Enter Date: Not reported
Regional Board: Central Coast Region
Stop Date: 2/1/01
How Stopped: Not reported

Map ID
Direction
Distance (ft.)
Elevation
Site

MAP FINDINGS

Database(s)
EPA ID Number
EPA ID Number

FORMER VAPOR CLEANERS SITE (Continued)

Cause: UNK
Lead Agency: Regional Board
Case Type: Undefined
Contact: Not reported
Facility Status: Preliminary site assessment workplan submitted
Review Date: Monterey
Confirm Leak: Not reported
Prelim Assess: Not reported
Remedial Plan: Not reported
Monitoring: Not reported
Enforce Date: Not reported
Enforce Type: LET
Interim Action: Not reported
Mile Concentration: Not reported
Mile Fuel: 0
Org Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
Max MTBE Date: Not reported
MTBE Tested: NRQ
Leak Date: 36 800137 / -121.882983
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: Haz Mat incident report filed

Staff initials: JWG
Funding: Not reported
Workplan: 03/27/2001
Pollution Char: Not reported
Remedial Action: Not reported
Close Date: Not reported
Pilot Program: UST
Region: 3

65
NNW
1/4-1/2
2287 ft.
Higher

PREARIO OF MONTEREY
LIGHTHOUSE AVE / FOAM ST
MONTEREY, CA 93940

Cortese 8109028035
N/A

CORTESE:
Reg Id: 27290004
Region: CORTESE
Reg By: CALSI

66
East
1/2-1
2892 ft.
Higher

EXXON SERVICE STATION
1042 DEL MONTE AVE
MONTEREY, CA

Cortese 8102438734
N/A

CORTESE:
Reg Id: 1029
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

Map ID
Direction
Distance (ft.)
Elevation
Site

MAP FINDINGS

Database(s)
EPA ID Number
EPA ID Number

COAST GUARD STATION MONTEREY (

687
NNW
1/2-1
3046 ft.
Higher

100 LIGHTHOUSE AVE
MONTEREY, CA 93940

CHMRS 0001593846
HIST UST N/A

Site 1 of 2 in cluster Q

CHMRS:
OES Control Number: 10817
DOT Hazard Class: DOT ID: Not reported
Chemical Name: diesel fuel
Extent of Release: Not reported
CAS Number: Not reported
Environmental Contamination: None Reported
Incident Date: Not reported
Time Completed: Not reported
Physical State Released: Not reported
Release Unit: Not reported
Container Description: Not reported
Container Type: Not reported
Container Material: Not reported
Level of Container: Not reported
Container Capacity: Not reported
Extent Of Release (code): Not reported
Agency Id Number: Not reported
Agency Incident Number: 10817
Time Notified: Not reported
Surrounding Area: Not reported
Estimated Temperature: Not reported
Property Management: Not reported
More Than Two Substances Involved?: Not reported
Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
Responding Agency Personnel # Of Injuries: NO
Responding Agency Personnel # Of Fatalities: NO
Resp Agency Personnel # Of Decontaminated: Not reported
Others Number Of Injuries: Not reported
Others Number Of Fatalities: Not reported
Vehicle Make/Year: Not reported
Vehicle License Number: Not reported
Vehicle State: Not reported
Vehicle Id Number: Not reported
CADOT/FIDUCIC Number: Not reported
Company Name: Not reported
Reporting Officer Name/ID: Not reported
Report Date: Not reported
Comments: Not reported
Facility Telephone Number: Not reported
Waterway Involved: YES
Waterway: Monterey Bay
Still Site: uscg
Cleanup By: OTHER

Map ID
Direction
Distance
Elevation
Site
Database(s)
EPA ID Number

MAP FINDINGS

COAST GUARD STATION MONTEREY (Continued)

U001503546

Container:
What Happened: overfill during refueling process.
Date Time: 0815 11nov85
Evacuations: NO
Type: Not reported
Other: Not reported
Chemical 1: Not Reported
Chemical 2: Not Reported
Chemical 3: Not Reported
UST HIST:
Facility ID: 54206
Tank Num: 1
Tank Capacity: 10000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Leak Detection: Stock Inventory
Contact Name: COMMANDING OFFICER
Total Tanks: 2
Facility Type: 2
Container Num: 1
Year Installed: 1976
Tank Construction: Not reported
Telephone: (408) 375-2278
Region: STATE
Other Type: U.S. GOVERNMENT
Facility ID: 54206
Tank Num: 2
Tank Capacity: 1000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Leak Detection: Stock Inventory
Contact Name: COMMANDING OFFICER
Total Tanks: 2
Facility Type: 2
Container Num: 2
Year Installed: 1975
Tank Construction: Not reported
Telephone: (408) 375-2278
Region: STATE
Other Type: U.S. GOVERNMENT

Q68
NNW
1/2-1
3046 ft.
Higher
U.S. COAST GUARD
100 LIGHTHOUSE AVE
MONTEREY, CA 93940
LUST 810129055
Confess N/A

Site 2 of 2 in cluster Q

Site LUST:
Cross Street: REEDSIDE
City: Monterey
Case Number: 815
Reg Board: Central Coast Region
Chemical: Diesel
Local Agency: 27000
Local Agency: 27000
Case Type: Other ground water affected
Status: Remediation Plan
County: Monterey
Abate Method: Evaluate and Dispose - remove contaminated soil and dispose in approved site
Review Date: Not reported
Workplan: Not reported
Pollution Char: 11/1/1983
Remed Action: Not reported
Release Date: Not reported
Cleanup Fund ID: Not reported
Confirm Leak: Not reported
Prelim Assess: Not reported
Monitoring: Not reported

Map ID
Direction
Distance
Elevation
Site
Database(s)
EPA ID Number

MAP FINDINGS

U.S. COAST GUARD (Continued)

810129055

Discover Date: 1/1/1985
Enforcement ID: Not reported
Enter Date: 6/21/1990
Funding: Not reported
Staff Initials: UST
How Discovered: Tank Closure
How Stopped: Not reported
Inform: No
Leak Cause: Corrosion
Leak Source: Tank
MTBE Date: Not reported
Max MTBE GW: Not reported
MTBE Tasted: Not Required to be Tasted.
Priority: 0
Local Case #: Not reported
Beneficial: WNL
GW Qualifier: Not reported
Max MTBE Soil: Not reported
Soil Qualifier: Not reported
Hydr Basin #: 8.50
Operator: Not reported
Oversight Firm: RB Lead Underground Storage Tank
Oversight Firm: UST
Review Date: 2/24/1994
Stop Date: Not reported
Work Suspended: Not reported
Responsible Party: Not reported
RP Address: Not reported
Global ID: T0805300363
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mile Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch. Assigned Name: Not reported
LUST Region 3:
Case Number: 815
Cross Street: REEDSIDE
Responsible Party: Not reported
Local Agency: 03
Discover Date: 01/01/1985
How Found: Tank Closure
Source: Tank
Cause: Corrosion
Local Agency: Local Agency
Case Type: Other ground water affected
Contact: Not reported
Facility Status: Remediation Plan
Facility County: Monterey
Review Date: 2/24/94
Confirm Leak: Not reported
Prelim Assess: Not reported
Release Date: 05/30/1990
Enter Date: 6/21/90
Regional Board: Central Coast Region
Stop Date: Not reported
How Stopped: Not reported
Staff Initials: WNL
Funding: Not reported
Workplan: Not reported
Pollution Char: Not reported

Map ID
Direction
Distance (ft)
Elevation
Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

U.S. COAST GUARD (Continued)

Remedial Action: / /
Close Date: / /
Region: 3

Remedial Plan: 11/01/1993
Monitoring: Not reported
Eutrophication Type: Not reported
Eutrophication Date: / /
Intrusion Action: 0
Miss Concentration: 0
Miss Fuel: 0
Oil Name: Not reported
Max MTBE Ground Water: Not reported
Max MTBE Soil: Not reported
MTBE Data: / /
MTBE Tested: N/A
Lat/Long: 36.805528 / -121.8867821
Soil Qualifier: Not reported
Groundwater Qualifier: Not reported
Summary: 1000 GAL DIESEL TANK FOUND TO BE LEAKING UPON REMOVAL. 80 GAL OF DIESEL
+WATER WERE PUMPED FROM EXCAVATION. FURTHER SAMPLES ARE REQUIRED TO
DETERMINE VERTICAL AND HORIZONTAL EXTENT OF CONTAMINATION.

CORTESE
Reg id: 815
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

63
NW
1/2-1
3167 ft.
Higher

32 CANNERY ROW
UNINCORPORATED COUNTY AREA, CA 0

CHMRS
5105671428
N/A

CHMRS:
OES Control Number: 01-5808
DOT Hazard Class: Not Reported
Chemical Name: Diesel
Extent of Release: Not reported
CAS Number: Not reported
Environmental Contamination: None Reported
Incident Date: Not reported
Time Completed: Not reported
Physical State Stored: Not reported
Release Unit: Not reported
Container Description: Not reported
Container Type: Not reported
Level Of Container: Not reported
Container Material: Not reported
Container Capacity: Not reported
Extent Of Release (code): Not reported
Agency id Number: Not reported
OES Incident Number: Not reported
Time Notified: 01-5808
Surrounding Area: Not reported
Estimated Temperature: Not reported
Property Management: Not reported
More Than Two Substances Involved?: Not reported

Map ID
Direction
Distance (ft)
Elevation
Site

MAP FINDINGS

EDR ID Number
EPA ID Number
Database(s)

(Continued)

Special Studies 1: Not reported
Special Studies 2: Not reported
Special Studies 3: Not reported
Special Studies 4: Not reported
Special Studies 5: Not reported
Special Studies 6: Not reported
Responding Agency Personnel # Of Injuries: 0
Responding Agency Personnel # Of Fatalities: 0
Resp Agency Personnel # Of Decontaminated: Not reported
Others Number Of Injuries: Not reported
Others Number Of Fatalities: Not reported
Vehicle Make/year: Not reported
Vehicle License Number: Not reported
Vehicle State: Not reported
Vehicle id Number: Not reported
CADO/PUC/ICC Number: Not reported
Company Name: Not reported
Reporting Officer Name/ID: Not reported
Report Date: Not reported
Comments: Not reported
Facility Telephone Number: Not reported
Waterway Involved: Yes
Waterway: Monterey Harbor
Spill Site: Ship/Harbor/Port
Cleaning By: Unknown
Containment: Yes
What Happened: Per the NRC report, material was released when filling a vessel and the link broke.
Date/Time: 10/13/01 1500
Type: PETROLEUM
Other: Not reported
Chemical 1: Not Reported
Chemical 2: Not Reported
Chemical 3: Not Reported

70
East
1/2-1
3225 ft.
Higher

Z & S AUTO SALES
1179 DEL MONTE AVE
MONTEREY, CA 93940

LUST
5102441464
Corteese
N/A

State LUST:
Cross Street: PARK
Qty Leaked: Not reported
Case Number: 2778
Reg Board: Central Coast Region
Chemical: Gasoline
Lead Agency: Regional Board
Local Agency: 27000
Case Type: Other ground water affected
Status: Case Closed
County: Monterey
Abate Method: Unknown - action taken at site is unknown
Review Date: Not reported
Workplan: Not reported
Confirm Leak: Not reported
Prelim Assess: Not reported